## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/OFS/as/Banquet/2014/MDZ/789 Dated: 25/06/14

## FIRE SAFETY CERTIFICATE

Certified that the Tru Hallmark Banquets Hall running at ground, first & second Metro Station, Karkardooma Area Commercial Delhi,owned/occupied by M/s Tru Hallmark Banquets Pvt.Ltd , comprised of basement, ground plus three upper floors was granted fire safety certificate vide letter no. F.6/DFS/MS/2011/3537 dated 15.12.11. The Banquets hall building was inspected by the officer concerned of this department on 23.05.2014 in the presence of Sh.Vinod Arora, and found that the banquets hall building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group D "Assembly Building" with effect from . 25.7.0.6./.1.7.... for a period of three years, subject to conditions printed overleaf.

Issued on ...25 / 06 / 1.9 ..... at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Ph.011-23414000

To,
M/s Tru Hallmark Banquets Pvt.Ltd
Commercial Area Karkardooma Metro Station,
Pkg. –A, Delhi,

## CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety

measures, management shall be responsible.

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.

5. This Fire Safety certificate can not be treated in any case for regularizations

of unauthorized if any.

6. All comments/ directions of the Licensing Department shall always be

permitted and followed.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building: Tru Hallmark Banquets at GF,FF & Second floor commercial Area Karkardooma Metro Station,

Pkg. -A, Delhi.

2. Building is comprised of

: Basement , ground + 2, upper floors.

3. Type of Occupancy

: Assembly

4. Type of Case

: Renewal

5. Details of Previous FSC

: No.F.6/DFS/MS/2011/3537 Dated 15/12/11 in the

name of Red Carpet

6. Fire Safety direction letter No : F.6/DFS/MS/2011/2390 Dated 30.09.11

Date of Inspection

23.05.2014

8. Name of the Inspecting officers: DO Virendra Singh & ADO Suresh Singh

9. Name and designation of Officer:

from the building side

: Shri Vinod Arora

10. Year of Construction

: 2011

11. Applicant's letter No

letter dated 12.05.2014

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	NBC Requirement	Provided at Site	Remarks MR/NMR		
1	Access to building					
1	Road width	6 Mtrs	8 Mtrs.	MR		
	Gate width	4.5 Mtrs.	4.5Mtrs.	MR		
	Width of internal road	6 Mtrs.	6 Mtrs.	MR		
2	Number, Width, Type and Arrange	ment of Exits	* a" * * * * * * * * * * * * * * * * * *			
	a. Number of Staircases	9	. i.e.a			
	Upper Floor	02 Nos	04 Nos.	MR		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases			la di santa		
	Upper Floor	1.5 M	3 no. of 1.5 M & 1no. of 2 M	MR		
	Basement	N/A	N/A	N/A		
	c. Protection of exits		2	-		
	Fire check door	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to	N/A	N/A	N/A		
	terrace g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	2.0 Mtrs	2.0 Mtrs	MR		
3	Compartmentation.		5			
	Fire check door	Required	Provided	MR		
F	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Sealed	MR		
	<ul> <li>Fire rating of shaft door</li> </ul>	2 hrs.	2 hrs.	MR		
	Water curtain	N/A	N/A	N/A		
-	Fire Dampers	Required	Provided	MR		
4	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	12 a/c per	do	MR		
	opportion.	hour				

6	First-aid-Hose Reels.						
	Total numbers of ground floor	3 nos.	3 nos.	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	30 m	MR			
	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic fire detection and alarming system.						
-	Type of detectors	Heat & smoke	Provided	MR			
	<ul> <li>Location of main panel</li> </ul>	Ground floor	Provided	MR			
	<ul> <li>Location of repeater panel</li> </ul>	Required	Provided	MR			
	Alternate source of power	Battery & DG Set	Provided	MR			
	Hooter's location	Staircases & hall.	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public address System.	Required	provided	MR			
10	Automatic Sprinkler System.	Required	Provided	MR			
	Basement	N/A	N/A	N/A			
	<ul> <li>upper floor</li> </ul>	Required	Provided	MR			
11	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants	400	100				
	size of riser/down-comer	100 mm	100 mm	MR			
	<ul> <li>Number of hydrants per floor</li> </ul>	3 Nos.	3 Nos.	MR			
	Hose Box	3 Nos.	3 Nos.	MR			
12	Yard Hydrants.						
	<ul> <li>Total number of hydrants</li> </ul>	Two	Three	MR			
	Hose Box	Two	Three	MR			
13	Pumping Arrangements.			(Under DMRC-Control)			
	Ground Level	2850LPM	Provided	MR			
	Discharge of main Pump	2850 LPM	Provided	MR			
	➤ Head of Main Pump	70 Mtrs.	80 mtrs	MR			
	Number of main pumps	Two	2 No.	MR			
	Jockey pump out put	one 180 LPM	One 180 LPM	MR			
	Jockey pump head	70 Mtrs.	80 mtrs.	MR			
	Standby pump out put	2850 LPM	2850 LPM	MR			
	Standby pump Head	70Mtrs	80 Mtrs.	MR			
	<ul><li>Auto Starting /Manual stopping</li></ul>	Auto	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace Level	N/A	N/A	N/A			
	Discharge of pump	N/A	N/A	N/A			
	> Head of the Pump	N/A	N/A	N/A			
	> Power supply	N/A	N/A	N/A			
	Auto Starting of pump	N/A	N/A	N/A			
4	Captive Water Storage for Fire Fighting.			(Under DMRC-			
	Underground tank capacity	1,00,000 Ltrs.	2,00,000 Ltrs.	Control) MR			
	Draw-off connection	Required					

		Required	Provided	MR .
15	Exit Signage.	rtequired		
16	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft  The standard lift lebby	N/A	N/A	N/A
	<ul><li>Pressurization of Lift lobby</li><li>Communication in lift car</li></ul>	Required	Provided	MR
	<ul> <li>Firemen's grounding</li> </ul>	Required	Provided	MR
	switch	Required	Provided	MR
	Lift Signage	Required	125 KVA	MR
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
19	Location     Fire Control Room	N/A	Provided for Metro Station	M/R
	<ul> <li>Detector system panel</li> </ul>	N/A	Provided	MR
	Elitab nanol	N/A	N/A	MR
	PA system panel	N/A	N/A	MR
	Battery backup	N/A	N/A	MR
	Building Floor Plans	N/A	N/A	-N/A-
20	Special Fire Protection systems for protection of special Risks, if any:	Required for HT/LT panels	Provided	MR

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

This department has issued earlier single FSC vide letter no. No.F.6/DFS/MS/2011/3537 Dated 15/12/11 for Red Carpet & Orchidgrand Hospitality (P) Ltd. Which are in commercial area of DMRC. Now the name is changed from Red Carpet to Tru Hallmark Banquets Pvt.Ltd.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The fire safety certificate issued vide letter no. F.6/DFS/MS/2011/3537 Dated 15/12/11renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Stall 6.6.14

Signature of the Inspecting Officer Name:-Suresh Singh

Designation: - ADO (Shah)

Signature of the Inspecting Officer

Name:-Virendra Singh Designation: - DO (ED)

