GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: cfohq.dlfire@nic.in

No F 6/DFS/MS/2014/Hotel/HD2/831

Dated 08/07/14

FIRE SAFETY CERTIFICATE

Certified that **The Park Hotel** located at **15, Parliament Street, New Delhi** comprises of Lower Basement, Upper Basement, Ground + 10 upper was granted NOC by this department vide letter No.F6/DFS/MS/2011/Hotel/1820 dated 03-08-2011. The premises was re-inspected by the officers concerned of this department on 14-06-2014 in the presence of Sh. Jasbir Singh (Sr. Fire Officer) and found that the said hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Sub-Division A-6 Hotels of Group A Residential Building including Agni Discotheque** at ground floor with effect from -2014 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi 110049 w.r.t. letter No 23205/Addl. CP./Lic. (Amst.) dated New Delhi 18-06-2014.
- 2. The Park Hotel located at 15, Parliament Street, New Delhi.
- 3. Sh. P.K. Sharma Medical Officer of Health NDMC, Palika Kendra, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : The Park Hotel, at 15, Parliament Street, New Delhi.

2. Type of Occupancy : Sub Division A-6 (Hotels) of Group 'A' Residential building

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/2011/Hotel/1820 dated 03/08/2011

5. Fire Safety directives Letter No. : NA

6 Date of inspection : 14/06/2014

7 Name of the Inspecting Officer : Sh. Gurmukh Singh (DO/CD) & Sh. M. K. Sharma (ADO/CC)

8 Name and designation of Officer

from the building side : Sh. Jasbir Singh (Sr. Fire Officer)

9 Year of Construction : 1985

10. Applicant's letter No. : 23204/Joint. CP/Lic.(Amst.), dated New Delhi the 18/06/2014.

Old Case S No Minimum standards on fire prevention Existing Provided at site Remarks and fire safety U/R 33 Requirements MR/NMR 1. Access of building Road width 9 Mtr. 9 Mtr. MR Gate width 6 Mtr. 6 Mtr. MR Width of internal road 6 Mtr. 6 Mtr. MR Number, width, Type & Arrangements of exits 2. a. Number of staircases • Upper floors 2 Nos. 2 Nos. MR Basements 2 Nos. 2 Nos. MR b. Width of staircases Upper floors 1.25 Mtr. each 1.25 Mtr. each MR Basements 1.25 Mtr. each 1.25 Mtr. each MR c. Protection of exits Fire check door Required Provided MR Pressurization Required Provided MR d. No of continuous staircase to terrace 02 02 MR

L

Mon

	e. Width Of Corridor	1.0 Mtr.	1.50 Mtr.	MR	
**	f. Door Size	1.0 Mtr.	1.0 Mtr.	MR	
3.	Compartmentation			A	
	Fire check door	Required	Provided	MR	
	 Sealing of electrical shafts 	Required	Provided	MR	
	• Fire Rating of shaft door	Required	Provided	MR	
	Water Curtain	NA	NA	NA	
	• Fire Dampers	Required	Provided	MR	
4	Smoke managements System		-		
	Basements	30 ACPH	Mechanical	MR	
	Upper floors	12 ACPH	NATURAL	MR	
5	Fire Extinguishers				
	Total numbers	150 Nos.	154 Nos.	MR	
	• Types	ABC, CO ₂ , Wco ₂	ABC, CO ₂ , Wco ₂	MR	
	ISI marking	Required	Provided	MR	
6	First – Aid Hose Reels				
	Total numbers on each floor	02	02	MR	
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR	
	Nozzle diameter	05 MM	.05 MM	MR	
7	Automatic fire detection and alarming system				
	Type of detectors	Required	Provided	MR	
	 Location of Main Panel 	Lower Basement	Lower Basement	MR	
	 Location of Repeater Panel 	Ground Floor	Ground Floor	MR	
	 Alternate source of power 	Required	Battery Backup	MR	
	 Hooters' Location 	Floor wise	Floor wise	MR	
8	MOEFA	Required	Provided	MŔ	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler				
	 Basements 	Required	Provided	MR	
	 Upper Floor 	Required	Provided	MR	
	Sprinkler above false ceiling	Required	Provided	MR	
11	Internal Hydrants				

b

man

-N/8h-

	Size of riser/down- comer	150 MM	150 MM	MR	
	Number of hydrants per floor	02	02	MR	
	Hose Box	02	02	MR	
12	Yard Hydrants				
7 1 1 1 x	Total number of hydrants	06	06	MR	
	Hose Box	06	06	MR	
13	Pumping Arrangements				
	o Ground Level				
	Discharge of main pump	2280 LPM	2280 LPM	MR	
	Head of main pump	90 Mtr.	90 Mtr.	MR	
	Number of main pumps	01	01	MR	
	Jockey pump out put	380 LPM	380 LPM	MR	
	Jockey pump head	90 Mtr.	90 Mtr.	MR	
	Standby Pump out put	2280 LPM	2280 LPM	MR	
	Standby Pump Head	90 Mtr.	90 Mtr.	MR	
	auto Staring/Manual stopping	Required	Provided	MR	
	Pump House Access	Required	Provided	MR	
	o Terrace level				
	Discharge of pump	450 LPM	450 LPM	MR	
	Head of the pump	90 Mtr.	90 Mtr.	MR	
	Power supply	Required	Provided	MR	
	Auto starting of pump	Required	Provided	MR	
14	Captive water Storage for fire fighting	1 289	M. Marian Maria		
	Under ground tank capacity	2,00,000 Ltr.	2,00,000 Ltr.	MR	
	Draw of connection	Required	Provided	MR	
	• Fire service inlet	Required	Provided	MR	
•	 Access to tank 	Required	Provided	MR	
	Overhead Tank capacity	50,000 Ltr.	50,000 Ltr.	MR	
15	Exit Signage	Required	Provided	MR	
16	Provision of Lifts				
	Pressurization of Lift Shaft	Required	Provided	MR	

A

- M/85-

	 Pressurization of lift lobby 	Required	Provided	MR	
	Communication in lift Car	Required	Provided	MR	
	Fireman's Grounding Switch	Required	Provided	MR	
	Lift Signage	Required	Provided	MR	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area				
	Total area	NA	NA	NA	
	• Location	NA	NA	NA	
19	Fire control room				
	Detector system panel	Required	Provided	MR	
	Flow Switch Panel	Required	Provided	MR	
	PA System Panel	Required	Provided	MR	
	Batter backup	Required	Provided	MR	
	Building Floor Plans	Required	Provided	MR	
0	Special Fire Protection Systems for	Required	Co ₂ flooding	MR	
	Protection of special Risks, if any;		system in LT/HT		
			Panel		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2011/Hotel/1820 dated 03/08/2011 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended please.

Name :- Sh. Gurmukh Singh Designation :-DO(CD)

Name:- Sh. M. K. Sharma Designation :- A. D.O. (CC)