GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: cfohq.dlfire@nic.in

No F 6/DFS/MS/GH/2014/MD2/863 Dated 14/07/19

FIRE SAFETY CERTIFICATE

Certified that the Metro Plaza Guest House located at 2691-95, Chuna Mandi, Rajguru Road, Pahar Ganj, New Delhi comprises of Ground floor (reception), 1st floor to 3rd floor (05 guest rooms at each floor) with total 15 guest rooms was granted NOC by this department vide letter No.F6/DFS/MS/GH/2012/3664 dated 05-10-2012. The premises was re-inspected by the officer concerned of this department on 20-06-2014 in the presence of Mr. Vinay Misra (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub-Division A-1 lodging or rooming houses for 15 guest rooms with effect from -19107-1---2014 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 20 10.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service Ph - 011-23414333 of cma

Copy to:-

1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi -110049 w.r.t. letter No 16446-50/Addl. C.P./Lic. (H) dated New Delhi 11-04-2014.

2. Mr. Vinay Mishra (Manager) Metro Plaza Guest House located at 2691-95, Chuna Mandi, Rajguru Road, Pahar Ganj, New Delhi. Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Metro Plaza Guest House at 2691-95, Chuna Mandi, Rajguru

Road, Pahar Ganj, New Delhi.

2. Type of Occupancy : Residential (guest house) Gr.+3 floor total guest rooms-15

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/2012/3664 dated 05/10/2012

5. Fire Safety directives Letter No. : NA

6 Date of inspection : 20/06/2014

7 Name of the Inspecting Officer : M. K. Sharma (Assistant Divisional Officer)

8 Name and designation of Officer

from the building side : Mr. Viney Mishra (Manager)

9 Year of Construction : 2000

10. Applicant's letter No. : 16446-50/Addl. C.P./Lic.(H) dated New Delhi the 11/04/14.

S No	Minimum standards on fire prevention	Existing	Provided at site	Remarks	
	and fire safety U/R 33	Requirements		MR/NMR	
1.	Access of building				
	Road width	NA	6 Mtr.	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	• Upper floors	1 No	1 No	MR	
	Basements	NA	NA	NA	
	b. Width of staircases				
	Upper floors	1.25 Mtr.	1.50 Mtr.	MR	
	Basements	NA	NA	NA	
	c. Protection of exits		3		
	Fire check door	NA	NA	NA	

Meh

NIT

	Pressurization	NA	NA	NA	
	d. No of continuous staircase to terrace	1 No.	1 No.	MR	
	e. Width Of Corridor	1.0 Mtr.	1.30 Mtr.	MR	
	f. Door Size	1.0 Mtr.	1.0 Mtr.	MR	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	 Fire Rating of shaft door 	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	• Fire Dampers	NA	NA	NA	
4	Smoke managements System				
	Basements	NA	NA	NA	
	• Upper floors	12 ACPH	NATURAL	MR	
5	Fire Extinguishers				
	Total numbers	10 Nos.	10 Nos.	MR	
	 Types 	ABC, CO ₂ , Wco ₂	ABC, CO ₂ , Wco ₂	MR	
	 IS marking 	Required	Provided	MR	
6	First – Aid Hose Reels				
	Total numbers on each floor	01	01	MR	
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR	
	Nozzle diameter	05 MM	05 MM	MR	
7	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	 Location of Main Panel 	NA	NA	NA	
	 Location of Repeater Panel 	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	Required	Provided	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler				
	Basements	NA	NA	NA	

war

Upper Floor	NA	NA	NA
Sprinkler above false ceiling	NA	NA	NA
Internal Hydrants			1471
Size of riser/down- comer	NA	NA	NA
Number of hydrants per floor	NA	NA	NA
Hose Box	NA	NA	NA
2 Yard Hydrants			IVA
Total number of hydrants	NA	NA	NA
Hose Box	NA	NA ·	NA
Pumping Arrangements		1471	INA
Ground Level			
Discharge of main pump	NA	NA	NIA
Head of main pump	NA	NA	NA
Number of main pumps	NA	NA NA	NA
Jockey pump out put	NA	NA	NA
Jockey pump head	NA	NA NA	NA
Standby Pump out put	NA	NA	NA
Standby Pump Head	NA	NA	NA
auto Staring/Manual stopping	NA	NA NA	NA
Pump House Access	NA	NA NA	NA
Terrace level	NA	11.10	NA
Discharge of pump	450 LPM	NA 150 L DM	NA
Head of the pump	40 Mtr.	450 LPM	MR
Power supply	Required	40 Mtr.	MR
	Required	Provided	MR
Auto starting of pump	Required	Provided	MR
Captive water Storage for fire fighting	NA	NA	NIA
Under ground tank capacity	NA	NA NA	NA
Draw of connection	NA	NA .	NA
Fire service inlet	NA		NA
Access to tank	Required	NA	NA
Overhead Tank capacity	5000 Ltr.	Provided	MR
Tank capacity	3000 Ett.	5000 Ltr.	MR

hon

15	Exit Signage	Required	Provided	MR
16	Provision of Lifts	one lift ground to third floor		3
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of lift lobby	NA	NA	NA
	Communication in lift Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
	Total area	NA	NA	NA
	• Location	NA	NA	NA
19	Fire control room			
	Detector system panel	NA	NA	NA .
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Batter backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for	Required	ABC	MR
	Protection of special Risks, if any;			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/GH/2012/3664 dated 05/10/2012 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended please.

Signature of the Inspecting Officer

Name :- M.K. Sharma

Designation :- A. D.O. (CC)

Doled bolomy