GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: cfohq.dlfire@nic.in

No. F6/DFS/MS/GH/2014/ MOZ/918

Dated 24/07/19

FIRE SAFETY CERTIFICATE

Certified that the **Grand Godwin Guest House** located at **8502/41**, **Arakashan Road**, Pahar **Ganj**, **New Delhi** comprises of Ground floor (03 guest rooms + reception + 01 office) and 1st floor (09 guest rooms at each floor) with total 39 guest rooms was granted NOC by this department vide letter No.F6/DFS/MS/GH/2011/1641 dated 18-07-2011. The premises was re-inspected by the officer concerned of this department on 14-07-2014 in the presence of Mr. Vinod Sarean (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Residential**, **Sub-Division A-1 lodging or rooming houses** for 39 guest rooms with effect from -2-4/-27/--2014 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 2. 4. / at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

Copy to:-

- 1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi 110049 w.r.t. letter No 22906/Joint. C.P./Lic. (H) dated New Delhi 25-06-2014.
- 2. Mr. Vinod Sarean (Manager) Grand Godwin Guest House located at 8502/41, Arakashan Road, Pahar Ganj, New Delhi.
- 3. The Commissioner, North Delhi Municipal Corporation with the request to get the height of the building verified under intimation to this department.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry"

INSPECTION REPORT

1. Name & address of the building : Grand Godwin Guest House located at 8502/41, Arakashan Road,

Pahar Ganj, New Delhi.

2. Type of Occupancy : Residential (Guest house) G + 4 floors total guest rooms-39

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/2011/1641 dated 18/07/2011

5. Fire Safety directives Letter No. : NA

6 Date of inspection : 14/07/2014

7 Name of the Inspecting Officer : Sh. M. K. Sharma (ADO/CC)

8 Name and designation of Officer

from the building side : Mr. Vinod Sarean (Manager)

9 Year of Construction : 1983

10. Applicant's letter No. : 22906/Joint.C.P./Lic. (H) dated New Delhi the 25/06/2014.

Old Ca

-		Old Case			
S No	Minimum standards on fire prevention	Existing	Provided at site	Remarks	
	and fire safety U/R 33	Requirements	(PSS)	MR/NMR	
1.	Access of building	ALIE TO			
	Road width	NA	9 Mtr.	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	Upper floors	1 No.	1 No.	MR	
	Basements	NA	NA	NA	
	b.Width of staircases				
	• Upper floors	0.80 Mtr.	1.30 Mtr.	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	NA	NA	NA	

	Pressurization	NA	NA	NA	
	d. No of continuous staircase to terrace	1 No.	1 No.	MR	
	e. Width Of Corridor	1.0 Mtr.	1.0 Mtr.	MR	
	f. Door Size	1.0 Mtr.	1.0 Mtr.	MR	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
1	• Fire Dampers	NA	NA	NA	
4	Smoke managements System				
	• Basements	NA	NA	NA	
	• Upper floors	12 ACPH	NATURAL	MR	
5	Fire Extinguishers				
	Total numbers	20 Nos.	22 Nos.	MR	
	• Types	ABC, CO ₂ , Wco ₂	ABC, CO ₂ , Wco ₂	MR	
	IS marking	Required	Provided	MR	
5	First – Aid Hose Reels				
	Total numbers on each floor	01	01	MR	
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR	
	Nozzle diameter	05 MM	05 MM	MR	
7	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	• Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	Required	Provided	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler				
				NIA	
	Basements	NA	NA	NA	

	Sprinkler above false ceiling	NA	NA	NA
I	nternal Hydrants			
	Size of riser/down- comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA	NA
2	Yard Hydrants			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
3 1	Pumping Arrangements			
	o Ground Level			
	Discharge of main pump	NA	NA	NA
	Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	 Jockey pump out put 	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	auto Staring/Manual stopping	NA	NA	NA
	Pump House Access	NA	NA	NA
	Tump House AccessTerrace level	NA	NA	NA
	Discharge of pump	450 LPM	450 LPM	MR
		30 Mtr.	30 Mtr.	MR
		Required	Provided	MR
		Required	Provided	MR
	Auto starting of pump			
14	Captive water Storage for fire fighting	NA	NA	NA
. '	Under ground tank capacity	NA	NA	NA
	D. Ction	NA	NA	NA
	for its in let	NA	NA	NA
	for Edu	Required	Provided	MR
	Access to tank Overhead Tank capacity	5,000 ltr.	50,000 ltr.	MR
	Vollieda Tank Supaste		Required	MR

N/14

16	Provision of Lifts	NA	NA	NA
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of lift lobby	NA	NA	NA
	Communication in lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
,	Total area	NA	NA	NA
	• Location	NA	NA	NA
19	Fire control room			
	Detector system panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Batter backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for	Required	ABC,Co ₂	MR
	Protection of special Risks, if any;			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/GH/2011/1641 dated 18/07/2011 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended please.

Name:- Sh. M. K. Sharma

Designation: A D.O. (CC