## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2014/ SZ / 908

Dated: 22/07/19

## **FIRE SAFETY CERTIFICATE**

Certified that the **Hotel Prince International** located at 14A/24, Channa Market, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus three upper floors, using basement as storage, ground floor as reception & store, first, second & third floor each having 06 guest rooms respectively (Total 18 guest rooms) and a pantry with staff room on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2011/1743 dated 29.07.2011 owned/occupied by Sh. Pradeep Gulati. The guest house building was re- inspected by the officers concerned of this department on 17.07.2014 in the presence of Sh. Kamal Dahiya (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

## Copy to:-

- 1. The Joint Commissioner of Police (Lic.) 1<sup>st</sup> floor, P.S., Defence Colony, New Delhi. (Re. No. 22684/Joint C.P./Lic.(H), Dated 23.06.2014)
- 2. Sh. Pradeep Gulati (Owner), Hotel Prince International, 14A/24, Channa Mkt, Karol Bagh, New Delhi-110005.

## Basement, Ground Floor plus three cepper Floors.

		INION							
	1. Name & addross of the	INSPECT	ION REPORT	3					
	2. Type of Occupancy	e building :	totel Prince I	International, 1	4A124 Cham	a hal			
	3. Type of Case	Time to Read Day to							
	4. Details of Previous NC	New Case/Renewal							
	5. Fire Safety directives I	otton N	: Letter No. F.6/DF3/MS/GH/2011/1743 Date 29.07.20						
	6. Date of inspection	errer No :							
	7 Name = [11]		17.07.2014						
	8. Name and designation	10r & A.D.O F	o.s. Dahiyo						
	From the build and								
	9. Year of Construction	Sh. Kamal Dahiya (Manager)							
	10. Applicant's letter No.		1993-94 Toint C.P/LIC. (H) dated 23.06.2014						
	Minimum Standards on fire	. 0	22684 Joint (	P/LIC. (H) das	ted 23.06.	2014			
۱o.	prevention and fire safety t		MRC/BBC	Provided at	Remarks	1			
	Access to building	J/ H 33	Requirement	site	MR/NMR				
-	Road width		000			÷			
	Gate width		Accessible	07 mtr	MR				
	The second secon	·	•	180 cms	MR	į			
	• Width of internal roa	ad ,		- u					
•	Number, Width, Type & Arr	angement o	of Exits			<u>:</u>			
	a. Number of staircases	•							
	• Upper Floors		•	One	MO Qui	M11			
	Basements	Ĭ	-	-da-	MR, Being - do -	Ola			
	b. Width of staircases	1			- 000 -				
	Upper Floor		•	125 cms	MO Rai	A1.1.			
	• Basements		-	128 cms	MR, Being	Ola C			
	c. Protection of exits			TWOCHIS	- 00 -	- }			
	<ul> <li>Fire check door</li> </ul>		-		,				
	pressurization								
	d. No. of continuous stairce	ses to			And the second s	7.			
	terrace			One	MANUAL KANA MENUNUMBANAN MENUNUMBAN AND SERVE MANUAL MANUAL SERVE SERVENCES				
	e. Width of Corridor				-				
2	f. Door Size			240 cms, 205 cms					
-	Compatition	8		7.8 cms x 200 cms	-	1			
*******	Compartmentation								
	Fire check door		-						
	<ul> <li>Sealing of electrical s</li> </ul>	hafts		0 11					
	<ul> <li>Fire Rating of shaft d</li> </ul>	por		Sealed					
	Water Curtain								
	<ul> <li>Fire Dampers</li> </ul>	1			The same				
	Smoke Management System	1							
-	Basements			15-1	and the second s				
	• Upper floors		30 a/c per	exhaust fans	MR				
prosper and property to the segment	obber 110012		hour	are Provided latural Ventilation	7.75	. 1			



	N/26	# #6/5/20 # #6/5/20 # #6/5/20	· · · · · · · · · · · · · · · · · · ·	
The second secon	8.170	12 a/c per hour		
5.	Fire Extinguishers			All the second
	• Total numbers			
	• Types	Two at each floor	Provided	MR
	IS marking	ISI marked	-da-	MR
6.	First-Aid Hose Reels	DI Marked	1SI Marked	MR
	<ul> <li>Total numbers on each floor</li> </ul>	One	0	
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming	1	- de -	MR
	Type of detectors	, system		
1.	<ul> <li>Location of Main Panel</li> </ul>			+
	<ul> <li>Location of Repeater Panel</li> </ul>			
	Alternate source of power			
	Hooters' Location		D.G. Set of 25 KVA	
8.	MOEFA	0		
9.	Public Address System	Required	Provided	MR
10.	Automätic Sprinkler System - do -		-do-	MR
	• Basement	Roading	Parallal	
· Selection of the sele	Upper Floor	Required	Provided	MR
	<ul> <li>Sprinkler above false ceiling</li> </ul>	3	1	
11.	Internal Hydrants			
	Size of riser/down-comer			
	<ul> <li>Number of hydrants per floor</li> </ul>			
	<ul> <li>Hose Box</li> </ul>			<del></del>
12.	Yard Hydrants		J.	
	<ul> <li>Total number of hydrants</li> </ul>			
	★ Hose Box			1
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump			
-	Head of Main pump			
	Number of main pumps			
1	Jockey Pump out put			
	> Jockey pump head			
1	> Standby Pump out put			
	> Standby Pump Head		<u>i.</u>	
	> Auto Starting/Manual			
	stopping			-
		l .	1.	1

14A/24, Channa Market, WEA, N/g/. Karol Bagh, New Delli-110005.

	1,104,			1
	Pump House Access	_		
	<ul> <li>Terrace level</li> </ul>			*
	Discharge of pump		450 LPM	MR, Old Co
	Head of the pump	-	30 M	MR. Old Co
	Power Supply	Required	Provided	MR
	> Auto Starting of pump	,		
14.	Captive Water Storage for fire fighting		ii	. 1
	<ul> <li>Underground tank capacity</li> </ul>			, ,
	Draw-off connection		-	
	Fire service inlet		Provided	
	Access to tank			
	<ul> <li>Overhead Tank capacity</li> </ul>		5000 Ur	MR, Old Cas
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	8		4
	Pressurization of Lift Shaft		Consenter	
	<ul> <li>Pressurization of Lift lobby</li> </ul>			- 1
	Communication In lift Car		Provided	MR
	• * Fireman's Grounding Switch	0 . 1		
	Lift Signage	Kegleired	-do-	MR
	li di	- do -	-do-	MR
17.	Standby power supply	Required - do - Required	Provided	MR
			***	# 3
18.	Refuge Area.	-	# 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
	Total Area		- 1	
	> Location			
77				-
19.	Fire Control Room			·
	Detector System Panel      Section Report			
	• Flow Switch Panel			;
	PA System Panel		· · · · · · · · · · · · · · · · · · ·	
	Batter backup	Required	Provided	MR
	Building Floor Plans	/		12
20.	Special Fire Protection System for			
	Protection of special Risks, if any:	*		•
		v g		



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no.

 $f.6/\Delta FS/MS/GH/2011/1743$  dated 29.07.2011 renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name S.K. Tomar

Designation Divisional Officer

Name P.S. Dahiya
Designation Appt. Divisional Officer