GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

0

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2014/ 52/962

Dated: 3 0 / 07 /14

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Bharat Continental** located at R-548, Shanker Road, New Rajinder Nagar, New Delhi-110060 is comprised of Basement, ground floor plus three upper floors, using basement as storage/hall, ground floor as reception & 02 guest rooms, first, second & third floor each having 04 guest rooms respectively (Total 14 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2011-12/1926 dated 10.08.2011 owned/occupied by Sh. Sanjay Uppal. The guest house building was re- inspected by the officers concerned of this department on 18.07.2014 in the presence of Sh. A.P. Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic.)

 1st floor, P.S., Defence Colony, New Delhi.

 (Re. No. 24406/Joint C.P./Lic.(H), Dated 08.07.2014)
- 2. Sh. Sanjay Uppal (Owner), Hotel Bharat Continental, R-548, Shanker Road, New Rajinder Nagar, New Delhi-110060.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/7

INCDE	CTION		3			
1. Name & address of the building	CTION REPORT					
 Name & address of the building Type of Occupancy 	Hotel Bharat	Continental, R.	-548 Shanker Rd N			
3. Type of Case	MESTORCHITAL CTUEST HOUSE) KOLINGEN ALL A CO					
4. Details of Previous NOC	- Cosc/ Inches					
5. Fire Safety directives letter No	Letter No. F.6/BFS/MS/GH(2011-12)1926Date 16.08.2011					
6. Date of inspection						
7. Name of Inspecting Officer						
8. Name and designation of officer	8. Name and designation of officers					
From the building side						
9. Year of Construction	Sh. A. P. Singh (Manager) Before 2005					
10. Applicant's letter No.	: 24406 Joint C.P. LIC. (H) dated 08.07.2014					
Minimum Standards on fire	NBC BBL	Provided at	ated 08.07.2014			
lo. prevention and fire safety U/R 33	Requirement	site	Remarks			
. Access to building	- requirement	3116	MR/NMR			
Road width	Accessible	12 mtr	MR			
Gate width	_	215 cms	MR			
 Width of internal road 		w/3 C,	10/1			
. Number, Width, Type & Arrangemen	t of Evits					
a. Number of staircases	LAILS	T				
• Upper Floors						
• Basements		One	MR, Old Case			
b. Width of staircases	Two	Two	MR			
Upper Floor						
• Basements	-	125 cms	MR, Old Case			
c. Protection of exits		125cms, 175cms	-do -			
 Fire check door 			The second secon			
• pressurization						
d. Not of continuous staircases to						
terrace			The state of the s			
e. Width of Corridor		One	:			
f. Door Size		200 cms	_			
	_	78 cms x 212 cms	Committee and an experience of the second se			
Compartmentation		Cima	1 on contract the contract of			
Fire check door						
Sealing of electrical shafts						
Fire Rating of shaft door		Sealed				
Water Curtain						
• Fire Dampers						
The second of the second secon						
silond management system			The state of the s			
* Basements	30 a/c per	Exhaust Fond				
 Upper floors 	hour	are Provided	MR			
		Matural Ventilation	MR			

	N18-	3. \$ t	, a		
		12 a/c per			
The state of the s		hour	-		
5.	Fire Extinguishers				
	• Total numbers	Two at each floor			
	* Types	Co, ABC	Provided	MR	
	IS marking	ISI marked	-de-	MR	
6.	First-Aid Hose Reels	isi marked .	151 Marked	MR	
	 Total numbers on each floor 	NIR	0		
	 Length of hose reel hose 	30 m	Provided	MIR	
	Nozzle diameter	5 mm	-do-	MR	
7.	Automatic fire detection and alarming	system	- do	MR	
	Type of detectors	System		+	
1	 Location of Main Panel 			+	
	 Location of Repeater Panel 				
	Alternate source of power		09 1 (01/10)	1	
	Hooters' Location		02 D.G. Set of 80 KVA	+	
8.	MOEFA	NIIO			
9.	Public Address System	NIR	Provided	MR	
10.	Automätic Sprinkler System	- do -	- do -	MR	
	• Basement	Required	0 11		
1000	 Upper Floor 	Reguerred	Provided	MR	
	 Sprinkler above false ceiling 		1		
11.	Internal Hydrants				
	 Size of riser/down-comer 				
	 Number of hydrants per floor 			,	
	 Hose Box 				
12.	Yard Hydrants		J.		
	 Total number of hydrants 				
	 Hose Box 				
13.	Pumping Arrangements				
	 Ground Level 				
	Discharge of main Pump				
	Head of Main pump				
	Number of main pumps				
	> Jockey Pump out put				
	Jockey pump headStandby Pump out put			,	
	o canaby ramp out put				
	- Torrad Framp Fiedu				
	Auto Starting/Manual stopping			*	
	STODDING	-	_	4	

(V)

R-548, Shanker Road, New Rajinder Nagar, N/9. New Delhi-110060.

Pump House Access Terrace level Discharge of pump 450LPM 450 LPM MR > Head of the pump 30 M 30 M MR Power Supply Required Provided MR Auto Starting of pump 14. Captive Water Storage for fire fighting Underground tank capacity Draw-off connection -Fire service inlet Access to tank Overhead Tank capacity Sooo Ur 5000 Utr MR Required Provided MR 15. Exit Signage. 16. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Provided MR * Fireman's Grounding Switch Required - do -- do -MR Lift Signage - do -MR Required Provided MR 17. Standby power supply Refuge Area. 18. > Total Area Location 19. **Fire Control Room** Detector System Panel Flow Switch Panel PA System Panel Batter backup Provided MR **Building Floor Plans** 20. Special Fire Protection System for Protection of special Risks, if any:

(th

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F. 6/DFS/MS/GH/2011-12/1926 dated 10.08.2011 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name S.K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation ASSH. Divisional Officer.