GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2014/ 52/942

Dated: 30/07/14

FIRE SAFETY CERTIFICATE

Certified that M/s. "Pizza Express" restaurant at T-303 B, Third floor, Ambiance Mall, Vasant Kunj, New Delhi is running at third floor of a building comprised of three tier basements, ground plus three upper floors, owned/occupied by M/s Pizza Express (A unit of Atrium Rest India Pvt Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officers concerned of Delhi Fire Service on 16.07.2014 in the presence of Shri Manoj Kumar and that the building is fit for occupancy Class- D Assembly (restaurant) with effect from 30/07/19 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on 30/07/19 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

1. The Deputy Health Officer, MCD South Zone, Green Park, New Delhi.

2. The Owner, M/s. Pizza Express restaurant (A unit of Atrium Rest India Pvt Ltd.) T-303 B, Third floor, Ambiance Mall, Vasant Kuni, New Delhi

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s Pizza Express Restaurant, T-303 B, third floor,

Ambiance Mall, Vasant Kunj, New Delhi.

2. Type of Occupancy

: Assembly Building "D" Restaurant

3. Type of Case

: New

4. Details of previous NOC

: Nil

5. Fire Safety directives Letter No.:

Nil

6. Date of inspection

: 16.07.2014

7. Name of the Inspecting Officer: Dy. CFO Atul Garg & ADO M.K. Chattopadhyay

8. Name and designation of Officer

from the building side

: Mr. Manoj Kumar

9. Year of Construction

: N/A

10. Applicant's letter No.

: MCD Letter No DHO/SZ/2014/D/739 Dated 03.07.2014

(Restaurant running at third floor, T-303 B)

| S | Minimum standards on fire | NBC | Provided at site | Remarks |
|----|---|--------------|------------------|---------|
| No | prevention and fire safety U/R | Requirements | | MR/NMR |
| | 33 | | | |
| 1. | Access of building | | | X Z Z |
| | Road width | 9 Mtr. | Provided | MR |
| | Gate width | N/A | N/A | N/A |
| | Width of internal road | N/A | N/A | N/A |
| 2. | Number, width, Type & Arrangements of exits | | | |
| | a. Number of staircases | | | - |
| | Upper floors | 2 Nos | Provided | MR |
| | Basements | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | Upper floors | 1.5 Mtr | Provided | MR |
| | Basements | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | | | | |
| | • Fire check door | N/A | N/A | N/A |
| | Pressurization | N/A | N/A | N/A |
| | | | | |

| | d. No of continuous | N/A | N/A | N/A | |
|-----|---|-----------------------------|----------------------------|------|--|
| | staircase to terrace e. Width Of Corridor | N/A | NT/A | DT/A | |
| | e. Width Of Corridor f. Door Size | 2.00 mtr | N/A 2.00 & 1.22 Mtrs | N/A | |
| | 1. Door Size | 2.00 mtr | Provided Provided | MR | |
| 3. | Compartmentation | | Flovided | | |
| J. | Fire check door | N/A | N/A | N/A | |
| | | N/A | N/A | N/A | |
| | Sealing of electrical shafts | IVA | 17/74 | IVA | |
| | Fire Rating of shaft door | N/A | N/A | N/A | |
| | Water Curtain | N/A | N/A | N/A | |
| | Fire Dampers | N/A | N/A | N/A | |
| 4. | Smoke managements System | | | | |
| 1. | Basements | 30 a/c per hour | N/A | N/A | |
| | Upper floors | 12 a/c per hour | Provided | MR | |
| 5. | Fire Extinguishers | 12 are per flour | 1 TO VIGOU | 1711 | |
| J. | | | 07 Nos. | MR | |
| | • Total numbers | | | MR | |
| | • Types | ISI | ABC, Water CO ₂ | | |
| | • IS marking | | YES | MR | |
| 6. | First – Aid Hose Reels Provided & Maintain by Mall | | | | |
| | Total numbers on each floor | do | do | do | |
| | Length of hose reel hose | do | do | do | |
| | Nozzle diameter | do | do | do | |
| 7. | Automatic fire detection and alarming system :- Provided & Maintain by Mall | | | | |
| 72 | Type of detectors | do | do | do | |
| | Location of Main Panel | do | do | do | |
| | Location of Repeater Panel | do | do | do | |
| | Alternate source of power | do | do | do | |
| | Hooters' Location | do | do | do | |
| 8. | MOEFA | Provided & Maintain by Mall | | | |
| 9. | Public Address System | Provided & Maintain by Mall | | | |
| 10. | Automatic Sprinkler System :- Provided & Maintain by Mall | | | | |
| | Basements | do | do | do | |
| | Upper Floor | do | do | do | |
| | Sprinkler above false ceiling | do | do | do | |

| 11. | 11. Internal Hydrants :- Provided & Maintain by Mall | | | | | | |
|-----|--|--|--------------------|---------------|----|--|--|
| | • | Size of riser/down- | do | do | do | | |
| | | comer | | | | | |
| | • | Number of hydrants per | do | do | do | | |
| | | floor | do | do | do | | |
| | • | Hose Box | | | | | |
| 12. | Yard F | Yard Hydrants :- Provided & Maintain by Mall | | | | | |
| | • | Total number of hydrants | do | do | do | | |
| | • | Hose Box | do | do | do | | |
| 13. | Pumpi | ng Arrangements :- Provide | ed & Maintain by I | Mall | | | |
| | • | Discharge of main pump | do | do | do | | |
| | | Head of main pump | do | do | do | | |
| | | Number of main pumps | do | do | do | | |
| 3 | > | Jockey pump out put | do | do | do | | |
| | | Jockey pump head | do | do | do | | |
| | | Standby Pump out put | do | do | do | | |
| | | Standby Pump Head | do | do | do | | |
| | | Auto Staring/Manual | do | do | do | | |
| | | stopping | do | do | do | | |
| | | Pump House Access | do | do | do | | |
| | • | Terrace level | do | do | do | | |
| | > | Discharge of pump | do | do | do | | |
| | | Head of the pump | do | do | do | | |
| | | Power supply | do | do | do | | |
| | > | Auto starting of pump | | | | | |
| 14. | Captiv | e water Storage for fire figh | ting:- Provided & | | 1. | | |
| | • | Under ground tank capacity | do | do | do | | |
| | > | Draw of connection | do | do | do | | |
| | | Fire service inlet | do | do | do | | |
| | > | Access to tank | do | do | do | | |
| | • | Overhead Tank capacity | do | do | do | | |
| 15 | Exit S | ignage | Provided & Main | ntain by Mall | | | |
| 16. | | ion of Lifts :- Provided & | Maintain by Mall | | | | |
| | | Pressurization of Lift Shaft | do | do | do | | |
| | > | Pressurization of lift lobby | do | do | do | | |
| | > | Communication in lift | do | do | do | | |
| 8 | > | Fireman's Grounding Switch | do | do | do | | |
| | > | Lift Signage | do | do | do | | |
| | | | | Y. | | | |

| 17. | Standby power supply | Provided & Maintain by Mall | | |
|-----|-----------------------------------|--|-----|-----|
| 18. | Refuge Area | Provided & Maintain by Mall | | |
| | > Total area | do | do | do |
| | > Location | do | do | do |
| 19. | Fire control room :- Provided & I | | | |
| | Detector system panel | do | do | do |
| | > Flow Switch Panel | do | do | do |
| | PA System Panel | do | do | do |
| | Batter backup | do | do | do |
| | Building Floor Plans | do | do | do |
| 20. | Special Fire Protection Systems | N/A | N/A | N/A |
| | for Protection of special Risks, | Name of the last o | | |
| | if any; | | | |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

This department has already issued fire safety certificate vide letter No. F6/DFS/MS/2013/SZ/1140 Dated 30.10.2013 for Mall.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. The grant of Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for your approval and signature please

Signature of the Inspecting Officer

Signature of the Inspecting Officer