

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. FG/DFS/MS/EH/2014/W2/989

Dated: 07 / 08 / 2014

FIRE SAFETY CERTIFICATE

Certified that the M/S Bikanervala Foods Pvt. Ltd. at 103-105, 1st floor, Ring Road mall, Sctor-3, Rohini, Delhi-110085 was granted NOC by this department vide letter, no F6/DFS/MS/EH/2010/3119 dated 10/11/2010 in premise comprised of Basement, Ground + 8 upper floors. The premises was re-inspected by the officers concerned of this department on 03/ 07/ 2014 in the presence of Mr. Krishna (Outlet Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for Assembly (D-5) occupancy with effect from 07 / 08 / 2014 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of Delhi Fire Service Rules, 2010.

1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able by guests in an event of emergency.
2. All employees shall be acquainted with the use and maintenance of all the fire fighting installation/equipments.
3. The fire suppression / protection arrangements provided in the restaurant are to minimize losses, if maintained in good working condition. These systems cannot give any guarantee that there will be no fire or losses in the event of one.
4. Any loss of life and property due to non-functional of fire safety arrangements and other installations shall be the responsibility of the licensee.
5. This report may not in any way be treated as regularization of unauthorized construction, if any.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 07-08-2014 at New Delhi by


(SANTOKH SINGH)
Chief Fire Officer
Ph: 011-23414250

Copy to:

1. The Dy Health Officer, North Delhi Municipal Corporation, Health Department, Rohini Zone, Sector-V, Rohini, Delhi-110085 for information.
2. The Authority Signatory M/S Bikanervala Foods Pvt. Ltd. at 103-105, 1st floor, Ring Road mall, Sctor-3, Rohini, Delhi-110085

Copy to
7/8/14
9911504947

M-2

INSPECTION REPORT

1. Name & address of the building : M/S Bikanervala Foods Pvt. Ltd. at 103-105, 1st floor, Ring Road mall, Sctor-3, Rohini, Delhi-110085
2. Type of Occupancy : Assembly
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/EH/2010/3119 dated 10/11/2010
5. Fire Safety directives letter No : NBC Part-IV
6. Date of inspection : 03/07/2014
7. Name of the Inspecting Officers : DO (NW) & ADO (Rohini)
8. Name and designation of officers
from the building side : Mr.. Krishna (Outlet Manager)
9. Year of Construction : 2007
10. Applicant's letter No. : letter no nil dated 12/06/2014

| S. No | Minimum Standards on fire prevention and fire safety U/R 33 | BBL & NBC Requirement | Provided at site | Remarks MR/NMR |
|-------|---|-----------------------|--------------------|----------------|
| 1 | Access to building | | | |
| | • Road width | Accessible | Accessible | M.R. |
| | • Gate width | Accessible | Accessible | M.R. |
| | • Width of internal road | -- | -- | -- |
| 2 | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | | | |
| | • Upper Floors | 04 | Provided with mall | M.R. |
| | • Basements | -- | -- | -- |
| | b. Width of staircases | | | |
| | • Upper Floors | R | Provided with mall | M.R. |
| | • Basements | R | Provided with mall | M.R. |
| | c. Protection of exits | | | |
| | • Fire check door | R | Provided with mall | M.R. |
| | • Pressurization | R | Provided with mall | M.R. |
| | d. No. of continuous staircases to terrace | | | |
| | e. Width of Corridor | Old case | Old case | Old case |
| | f. Door Size | Old case | Old case | Old case |
| 3 | Compartmentation. | | | |
| | ➤ Fire check door | R | Provided with mall | M.R. |
| | ➤ Sealing of electrical shafts | R | Provided with mall | M.R. |
| | ➤ Fire Rating of shaft door | R | Provided with mall | M.R. |
| | ➤ Water Curtain | N.A | N.A | N.A |
| | ➤ Fire Dampers | N.A | N.A | N.A |

3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/EH/2010/3119 dated 10/11/2010
5. Fire Safety directives letter No : NBC Part-IV
6. Date of inspection : 03/07/2014
7. Name of the Inspecting Officers : DO (NW) & ADO (Rohini)
8. Name and designation of officers
from the building side : Mr.. Krishna (Outlet Manager)
9. Year of Construction : 2007
10. Applicant's letter No. : letter no nil dated 12/06/2014

| S. No | Minimum Standards on fire prevention and fire safety U/R 33 | BBL & NBC Requirement | Provided at site | Remarks MR/NMR |
|-------|---|--------------------------|--------------------|----------------|
| 1 | Access to building | | | |
| | • Road width | Accessible | Accessible | M.R. |
| | • Gate width | Accessible | Accessible | M.R. |
| | • Width of internal road | -- | -- | -- |
| 2 | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | | | |
| | • Upper Floors | 04 | Provided with mall | M.R. |
| | • Basements | -- | -- | -- |
| | b. Width of staircases | | | |
| | • Upper Floors | R | Provided with mall | M.R. |
| | • Basements | R | Provided with mall | M.R. |
| | c. Protection of exits | | | |
| | • Fire check door | R | Provided with mall | M.R. |
| | • Pressurization | R | Provided with mall | M.R. |
| | d. No. of continuous staircases to terrace | | | |
| | e. Width of Corridor | Old case | Old case | Old case |
| | f. Door Size | Old case | Old case | Old case |
| 3 | Compartmentation. | | | |
| | ➤ Fire check door | R | Provided with mall | M.R. |
| | ➤ Sealing of electrical shafts | R | Provided with mall | M.R. |
| | ➤ Fire Rating of shaft door | R | Provided with mall | M.R. |
| | ➤ Water Curtain | N.A | N.A | N.A |
| | ➤ Fire Dampers | N.A | N.A | N.A |
| 4 | Smoke Management System. | | | |
| | ➤ Basements | 30 a/c per hour | N/A | N/A |
| | ➤ Upper floors | 12 a/c per hour | N/A | N/A |
| 5 | Fire Extinguishers | | | |
| | ➤ Total numbers | One @ 300 m ² | P | M.R. |
| | ➤ Types | | ABC/ CO2 | M.R. |
| | ➤ IS marking | ISI marked | yes | M.R. |

M-3

| | | | | |
|----|---|---|---|---|
| 6 | First-Aid Hose Reels. | | | |
| | <ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter | R 30mm 5mm | Provided with mall Provided with mall Provided with mall | M.R. M.R. M.R. |
| 7 | Automatic fire detection and alarming system. | | | |
| | <ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location | R N/A N/A N/A N/A | Provided in restaurant N/A N/A N/A N/A | M.R. N/A N/A N/A N/A |
| 8 | MOEFA | R | Provided with mall | M.R. |
| 9 | Public Address System. | R | Provided with mall | M.R. |
| 10 | Automatic Sprinkler System. | | | |
| | <ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling | N/A R R | N/A Provided Provided | N/A M.R. M.R. |
| 11 | Internal Hydrants | | | |
| | <ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box | 100 mm 01 01 | Provided with mall Provided with mall Provided with mall | M.R. M.R. M.R. |
| 12 | Yard Hydrants. | | | |
| | <ul style="list-style-type: none"> Total number of hydrants Hose Box | N/A N/A | N/A N/A | N/A N/A |
| 13 | Pumping Arrangements. | | | |
| | <ul style="list-style-type: none"> Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping | 4500 LPM 70 M — 180 LPM 70 M 4500 LPM 70 M R | Provided with mall Provided with mall — Provided with mall Provided with mall Provided with mall Provided with mall Provided with mall | M.R. M.R. — M.R. M.R. M.R. M.R. M.R. |

| | | | | |
|----|------------------------------------|----------|--------------------|------|
| | ➤ Alternate source of power | N/A | N/A | N/A |
| | ➤ Hooters' Location | N/A | N/A | N/A |
| 8 | MOEFA | R | Provided with mall | M.R |
| 9 | Public Address System. | R | Provided with mall | M.R |
| 10 | Automatic Sprinkler System. | | | |
| | ➤ Basement | N/A | N/A | N/A |
| | ➤ Upper Floor | R | Provided | M.R |
| | ➤ Sprinkler above false ceiling | R | Provided | M.R |
| 11 | Internal Hydrants | | | |
| | ➤ Size of riser/down-comer | 100 mm | Provided with mall | M.R |
| | ➤ Number of hydrants per floor | 01 | Provided with mall | M.R |
| | ➤ Hose Box | 01 | Provided with mall | M.R |
| 12 | Yard Hydrants. | | | |
| | ➤ Total number of hydrants | N/A | N/A | N/A |
| | ➤ Hose Box | N/A | N/A | N/A |
| 13 | Pumping Arrangements. | | | |
| | • Ground Level | | | |
| | ➤ Discharge of main Pump | 4500 LPM | Provided with mall | M.R. |
| | ➤ Head of Main pump | 70 M | Provided with mall | M.R. |
| | ➤ Number of main pumps | — | — | — |
| | ➤ Jockey Pump out put | 180 LPM | Provided with mall | M.R. |
| | ➤ Jockey pump head | 70 M | Provided with mall | M.R. |
| | ➤ Standby Pump out put | 4500 LPM | Provided with mall | M.R. |
| | ➤ Standby Pump Head | 70 M | Provided with mall | M.R. |
| | ➤ Auto Starting/ Manual stopping | R | Provided with mall | M.R |
| | ➤ Pump House Access | R | Provided with mall | M.R |
| | • Terrace level | | | |
| | ➤ Discharge of pump | — | — | — |
| | ➤ Head of the pump | — | — | — |
| | ➤ Power Supply | — | — | — |
| | ➤ Auto Starting of pump | — | — | — |

| | | | | |
|----|--|--------------|---|-------|
| 14 | Captive Water Storage for fire fighting. | | | |
| | • Underground tank capacity | 2,20,000 ltr | Provided with mall | M.R ✓ |
| | ➤ Draw-off connection | R | Provided with mall | M.R ✓ |
| | ➤ Fire service inlet | R | Provided with mall | M.R ✓ |
| | ➤ Access to tank | R | Provided with mall | M.R ✓ |
| | • Overhead Tank capacity | 30,000 lts | Provided with mall | M.R ✓ |
| 15 | Exit Signage. | R | Provided in restaurant | M.R ✓ |
| 16 | Provision of Lifts. | | | |
| | • Pressurization of Lift Shaft | R | Provided with mall | M.R ✓ |
| | • Pressurization of Lift lobby | - | - | - |
| | • Communication In lift Car | R | Provided with mall | M.R ✓ |
| | • Fireman's Grounding Switch | R | Provided with mall | M.R ✓ |
| | • Lift Signage | R | Provided with mall | M.R ✓ |
| 17 | Standby power supply | R | Provided with mall | M.R ✓ |
| 18 | Refuge Area. | | | |
| | ➤ Total Area | N/A | N/A | N/A |
| | ➤ Location | N/A | N/A | N/A |
| 19 | Fire Control Room | | | |
| | • Detector System Panel | R | Provided with mall | M.R ✓ |
| | • Flow Switch Panel | R | Provided with mall | M.R ✓ |
| | • PA System Panel | R | Provided with mall | M.R ✓ |
| | • Batter backup | R | Provided with mall | M.R ✓ |
| | • Building Floor Plans | R | Provided with mall | M.R ✓ |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | ✓ | No special risk seen at the time of inspection. | ✓ |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules, the NOC issued vide letter no. F6/DFS/MS/EH/2010/3119 dated 10/11/2010 Renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

CFO/748
15/7/14

Signature of the Inspecting Officer

Name

Designation

DO-NTW

N.P. Sharma

N.P. Sharma

ADD 'R'


15/7/14

08-7-14

Signature of the Inspecting Officer

Name

Designation



The certificate to mall already issued by dept