GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

20

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2014/ 5 2 1864

Dated: 22/8/14

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Marble Arch** located at 8/6, WEA, Pusa Lane, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus two upper floors, using basement as hall, ground floor as reception, offices, pantry & 05 rooms (personal use), first & second floor each having 11 guest rooms respectively (Total 22 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2011/590 dated 05.04.2011 for 27 guest rooms owned/occupied by Sh. Arham Qureshi. The guest house building was re- inspected by the officers concerned of this department on 20.08.2014 in the presence of Sh. Deepak Sondhi (G.M) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential for 22 guest rooms w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 22/08/14 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph;- 011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No. 32240-43/Joint C.P./Lic.(H), Dated 07.08.2014)
- 2. Sh. Arham Qureshi (Owner), M/s Marble Arch, 8/6, WEA, Pusa Lane, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

100	INSPECT	ION REPORT			
	1. Name & address of the building:	Hotel Marble A	rch. 816 WEA	Pusa lone	to
1	1. Name & address of the building: 2. Type of Occupancy :	Residential (nuest House	, 1950 (971)	N.
	3. Type of Case	New Case/Renev	Val		
	4. Details of Previous NOC :		FS/MS/GH/2011/59	Date AT.A	4. 2
	5. Fire Safety directives letter No :	10/0	-	70 Date 03 70	1,2
	6. Date of inspection	.90	08.2014		
	7. Name of Inspecting Officer			2 Aalu	
	8. Name and designation of officers	Dio 3 Ki lam	ar & ADO F	· S. Baniya	
	From the building side :	Sh. Asaba	k Sondhi CG.1	2	
	9. Year of Construction :	2009-10	N SUNAINI CONT	4)	
			10011.4 (11)	dada 1 a z a	0 1
5.	Minimum Standards on fire	NBC/BBL	Provided at	A STREET, STRE	8.2
Vo.	prevention and fire safety U/R 33	/		Remarks	
1.	Access to building	Requirement	site	MR/NMR	
		Accessible	07 mtr	000	
	Road width	MICESSIBIE		MR	
	Gate width	***	180 cms	MR	į
	 Width of internal road 			_	
2.	Number, Width, Type & Arrangement	of Exits	10 10 10 10 10 10 10 10 10 10 10 10 10 1		1
	a. Number of staircases			25	
	• Upper Floors	Two	Two	MR	• ;
	 Basements 	- do -	-do-	MR	
	b. Width of staircases	0.0	- 00	1.77	
	Upper Floor		140 cm , 90 cm ,	NOR ALL	10-
	Basements		148cms, 90cms	MR, 0/d	1
	c. Protection of exits		148 cms, 160 cms	-do-	- 1
	Fire check door				
	• pressurization				
	d. Not of continuous staircases to		S = 20 1/2	7	
	terrace				
	e. Width of Corridor		Two		
	f. Door Size	-	275 cms, 145 cms	-	
	1. 0001 3126		80 cms × 220 cms		;
3.	Compartmentation		OD CINB A CONTROL		-
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 			-	
		-	Sealed		10
					42
4.	Smoke Management System				
		70 /	Exhaust Fans		
	BasementsUpper floors	30 a/c per	are Provided	MR	
		hour	Natural Ventilation		

	NIG.	- As -		
		12 a/c per		1
		hour		9
5.	Eiro Estino del			l .
J.	Fire Extinguishers			
	• Total numbers	four at each flo	or Provided	MR
	* Types	ABC, WCo2	-do-	MR
6.	IS marking	ISI marked	1SI Marked	MR
0.	First-Aid Hose Reels			
	 Total numbers on each floor 	One	Provided	MR
74	 Length of hose reel hose 	30 m	-do-	MR
1	Nozzle diameter	5 mm	- do :	MR
7.	Automatic fire detection and alarming	system		1 1
	 Type of detectors 			
	 Location of Main Panel 			+ 1
	 Location of Repeater Panel 	_	_	
	 Alternate source of power 	-	D.G. Set of 125 KVA	D-0
	 Hooters' Location 		2 07 301 7 7 7 A3 KVM	MR
8.	MOEFA	Required	Provided	MAR
9.	Public Address System	-do-	-do-	
10.	Automätic Sprinkler System		-00-	MR
	 Basement 	Required	Provided	MR
	 Upper Floor 	reguired	1 BOVIOLEA	
	 Sprinkler above false ceiling 	•	1	
11.	Internal Hydrants			
	Size of riser/down-comer			
	 Number of hydrants per floor 			
* A	• Hose Box			-
12.	Yard Hydrants			
	 Total number of hydrants 		J.	
1	 Hose Box 			
13.	Pumping Arrangements			
,	Ground Level			8 8 2
	Discharge of main Pump			1,27,31
	> Head of Main pump			
	Number of main pumps	7		
۰	Jockey Pump out put			;
	Jockey pump head	-		,-
	Standby Pump out put			
	Standby Pump Head		7	
*	Auto Starting/Manual		· · ·	
	stopping		i	
ļ		Ap-	!	

N

N17

8/6, WEA, Pusa Lane, Karol Beigh, New Delli-110005.

· V	Pump House Access		. —	-
8	Terrace level	=		
	Discharge of pump	900 LPM	450 LPM Each	MR CO2 PC
	Head of the pump	30 M	30 M Each	MR CO2 P
	Power Supply	Required	Provided	MR
	Auto Starting of pump			
14.	Captive Water Storage for fire fighting		, .	1
	 Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 			
		V -		
			Provided	MR
			70001616	
		10000 /4~	10000 Hr	MR
	()	Required	5.07	
15.	Exit Signage.	Kequired	Provided	MR
16.	Provision of Lifts.			â
10.				
				-
	Pressurization of Lift lobbyCommunication In lift Car			
			Provided	MR
	Fireman's Grounding SwitchLift Signage	Required	-do-	MR
		-do-	-do-	MR
17.	Standby power supply	Required -do- Required	Provided	MR
		Lever and the second se	<u> </u>	
18.	Refuge Area.			
	> Total Area > Location			
		,		· · · · · · · · · · · · · · · · · · ·
19.	Fire Control Room			
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 			<u> </u>
				1
		0	0 .11	D 0 0
		Required	Provided	MR
			•	
20.	Special Fire Protection System for			



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. $\frac{\text{F.6/\DeltaFS} MS/GH/2011}{S90}$ dated $\frac{\text{OS.04.2011}}{\text{conservation}}$ renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

Note: The OS rooms at Ground Floor are used for personal use. First & second floor each having 11 quest rooms respectively. The renewal of NOC is only for 22 quest rooms at first & second Floorand reception with pantry at Ground Flooras per letter No. 32240-43 | Joint C.P | LIC. CM) dated 07.08.2014.

Signature of Inspecting Officer

Name S.K. Tomar

Designation Divisional

Name P. S. Dahiya

Designation Appt. Divisional Officer.