## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. FOLDFS/MS/2014) NO2/1188

Dated: 1219114

## FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Middle School at Badarpur Khadar, Delhi -110094, comprising of ground plus first floor only owned/occupied by Sarvodaya Middle School have complied with the fire prevention and fire safety requirements in accordance with the circular No-F-16/Estate/CC/FireSafety/2011/3298to3398 dated-01/03/2011 issued by Director of Education and verified by the officer concerned of this department on 25/08/2014 in the presence of Mr. Sudhir, Teacher of the school and found that the school building is fit for occupancy class "B" 'Educational Building' with effect from ...(2.1.9...(1.5). for a period of three years, subject to conditions, printed overleaf.

Issued on 121 a 12 of 19 at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer Ph.011-23414333

le lu

To.

The Principal, Sarvodaya Middle School, Badarpur Khadar, Delhi -110094.

Copy:-

The Dy. Director of Education B–Block, Yamuna Vihar, Delhi-110053.

## CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this certificate, six months prior to its expiry

Name & address of the building : Sarvodaya Middle School,

Badarpur Khadar, Delhi-110094.

2. Building is comprised of Ground plus first floor (in two blocks)

B. Type of Occupancy : Educational

4. Type of Case : New

5. Details of Previous NOC letter : Nil

5. Fire Safety direction letter No : F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection : 25/08/2014

8. Name of the Inspecting officers : ADO Vijay Bahadur

9. Name and designation of Officer

from the building side : Mr. Sudhir (Teacher)

10. Year of Construction : 2014

11. Applicant's letter No : Letter No.-SV/BPK/2014/94, Dated- 15/07/2014

Sr. No.	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site Remark			
01	Access to building					
	Road width	06 mtr.	06 mtr.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
02	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor ,	01 nos.	01 nos. (in each block)	MR		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases					
	Upper Floor	1.50 mtr.	1.50 mtr.	MR		
	<ul> <li>Basement</li> </ul>	N/A	N/A	N/A		
	c. Protection of exits					
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	d. No. of continuous staircases to terrace	01 nos.	01 nos.	MR		
	e. Width of Corridor	1.50 mtr.	1.70 mtr.	MR		
	f. Door Size	01 mtr.	1.10 mtr.	MR		
03	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical</li> </ul>	N/A	N/A	N/A		
	shafts	N/A	N/A	N/A		
	<ul> <li>Fire rating of shaft door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Water curtain</li> </ul>	N/A	N/A	N/A		
	Fire Dampers					
04	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A		

.x. Travel distance requirement is meeting by one staircase in each black

	Tabel as makeure	10 nos.	20 nos.	MR				
	Total numbers	ABC /CO <sub>2</sub>	ABC /CO2	MR				
	• types	ISI marked	ISI marked	MR				
	IS marking	Official						
)6	First-aid-Hose Reels.							
	Total numbers on each floor	N/A	N/A	N/A				
	Length of hose reel hose	N/A	N/A	N/A				
	Nozzle diameter	N/A	N/A	N/A				
07	Automatic fire detection and alarming system.							
	Type of detectors	N/A	N/A	N/A				
	Location of main panel	N/A	N/A	N/A				
	Location of repeater panel	N/A	N/A	N/A				
	Alternate source of power	N/A	N/A	N/A				
	Hooter's location	N/A	N/A	N/A				
0.0		N/A	N/A	N/A				
80	MOEFA Public address System.	N/A	N/A	N/A				
09 10	Automatic Sprinkler System.	1 2/2 3	1	and the second second				
10	Autoriatio Ophinici Oystem.		4114	KIZA				
	Basement	N/A	N/A	N/A				
*****************	upper floor	N/A	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants							
		N/A	N/A	N/A				
	size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per floor							
	Hose Box	N/A	N/A	N/A				
12	Yard Hydrants.							
		N/A	N/A	N/A				
	Total number of hydrants	N/A	N/A	N/A				
40	Hose Box	1 W / 1	1					
13	Pumping Arrangements.							
	Ground Level	N/A	N/A	N/A				
	Discharge of main Pump	N/A	N/A	N/A				
	➤ Head of Main Pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	> Jockey pump out put	N/A	N/A	N/A				
	> Jockey pump head	N/A	N/A	N/A				
	> Standby pump out put	N/A	N/A	N/A				
	Standby pump Head	N/A	N/A	N/A				
	Auto Starting /Manual stopping	N/A	N/A	N/A				
	Pump House Access	N/A	N/A	N/A				
	Terrace Level	N/A	N/A	N/A				
	Discharge of pump	N/A	N/A	N/A				
	> Head of the Pump	N/A	N/A	N/A				
	➤ Power supply	N/A	N/A	N//				
	> Auto Starting of pump	N/A	N/A	N/				

14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A	
	Underground tank capacity	N/A	N/A	N/A	
	> Draw-off connection	N/A	N/A	N/A	
	➤ Fire service inlet	N/A	N/A	N/A	
	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
15	Exit Signage.	N/A	N/A	N/A	
16	Provision of Lifts.	au - Inner and the contract of	aankeen de vervelde en de verde en de verde en van de vervelde en verde en de vervelde en de en de en de en de	00000000000000000000000000000000000000	
************	Pressurization of Lift Shaft	N/A	N/A	N/A	
***************************************	Pressurization of Lift lobby	N/A	N/A	N/A	
***************************************	Communication in lift car	N/A	N/A	N/A	
	Firemen's grounding switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector system panel	N/A	N/A	N/A	
	Flow switch panel	N/A	N/A	N/A	
	PA system panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection systems for	N/A	N/A	N/A	
	protection of special Risks, if any:			-	

The fire protection systems provided in the building were tested/checked at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the circular no- F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11, rules it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer Name- Vijay Bahadur

Designation- A.D.O