GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2014/ \$2 /1237

Dated: 24/09/14

FIRE SAFETY CERTIFICATE

Certified that M/s. Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.) located at 1st floor, Community Centre, New Friends Colony, New Delhi is running at first floor of a building comprised of ground plus one upper floor was granted NOC by this department vide letter No. F.6/DFS/MS/EH/2011/2135 dated 02-09-2011. The premises was re-inspected by the officer concerned of this department on 15-09-2014 in the presence of Mr. Susan Char, manager of the restaurant and found that the said eating house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy Class- D Assembly (restaurant) with exfect from 2 4 0 9 14 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on 24/09/14 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. The Manager, M/s. Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.), 1st floor, Community Centre, New Friends Colony, New Delhi.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s. Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt.

Ltd.), 1st floor, Community Centre, New Friends Colony, New

Delhi

2. Type of Occupancy

: Assembly

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/EH/2011/2135 dated 02-09-2011.

5. Fire Safety directives letter No

: Circular NO. F.6/DFS/MS/2005/718 dated 11.11.2005

6. Date of inspection

: 21-08-2014

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officer

from the building side

: Mr. Susan Char, Manager

9. Year of Construction

: 2006-07

10. Applicant's letter No.

: nil dated 25.08.2014.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	06 mts	Provided	MR	
	Gate width		Directly accessible from the road	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases	-	- " " " " "	-	
	Upper Floors	02	Provided	MR	
	Basements	N/A	N/A	N/A	
	b. Width of staircases	-	_		
	Upper Floors	Old case	Provided (1.5, 1.0 mts)	MR	
	Basements	N/A	N/A	N/A	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d. No. of continuous staircases to terrace	01	01	MR	
	e. Width of Corridor	N/A	N/A	N/A	
	f. Door Size	1.5 mts	Provided	MR	
3	Compartmentation.		_		
	Fire check door	N/A	N/A	N/A	

	T			VE AND	
	Sealing of electrical shafts	N/A	N/A	N/A	
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.				
	Basements	30 a/c per hour	N/A	N/A	
	Upper floors	12 a/c per hour	Venting provided in kitchen	MR	
5	Fire Extinguishers				
4	Total numbers	04	Provided	MR	
	• Types	ABC, CO ₂	Provided	MR	
	IS marking	ISI marked	Provided	MR	
6	First-Aid Hose Reels.			8 5	
	Total numbers on each floor	01	Provided	MR	
	Length of hose reel hose	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	Basement	N/A	N/A	N/A	
	Upper Floor	Required	Drovidad	MD	
	Sprinkler above false ceiling	N/A	Provided N/A	MR N/A	
		1771	41/44	11/17	
11	Internal Hydrants				
	Size of riser/down-comer	100 mm	Provided	MR	
	Number of hydrants per floor Hage Bay	01	Provided	MR	
	Hose Box	01	Provided	MR	
12	Yard Hydrants.		-		

and the same of th				
	 Total number of hydrants 	N/A	N/A	N/A
3	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.	2		
	Ground Level	-	-	_
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/ Manual	N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	Pump House Access			
	Terrace level		,,	
	Discharge of pump	450, 225 LPM	Provided	MR
	➤ Head of the pump	40 mts	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.	•		*
	 Underground tank capacity 	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	5000 lts	Provided (10,000 lts)	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Ct Il			- V/ - X
1/	Standby power supply	Required	Provided (125 KVA)	MR

18	Refuge Area.		*	10.0		
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 CO ₂ type fire extinguishers found provided near elect.	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/2011/2135 dated 02-09-2011, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

00(52)

Signature of the Inspecting Officer
Name M.K.CHATTOPADHYAY
Designation: - Asstt. Div. Officer (M.Rd)