GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: <u>cfohq.dlfire@nic.in</u>, <u>Tel:-</u> 011-23414333 NO.F6/DFS/MS/EH/2014/ \$7/13/6 Dated: 21/10/19

FIRE SAFETY CERTIFICATE

Certified that M/s. Haldiram restaurant located at ground, first and second floor of B-1/H-8, M.C.I.E., Main Mathura Road, New Delhi-110044 of a building comprised of basement, ground and two upper floors owned/occupied by M/s. Haldiram Marketing Pvt. Ltd. was granted NOC by this department vide letter No. F.6/DFS/MS/EH/2011/1358 dated 28-06-2011. The premises was re-inspected by the officer concerned of this department on 10-10-2014 in the presence of manager of the restaurant and found that the said eating house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy Class-D Assembly (restaurant) with effect from 21/10/19 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules 2010.

Issued on 21/10/14 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

7

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

2. The Manager, M/s. Haldiram restaurant located at B-1/H-8, M.C.I.E., Main Mathura Road, New Delhi-110044.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s. Haldiram restaurant located at B-1/H-8, M.C.I.E., Main

Mathura Road, New Delhi-110044

2. Type of Occupancy : Assembly

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/EH/2011/1358 dated 28-06-2011.

5. Fire Safety directives letter No : N/A

6. Date of inspection : 10-10-2014

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officers

from the building side : Mr. S.K. Jain, Manager

9. Year of Construction : 2011-12

10. Applicant's letter No. : nil dated 18.08.2014.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	Provided	MR		
	• Gate width		Directly accessible from the road	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	-	-	-		
	• Upper Floors	02	Provided	MR		
	• Basements	N/A	N/A	N/A		
	b. Width of staircases	-	-	-		
	 Upper Floors 	1.5 mts	1.5 Provided	MR		
	• Basements	N/A	N/A	N/A		
	c. Protection of exits			1N/A		
	• Fire check door	Required	Provided			
	 Pressurization 	N/A	N/A	MR N/A		
	d. No. of continuous staircases to terrace	0 1	01	MR		
	e. Width of Corridor	1.5 mts	Provided	MR		
	f. Door Size	1.5 mts	Provided	MR		
3	Compartmentation.					
	• Fire check door	Required	Provided	MR		



Sealing of electrical shaftsFire Rating of shaft door	N/A	N/A	N/A
Fire Rating of shaft door	~ * / /	~ * / .	
111011111111111111111111111111111111111	N/A	N/A	N/A
Water Curtain	N/A	N/A	N/A
• Fire Dampers	N/A	N/A	N/A
Smoke Management System.			
	30 a/c per hour	N/A	N/A
	12 a/c per hour	Provided	MR
Total numbers	10	Provided	MR
• Types	ABC, CO ₂	Provided	MR
*	ISI marked	Provided	MR
	01	Provided	MR
	30 m	Provided	MR
	5 mm	Provided	MR
	system.		
	smoke	Provided	MR
• •	Ground Floor	Provided	MR
	N/A	N/A	N/A
	Required	Provided	MR
	•		MR
Hooters' Location		, , , , , , , , , , , , , , , , , , ,	MR
MOEFA			N/A
Public Address System.	IN/A	14/71	
Automatic Sprinkler System.	NT/A	N/A	N/A
Basement	IN/A	14/1	
Upper Floor	Required	Provided	MR
Sprinkler above false ceiling	N/A	N/A	N/A
Internal Hydrants			
	100 mm	Provided	MR
Number of hydrants per floor	01 no.	Provided	MR
Hose Box	01 no.	Provided	MR
	Basements Upper floors Fire Extinguishers Total numbers Types IS marking First-Aid Hose Reels. Total numbers on each floor Length of hose reel hose Nozzle diameter Automatic fire detection and alarming Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer Number of hydrants per floor	Basements Upper floors Total numbers Is marking First-Aid Hose Reels. Total numbers on each floor Length of hose reel hose Nozzle diameter Type of detectors Location of Main Panel Alternate source of power Hooters' Location Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Mid Alternal Hydrants Size of riser/down-comer Number of hydrants per floor Number of hydrants per floor Notal numbers 10 ABC, CO ₂ ISI marked 01 30 m 30 m 5 mm Coll 30 m Some Coround Floor Required N/A Required N/A Required N/A Required N/A Required N/A Internal Hydrants Size of riser/down-comer Number of hydrants per floor Number of hydrants per floor Number of hydrants per floor	Basements Upper floors Total numbers Is marking First-Aid Hose Reels. Total numbers on each floor Length of hose reel hose Nozzle diameter Type of detectors Location of Main Panel Alternate source of power Hooters' Location Basement Automatic Sprinkler System. MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Ni/A Provided Ni/A Ni



	 Total number of hydrants 	02 nos.	Provided	MR
	Hose Box	02 nos.	Provided	
13	Pumping Arrangements.		Trovided	MR
	Ground Level	-	-	_
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual	N/A	N/A	N/A
	stopping Pump House Access	N/A	N/A	N/A
	Terrace level			· · · · · · · · · · · · · · · · · · ·
	Discharge of pump	900, 180 LPM	D	
	Head of the pump	40 mts	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting		Provided	MR
	Underground tank capacity	N/A	Provided 1,00000 lts for	N/A
	Draw-off connection	N/A	factory building	
	Fire service inlet	N/A	N/A N/A	N/A
	Access to tank	N/A		N/A
		IN/A	N/A	N/A
_	o vernedd Tank Capacity	10,000 lts	Provided	MR
	Exit Signage.	Required	Provided	MR
6 P	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	
	• Lift Signage			N/A
_		N/A	N/A	N/A
$7 \mid S_1$	tandby power supply	Required	Provided 125 KVA	MR



18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	Required	Provided	MR	
ř	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	Required	Provided	MR	
	 Building Floor Plans 	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	02 CO ₂ type fire extinguishers found provided near elect.	MR	
			panel		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The shortcomings already pointed out by this department vide letter F.6/DFS/MS/EH/2014/1276 dated 11.06.2014 has been compliance by the management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/2011/1358 dated 28-06-2014, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY

Designation: - Asstt. Div. Officer (M.Rd)

12/10/14