## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: <u>cfohq.dlfire@nic.in</u>, <u>Tel:-</u> 011-23414333 NO.F6/DFS/MS/EH/2014/ 57 1317 Dated: 21 10 19

## FIRE SAFETY CERTIFICATE

Certified that M/s Pind Balluchi Restaurant (a unit of J.S.Hospitality Services Pvt. Ltd) located at ground floor, A-38, M.C.I.E, Mathura road, New Delhi of a building comprised of basement, ground and first floor was granted Fire Safety Certificate by this department vide letter No. F6/MS/DFS/EH/2011/699 dated 20.04.2011. The restaurant was re-inspected by the officer concerned of this department on 29-09-2014 in presence of Mr. Shakti Prasad, Manager (liaison) and observed that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class- D (Assembly Building) with effect from 21 10 14 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on 21/10/14 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

- 1. M/s Pind Balluchi Restaurant (a unit of J.S.Hospitality Services Pvt. Ltd), A-38, M.C.I.E, Mathura road, New Delhi.
- 2. The Dy. Health Officer, MCD, Central Zone, Lajpat Nagar, New Delhi

## Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

## **INSPECTION REPORT**

1. Name & address of the building: M/s Pind Balluchi Restaurant (A unit of J.S. Hospitality

Services Pvt. Ltd.), ground floor, A-38, M.C.I.E, Mathura

Road, New Delhi

2. Type of Occupancy

: Assembly

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/MS/DFS/EH/2011/699 dated 20.04.2011

5. Fire Safety directives letter No

: Delhi Fire Service Act-2007 & Rules 2010.

6. Date of inspection

: 29-09-2014

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officers

from the building side

: Mr. Shakti Prasad, Manager (liaison)

9. Year of Construction

: 1975

10. Applicant's letter No.

: nil dated 11.08.2014.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR
1	Access to building			,
	Road width	06 mts	Provided	MR
	Gate width		Directly accessible from the road	MR
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of	of Exits	* * * * * * * * * * * * * * * * * * *	
	a. Number of staircases	_	- " , " .	-
	Upper Floors	GF only	N/A	N/A
	Basements	N/A	N/A	N/A
	b. 'Width of staircases	-	-	-
	Upper Floors	GF only	N/A	N/A
	Basements	N/A	N/A	N/A
	c. Protection of exits			
		N/A	N/A	N/A
	Fire check door	N/A	N/A	N/A
	<ul> <li>Pressurization</li> </ul>			
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	1.5 mts	Provided	MR
3	Compartmentation.			



	D:			)
	• Fire check door	N/A	N/A	N/A
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A		N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A N/A	N/A
4	Smoke Management System.		1771	N/A
	• Basements	20 0/2	DI/A	
	<ul> <li>Upper floors</li> </ul>	30 a/c per hour	N/A	N/A
5	Fire Extinguishers	12 a/c per hour	Venting provided in kitchen	MR
	• Total numbers			
		08	Provided	MD
	• Types	ABC, CO <sub>2</sub>	Provided	MR
6	• IS marking	ISI marked	Provided	MR
+	First-Aid Hose Reels.		1 TO VIGEU	MR
	<ul> <li>Total numbers on each floor</li> </ul>	02	Provided	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m		MR
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR
F	Automatic fire detection and alarming	T OVIGA	Provided	MR
	Type of detectors			
		Required	Provided	MR
	<ul> <li>Location of Main Panel</li> </ul>	Required	Provided	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	MR
	<ul> <li>Alternate source of power</li> </ul>	Required	1771	N/A
	Hooters' Location	required	Provided	MR
		Required	Provided	MD
	OEFA	Required	Provided	MR
	ıblic Address System.	N/A	N/A	MR
Au	itomatic Sprinkler System.		1111	N/A
	• Basement	N/A	N/A	27/
	• Upper Floor	NI/A		N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
	Table Certifig	N/A	N/A	N/A
Inte	ernal Hydrants			IVA
	Size of riser/down-comer	D.		
1	Number of hydrants per floor	Required	Provided	MR
	- ~ A A A A A A A A A A A A A A A A A A			
	• Hose Box	Required	Provided	MR



12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level	-	-	_
	<ul><li>Discharge of main Pump</li></ul>	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	<ul> <li>Auto Starting/ Manual stopping</li> </ul>	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	<ul><li>Discharge of pump</li></ul>	450 LPM	Provided	MR
	➤ Head of the pump	40 mts	Provided	MR
2	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting	<b>;</b> •		
	Underground tank capacity	N/A	N/A	N/A
,	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 lts	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A
	Communication In lift Car	» N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A		



17	Standby power supply	B .		
18	Refuge Area.	Required	Provided	MR
	> Total Area			2721
	► Location	N/A	N/A	N/A
9	Fire Control Room	N/A	N/A	N/A
	<ul> <li>Detector System Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	
	<ul> <li>PA System Panel</li> </ul>	NI/A		N/A
		N/A	N/A	N/A
	<ul> <li>Batter backup</li> </ul>	N/A	N/A	N/A
+	<ul> <li>Building Floor Plans</li> </ul>	N/A	NI/A	
	Special Fire Protection Systems for		N/A	N/A
1	Protection of special Risks, if any:	Required	01 CO <sub>2</sub> type fire extinguishers found provided near elect.	MR
		*	panel	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The management has rectified all the shortcomings issued by this department vide letter No. F6/DFS/MS/EH/2014/1046 dated 13.05.2014.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/MS/DFS/EH/2011/699 dated 20.04.2011, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

85 m

DC fo (3/2) [10/14

Signature of the Inspecting Officer

Name M.K.CHATTOPADHYAY Designation: - Asstt. Div. Officer (M.Rd)