GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- <u>cfohq.dlfire@nic.in</u>
No.F.6/DFS/MS/School/2014/ s z / 1198

Fax:- 011-23412593

Dated: /5/68//4

FIRE SAFETY CERTIFICATE

Certified that the **Rao Brij Mohan Public School**, Plot No. 7, Brij Vihar, Paprawat, Najafgarh, New Delhi 110043 comprised of ground floor plus two upper floors, was issued NOC by this department vide letter F.6/DFS/MS/2010/2263 dated 30.07.2010 for ground floor plus one upper floor. The School building was re-inspected by the officer concerned of this department on 30.08.2014 in the presence of Sh. Jaibir Yadav (Director) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

orc san

Copy to:-

1

- 1. The Director, Rao Brij Mohan Public School, Plot No. 7, Brij Vihar, Paprawat, Najafgarh, New Delhi 110043.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.



Ground plus two upper floors

(Rao Brij Mohan Public School, Plot No. 7, Brij Vihar,

Paprawat, Najafgarh, New Delhi – 110043)

INSPECTION REPORT

1. Name & address of the building: Rao Brij Mohan Public School, Plot No. 7, Brij Vihar,

Paprawat, Najafgarh, New Delhi – 110043

2. Type of Occupancy : Educational

3. Type of Case : Renewal

4. Details of Previous NOC : F.6/DFS/MS/2010/2263 dated 30.07.2010

5. Fire Safety directives letter No : N/A

6. Date of inspection : 30.08.2014

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. Jaibir Yadav (Director)

9. Year of Construction : From 2008 to 2010.

	10. Applicant's letter No. : 12014/14,	/RBM dated 01.08	.2014			
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road width	Accessible	6.0 mtrs	M/R		
	Gate width		3.0 mtrs	1		
	 Width of internal road 					
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02 No's.	02 No's	M/R		
	 Basements 	N/A	N/A	No basement		
	b. Width of staircases		Com			
	Upper Floor		136 & 125 cms	M/R, Old case/bldg.		
	 Basements 	N/A	N/A	No basement		
	c. Protection of exits	1471	1.0.2			
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	,	N/A	IN/A	IVI		
	d. No. of continuous staircases to					
	terrace			, and an analysis of the state		
	e. Width of Corridor		160 cms	N/A		
	f. Door Size	_	160 cms	IN/A		
	1. Door Size					
	,		90 cms	M/R, Old case/bldg.		
3.	Compartmentation					
3.	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A N/A	N/A	N/A		
		IN/A	14/74	11111		
4.	Smoke Management System					
	Basements	N/A	N/A	No basement		

Ground plus two upper floors

(Rao Brij Mohan Public School, Plot No. 7, Brij Vihar, Paprawat, Najafgarh, New Delhi – 110043)

	Paprawa	t, Najafgarn, New		M/D		
	Upper floors	<u>-</u>	Natural ventilation	M/R		
•	Fire Extinguishers		7 111	M/D		
	Total numbers	Eight no's ABC/CO2 type	Provided	M/R		
	• Types	ABC/CO2 type	Provided	M/R		
	IS marking	ISI marked	ISI marked	M/R		
<u>.</u>	First-Aid Hose Reels			3.679		
0.	Total numbers on each floor	one	Provided	M/R		
	 Length of hose reel hose 	30 mtrs	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		
	2					
7.	Automatic fire detection and alarming system	N/A	N/A	N/A		
	Type of detectors	N/A N/A		N/A		
	Location of Main Panel	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
			N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8.	MOEFA	14/17				
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Sprinkler System					
	Doorwood	N/A	N/A	N/A		
	Basement Grand Floor	N/A	N/A	N/A		
	Ground Floor Graph Har above false soiling	N/A	N/A	N/A		
11	Sprinkler above false ceiling Internal Hydrants	11/12		<u> </u>		
11.	Internal Hydrants		2.3	1		
. 535-75	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements		a a	0.00		
	Ground Level					
	Ground LevelDischarge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put			N/A		
	> Jockey pump head	N/A	N/A	VIII 100 II		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		

MIT

Ground plus two upper floors

(Rao Brij Mohan Public School, Plot No. 7, Brij Vihar, Paprawat, Najafgarh, New Delhi – 110043)

	Ground plus two upper floors Panrawat Nai	Noiofagrh New Delhi - 110043)			
A		N/A	N/A	N/A	
	Pump House Access			-	
	Terrace level	450 LPM	Provided	M/R	
	Discharge of pump	40 mtrs	Provided	M/R	
	Head of the pump	N/A	N/A	N/A	
	> Power Supply	N/A	N/A	N/A	
	> Auto Starting of pump				
	Captive Water Storage for fire fighting		N/A	N/A	
1.	Underground tank capacity	N/A	N/A	N/A	
	CCction	N/A	N/A		
	- inlot	N/A	N/A	N/A	
	> Fire service inlet > Access to tank	N/A	N/A	N/A	
	a wheed Tank canacity	10000 ltrs	Provided	M/R	
	Overnead Talik Capacity	Required	Provided	M/R	
5.	Exit Signage.			V	
			No Lift	NI/A	
16.	Provision of Lifts.	N/A	N/A	N/A	
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch		N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
		N/A	N/A		
17.	Standby power supply				
18.	Refuge Area.	N/A	N/A	N/A	
10.	> Total Area		NI/A	N/A	
	> Location	N/A	N/A	1772	
19.	Fire Control Room	N/A	N/A	N/A	
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel		N/A	N/A	
	Pottony backlin	N/A	N/A	N/A	
	Battery backup	N/A	14/71	2	
	Building Floor Plans				
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A	

Ground plus two upper floors

(Rao Brij Mohan Public School, Plot No. 7, Brij Vihar, Paprawat, Najafgarh, New Delhi – 110043)



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number dated 30.07.2010 renewal under rule 35 of the F.6/DFS/MS/2010/2263 Delhi Fire Service Rules 2010 is recommended.

Note: - The undertaking is placed on C-12 given by the Manager of School, regarding No. of students in each class less than 45 & year of construction from 2008 to 2010 of School building comprised of ground, first and second floor.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

D.O. (South West) for renewal of FSC pl.