GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6 OFS (MS) school /2014/ MOZ /1327

Dated: 22 (0)19

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Senior Secondary School, Lalita Park (Ramesh Park), Delhi-92, comprised of ground floor plus one upper floor was granted FSC by this department vide Letter No- F.6/DFS/MS/School/2011/2971 dated 15.11.2011. School building was re-inspected by the officer concerned of this department on 15.10.2014 in the presence of HOS of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular No. F.16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and found that the building is fit for occupancy Group B "Educational Building" with effect from....renewed for a period of three years, subject to conditions printed overleaf.

Issued on 22/10/17 at New Delhi by

(Dr. G.C. Misra)

Chief Fire Officer

Ph -011- 23414333

To,

The Principal

Govt. Girls Senior Secondary School, Lalita Park (Ramesh Park), Delhi-92

Copy to:-.

1. The Joint Director of Education

(Land & Estate)

Directorate of Education, Lucknow Road, Delhi -54

2. The Principal

Govt. Boys Senior Secondary School, Lalita Park (Ramesh Park), Delhi-92

CONDITIONS:

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

	INCDE	TION REPORT	-				
1. Na	200 P 20 P		المسر ومام ما المانه	Davil			
	7	: Govt. Girls Senior Secondary School, Lalita Park (Ramesh Park), Delhi-92					
2. Bu	uilding is comprised of : G+1	icsii i arkį, Delili-32					
		ational	22				
	pe of Case : Rene						
		DFS/MS/School/201	1/2071 dated 1	. 11 2011			
		/Estate/CC/Fire safe					
		d 01.03.11	(7/2011/3236 (0	73336			
7. Da		0.2014					
	ame of the Inspecting Officers: : Suresh						
	ame of the designation of Officer	S. ()					
	om the building side : HOS						
10. Ye	ear of Construction : 1989	5					
11. A	pplicant's letter No : GGS	SS/LP/197 Dated 23.	09.2014				
S.No		afety Requirement		Remarks			
	requirements as per circular no. 329	8 to	Site	MR/NMR			
	3398 Dated. 01.03.11			4			
1	Access to building		4	1			
	Road width	6 m	6 m	MR			
	Gate width	4.5 m	5.2 m	MR			
	Width of internal road	N.A.	N.A.	N.A.			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	07 no.	07no.	MR			
	Basement	N.A	N.A.	N.A.			
	B. Width of Staircases		1.00	340			
	Upper Floor	1.5 m	1.5 m each	MR			
	Basement	N.A	N.A.	N.A.			
=	c. Protection of exits	N.A	N.A.	N.A.			
	Fire check door	N.A.	N.A.	N.A.			
	Pressurization	N.A.	N.A.	N.A.			
	e. No. of continuous staircases to terra	nce N.A.	N.A.	N-A			
	g. Width of Corridor	1.5 m	1.5 m	MR			
	h. Door Size	1 m	1 m	MR			
3	Compartmentation						
	Fire check door	N.A.	N.A.	N.A.			
	Sealing of electrical shafts	N.A.	N.A.	N.A.			
	Fire rating of shaft door	N.A.	N.A.	N.A.			
	Water curtain	N.A.	N.A.	N.A.			
	Fire Dampers	N.A.	N.A.	N.A.			
4	Smoke Management System.	IV.A.	IV.A.	14.A.			
i i	Basement	N.A.	N.A.	NιΛ			
	Upper floor	N.A.	N.A.	N.A.			
	opportion	IV.A.	IV.A.	N.A.			

5.	Fire Extinguisher					
	Total numbers	15 no.	15 no.	MR		
	types	CO ₂ & ABC	CO ₂ & ABC	MR		
6	IS marking	ISI marked	ISI marked	MR		
Ь	First-aid-Hose Reels.			\$25g		
	Total numbers of each floor	N.A.	N.A.	N.A.		
	Length of hose reel hose	N.A.	N.A.	N.A.		
	Nozzle diameter	N.A.	N.A.	N.A.		
7	Automatic fire detection and alarming system.					
	Type of detectors	N.A.	N.A.	N.A.		
	Location of main panel	N.A.	N.A.	N.A.		
	Location of repeater panel	N.A.	N.A.	N.A.		
	Alternate source of power	N.A.	N.A.	N.A.		
*	Hooters's location	N.A.	N.A.	N.A.		
8	MOEFA	N.A.	Provided	MR		
9	Public address System.	N.A.	Provided	MR		
10	Automatic Sprinkler System.					
	basement	N.A.	N.A.	N.A.		
	upper floor	N.A.	N.A.	N.A.		
	sprinkler above false ceiling	N.A.	N.A.	N.A.		
11	Internal Hydrants					
	size of riser/down-comer	N.A.	N.A.	N.A.		
	Number of hydrants per floor	N.A.	N.A.	N.A.		
	Hose Box	N.A.	N.A.	N.A.		
12	Yard Hydrants.					
	Total number of hydrants	N.A.	N.A.	N.A.		
	Hose Box	N.A.	N.A.	N.A.		
13	Pumping Arrangements.					
	Ground Level	N.A.	N.A.	N.A.		
	 Discharge of main Pump 	N.A.	N.A.	N.A.		
	➤ Head of Main Pump	N.A.	N.A.	N.A.		
	Number of main pumps	N.A.	N.A.	N.A.		
	> Jockey pump out put	N.A.	N.A.	N.A.		
	Jockey pump head	N.A.	N.A.	N.A.		
	Standby pump out put	N.A.	N.A.	N.A.		
	Standby pump Head	N.A.	N.A.	N.A.		
	Auto Starting / Manual stopping	N.A.	N.A.	N.A.		
	Pump House Access	N.A.	N.A.	N.A.		
	Terrace Level	N.A.	N.A.	N.A.		
	Discharge of pump	N.A.	N.A.	N.A.		
	Head of the Pump	N.A.	N.A.	N.A.		
	Power supply	N.A.	N.A.	N.A.		
		1 4 4 / 10	1 1 N 1 / N 1	I I W M		

Govt. Girls Senior Secondary School, Lalita Park (Ramesh Park), Delhi-92

14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	N.A.	N.A.	N.A.		
	Draw-off connection	N.A.	N.A.	N.A.		
	Fire service inlet	N.A.	N.A.	N.A.		
	Access to tank	N.A.	N.A.	N.A.		
	Overhead Tank capacity	N.A.	N.A.	N.A.		
15	Exit Signage.	N.A.	N.A.	N.A.		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.		
	Pressurization of Lift lobby	N.A.	N.A.	N.A.		
	Communication in lift car	N.A.	N.A.	N.A.		
	Firemen's grounding switch	N.A.	N.A.	N.A.		
	Lift Signage	N.A.	N.A.	N.A.		
17	Standby power supply	N.A.	N.A.	N.A.		
18	Refuge Area.					
	Total area	N.A.	N.A.	N.A.		
	Location	N.A.	N.A.	N.A.		
19	Fire Control Room					
	Detector system panel	N.A.	N.A.	N.A.		
	Flow switch panel	N.A.	N.A.	N.A.		
	PA system panel	N.A.	N.A.	N.A.		
	Batter backup	N.A.	N.A.	N.A.		
	Building Floor Plans	N.A.	N.A.	N.A.		
20	Special Fire Protection systems for	N.A.	N.A.	N.A.		
	protection of special Risks, if any:					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules the FSC issued vide letter no. F.6/DFS/MS/School/2011/2971 dated 15.11.2011 renewal under the circular No. 3298 to 3398 dated 01.03.11 is recommended.

Signature of the Inspecting Officer

Name

Suresh Singh

Designation

ADO (Shah)

DO (EAST)