

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

**Fax: 23412593, Tel:- 011-23414333**

No. F6/MS/DFS/EH/2014/ 52/1348

Dated: 28/10/14

**FIRE SAFETY CERTIFICATE**

Certified that the Burger King restaurant located at Shop No.2 & 3, 2<sup>nd</sup> floor, Select City Walk Mall, A-3 Distt. Center Saket, New Delhi-110017, comprised of basement, ground floor + two upper floors owned/occupied by Burger King India Private Ltd. The restaurant is running at second floor. The premises was inspected by the officer concerned of this department on 25/10/14 in the presence of Mr. Manish Shankar and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group – D, Assembly Building with effect from 28/10/14 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 28/10/14 at New Delhi by.

  
(Dr.G.C.Misra)  
Chief Fire Officer

Copy to:-

(1) Dy. Health Officer/ South Zone  
Aurbindo Marg, Green Park  
New Delhi

(2) Mr. Amit Kumar  
Burger King  
Shop No.2 & 3 2<sup>nd</sup> Floor, Select City Walk Mall,  
A-3 Distt Center Saket, New Delhi-110017,

  
ADDO (B.C.P.)

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of NBC
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)

**INSPECTION REPORT**

1. Name & address of the building:-Burger King India Private Ltd.Unit No-S2& 3 2<sup>nd</sup> Floor, Select City Mall,A-3,Distt. Center Saket, New Delhi-110017
  2. Type of occupancy:- Assembly Building, Group – D, Restaurant
  3. Type of case:- New
  4. Details of previous NOC:- Nil
  5. Fire safety directives No.- Nil
  6. Date of inspection:-25/10/14
  7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
  8. Name & designation of officer From the building side:- Mr. Manish Shankar
  9. Year of construction:- 2007.
  10. Applicant's letter No:-No.DHO/SZ/2014/D/1498 dated 20/10/14
- Building is comprised of Basement, Ground + Two Upper Floors. Restaurant is running at second floor.

Sl.No	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Remarks MR/NMR
<b>1.</b>	<b>Access to Building</b>			
	1) Road width	9mtrs	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	06	Provided	MR
<b>2.</b>	<b>Number, Width Type &amp; Arrangement of Exits</b> <span style="float:right"><b>Provided and maintained by Mall</b></span>			
	A. Number of staircases			
	1. Upper floors	1.5m	Two Provided near Restaurant	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.5m	1.52m & 1.16m	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required	Provided by mall	MR
	2. Pressurization	Required	Provided by mall	MR
	D. No. of continuous staircase to terrace	Required	Provided by mall	MR
	E. Width of corridor	Required	Provided by mall	MR
	F. Door size	02 m	Open front more than 12 m & 1.75m	MR
<b>3.</b>	<b>Compartmentation</b> <span style="float:right"><b>Provided and maintained by Mall</b></span>			
	1) Fire check door	Required	Provided by Mall	MR
	2) Sealing of electrical shafts	Required	Provided by Mall	MR
	3) Fire rating of shaft door	Required	Provided by Mall	MR
	4) Water curtain	Required	Provided by Mall	MR
	5) Fire Dampers	Required	Provided by Mall	MR
<b>4.</b>	<b>Smoke Management System</b> <span style="float:right"><b>Provided and maintained by Mall</b></span>			
	1) Basements	30 a/c per hour	Provided by Mall	MR
	2) Upper floors	12 a/c per hour	Provided by Mall	MR
<b>5.</b>	<b>Fire Extinguishers</b> <span style="float:right"><b>Provided and maintained by Mall</b></span>			
	1) Total numbers	ISI Marked	06 Nos.	MR
	2) Types		ABC, Co2 ,Foam	MR
	3) ISI marking		Yes	MR

*[Handwritten Signature]*

<b>6.</b>	<b>First-Aid Hose Reel</b>	<b>Provided and maintained by Mall</b>		
	1) Total number of each floor	do	do	do
	2) Length of hose reel hose	do	do	do
	3) Nozzle diameter	do	do	do
<b>7.</b>	<b>Automatic Fire Detection &amp; Alarming System</b>	<b>Provided and maintained by Mall</b>		
	1) Type of detectors	do	do	do
	2) Location of main panel	do	do	do
	3) Location of repeater panel	do	do	do
	4) Alternate source of power	do	do	do
	5) Hooter's Location	do	do	do
<b>8.</b>	<b>MOEFA</b>	<b>Provided and maintained by Mall</b>		
<b>9.</b>	<b>Public Address System</b>	<b>Provided and maintained by Mall</b>		
<b>10.</b>	<b>Automatic Sprinkler System</b>	<b>Provided and maintained by Mall</b>		
	1) Basement	do	do	do
	2) Upper floors	do	do	do
	3) Sprinkler above false ceiling	do	do	do
<b>11.</b>	<b>Internal Hydrants</b>	<b>Provided and maintained by Mall</b>		
	1) Size of riser/down-comer	do	do	do
	2) Number of hydrants per floor	do	do	do
	3) Hose box	do	do	do
<b>12.</b>	<b>Yard Hydrants</b>	<b>Provided and maintained by Mall</b>		
	1) Total number of hydrants	do	do	do
	2) Hose box	do	do	do
<b>13.</b>	<b>Pumping Arrangement</b>	<b>Provided and maintained by Mall</b>		
	1) Ground level	do	do	do
	a) Discharge of main pump	do	do	do
	b) Head of main pump	do	do	do
	c) Number of main pump	do	do	do
	d) Jockey pump out put	do	do	do
	e) Jockey pump head	do	do	do
	f) Stand by pump output	do	do	do
	g) Stand by pump head	do	do	do
	h) Auto starting/Manual stopping	do	do	do
	2) Terrace level	do	do	do
	a) Discharge of pump	do	do	do
	b) Head of pump	do	do	do
	c) Power supply	do	do	do
	d) Auto starting of pump	do	do	do
<b>14.</b>	<b>Captive Water Storage for Fire Fighting</b>	<b>Provided and maintained by Mall</b>		
	1) Under ground tank capacity	do	do	do
	a) Draw-off connection	do	do	do
	b) Fire service inlet	do	do	do
	c) Access to tank	do	do	do
	d) Over head tank capacity	do	do	do
<b>15.</b>	<b>Exit Signage.</b>	<b>Provided and maintained by Mall</b>		
<b>16.</b>	<b>Provision of Lifts.</b>	<b>Provided and maintained by Mall</b>		
	a) Pressurization of lift shaft	do	do	do
	b) Pressurization of lift lobby	do	do	do
	c) Communication in lift car	do	do	do
	d) Fireman's switch	do	do	do
	e) Lift signage	do	do	do

02/4

17.	Stand by Power Supply	Provided and maintained by Mall		
18.	Refuge Area	Provided and maintained by Mall		
	Total area	do	do	do
	location	do	do	do

19.	Fire Control Room	Provided and maintained by Mall		
	a) Detector system panel	do	do	do
	b) Flow switch panel	do	do	do
	c) PA system panel	do	do	do
	d) Battery backup	do	do	do
	e) Building floor plan	do	do	do

20. **Special Fire Protection System for Protection of special Risk, if any:**

The fire protection system provided in the building were checked and found functional at the time of inspection.

The mall has issued FSC vide letter no. F6/DFS/MS/2011/3114 dated 22/11/2011.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 3 5 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer  
 Name :- D.B. Mukherjee.  
 Designation :- Assistant Divisional Officer.

*[Handwritten Signature]*  
 27/11/2014

*[Handwritten Signature]*  
 27/11/2014

*[Handwritten Signature]*  
 27/11/2014