GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. FB DF3/ms/Hospital/2014/w2/1374 Dated: 07/11/2014

FIRE SAFETY CERTIFICATE

Certified that the MAX Health Care Institute Ltd. at FC-50 Shalimar Bagh, New Delhi comprised of 2 Basement+Ground+09 upper floors, owned/occupied by MAX Health Care Ltd was earlier issued FSC by this deptt. vide letter F.6/DFS/MS//Hospital/2011/2019 dated 19/08/11. The premises was re-inspected by the officer concerned of this department on 26-09-2014 in the presence of Mr. Dhramender and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore, deemed complied with the requirement under Rule 33 of the Delhi Fire Service Rule 2010 and thus the building/premises is fit for accordance with rule 36 unless renewed under 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under 38 of the Delhi Fire Service Rule 2010.

Following fire safety directives must be adhered to:-

1) All the means of escape shall be kept free of all type of obstruction all the time.

2) All the employees shall be acquainted with the use and maintenance of a fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3) All the fire fighting equipment shall be maintained in perfect working condition all the time and lapse rendering non-functional of fire safety measures, management shall be responsible.

4) Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.

5) Basement shall be used as per NBC.

6) This NOC may not be treated in any case for regularizations of unauthorized construction, if any.

7) The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

8) "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

Issued on.....at New Delhi by

(Santokh Singh) Chief Fire Officer Tel. No. 23414250 cfowz.dlfire@nic.in

016

Copy to: Authorised Signatory MAX Health Care Institute Ltd. at FC-50 Shalimar Bagh, New Delhi

INSPECTION REPORT

Basement + Ground + Nine Upper floors

Name & address of the building : MAX Health Care Institute Ltd. at FC-50 Shalimar Bagh, New

Delhi.

2. Type of Occupancy : Institutional3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS//Hospital/2011/2019 dated 19/08/11

5. Fire Safety directives letter No. : F.6/DFS/MS/BP/2009/2635 dated 26/08/2009

6. Date of inspection : 26-09-2014

7. Name of the Inspecting Officers : ADO (W.P.) & Sunil Chawdhary DO (M.N.)

8. Name and designation of officers From the building side

From the building side : Mr. Dharmender
9. Year of Construction : 2008-2009
10. Applicant's letter No. : nil dated nil

S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road width	12 m	30 m	M/R		
	Gate width	06 m	Provided /	M/R		
	Width of internal road	06 m	Provided	M/R		
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	• Upper Floors	06 staircase up to 3 rd floor out of which 4 staircase from 4 th floor to 9 th floor	Provided	M/R		
	Basement	06	Provided	M/R		
	b. Width of staircases			-		
	Upper Floors	2 m	Provided C	M/R		
	Basement	2 m	Provided	M/R		
	c. Protection of exits					
	Fire check door	Required	Provided	M.R.		
	Pressurization	Required	Provided	M.R.		
	d. No. of continuous staircases to					
	e. Width of Corridor	Old case	Old case	M.R.		
	f. Door size	Old case	Old case	M.R.		
2		Old ouse				
3.	Compartmentation.					
	Fire check door	Required	Provided _	M.R.		
	Sealing of electrical shaftsFire Rating of shaft door	Required	Provided -	M.R.		
		Required	Provided	M.R.		
	Water Curtain	Required	Provided	M.R.		
	Fire Dampers	Required	Provided	M.R.		
4	Smoke Management System.					
	Basements	Required	Provided	M.R		
		Required	Provided 6	M.R.		
-	Upper floors	Required	Trovided	177.17.		
5.	Fire Extinguishers	165	106	M.R		
	Total numbers	165	186			
	• Types	ABC, CO ₂ Type	Provided	M.R		
	IS marking	ISI marked	Provided	M.R		
6.	First-Aid Hose Reels.					
	Total numbers on each floor	02	Provided /	M.R		
1	Length of hose reel hose	30 m required	Provided C	M.R		
		5 mm	Provided	M.R		

	- Type of detectors	Smoke & Heat	Provided /	M.R.
	Location of Main Panel	G. floor	Provided	M.R.
	Location of Repeater Panel	Each floor	Provided	M.R.
	Alternate source of power	Required	Provided	M.R.
	Hooter's Location	Required	Provided	M.R.
8.	MOEFA	Required	Provided	M.R
9.	The state of the s	Required	Provided	M.R
10	Automatic Sprinkler system	Required	Provided	M.R
	Basement	Required	Provided	M.R
	• Upper Floor	Required	Provided	M.R
	 Sprinkler above false ceiling 	N.R.	N.R.	N.R.
11	. Internal Hydrants		A DESCRIPTION OF THE PROPERTY	
	Size of riser/down-comer	150 mm	provided	M.R
	Number of hydrants per floor	required	provided	M.R.
	Hose Box	Required	provided	M.R
12.	Yard Hydrants.			
	Total number of hydrants	06	I.B. id. id.	-
		06	Provided /	M.R.
	Hose Box	00	Provided	M.R.
13.	Pumping Arrangements.			
	Ground Level			
	Discharge of main pump	2280 LPM	Provided	MD
	Head of Main pump	120 m	Provided /	M.R.
	Number of main pumps	02	Provided	M.R.
	> Jockey Pump out put	180 LPM		
	> Jockey rump out put > Jockey pump head		Provided	M.R.
		120 m	Provided	M.R.
	pump out put	2280 LPM	Provided	M.R.
	Standby pump HeadAuto Starting/Manual	120 m	Provided	M.R.
	stopping	Required	Provided	M.R.
	> Pump Hose Access	Required	Provided	M.R.
7 837	Terrace level	900 LPM	Described.	
	Discharge of pump	70 m	Provided /	M.R.
	Head of the pump	Required **	Provided Provided	M.R.
	Power supplyAuto Starting of pump	Required	Provided /	M.R.
14.	Captive Water Storage for fire figl		1 Tovided y	W.R.
	Underground tank capacity	2,00,000 ltrs	D. iti	
	> Draw -off connection	Required	Provided Provided	M.R.
	Fire service inlet	Required	Provided Provided	M.R.
	Access to tank	Required	Provided	M.R.
	Overhead Tank Capacity	20,000 ltrs	Provided	M.R.
15	Exit Signage.	required	Provided (M.R.
16	Provision SX'S			174,116

				Provided	M.R.
	0	ommunication In lift Car	Required	Flovided	
			Required	Provided	M.R.
		reman's Grounding Switch		Provided	M.R.
	• Li	ft Signage	Required	Flovided	
	Mar But				
			Required	Provided	M.R
17.	Stand	by power supply	Requires		
18.	Refug	ge Area			
			0.00 5 mtm	Provided	M.R.
	>	Total Area	19.5 mtr & 26.5 mtr	11041000	
			5 th & 7 th floor	Provided	M.R.
	>	Location			
19.	Fire C	ontrol Room			
				Provided	M.R.
	A	Detector System Panel	Required	Flovided	
		Flow Switch Panel	Required	Provided	M.R.
	>	Flow Switch Faller	Required		N/ D
	>	PA system Panel	Required	Provided	M.R.
				Provided	M.R.
	A	Batter backup	Required	Provided	141.14
		•	Required	Provided	M.R.
	>	Building Floor plans	Kedanea		
	-	1 El D 4 d'an Caratanna	N.R.	N.R.	N.R.
20.		al Fire Protection Systems	14.17.		
		otection of special Risks, if			
	any:		3	`	

The fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC vide letter No. F.6/DFS/MS//Hospital/2011/2019 dated 19/08/11 renewal under rule 35 of the Delhi Fire Service rule 2010 is recommended.

Signature of the Inspection Officer

Name Sunil Chawdhary Uday Vir Singh

Designation DO(W) ADO (WP)

Signature of the Inspection Officer

Name 2h. Somit charothany
Designation Do (w)