GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 011-23412593, Tel:- 011-23414333

No. F6/MS/DFS/EH/2014/52 / 1424

Dated 19/11/14

FIRE SAFETY CERTIFICATE

Issued -4-7-4-4----at New Delhi by.

(Dr. G.C.Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

OTE 18/11/2014 18/11/2014 Dao (Bes)

Copy to:- (1) Mr Shailendra Pandey
Connaught Plaza Restaurants Pvt. Ltd.
13A,Jor Bagh Market, New Delhi-110013

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of NBC
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1.Name & address of the building:-Mc.Donald Family Resturant, Shop No-1, Ground Floor, Satyam Complex, Nehru Place, New Delhi-110019
- 2. Type of occupancy:- Assembly Building, Group D, Restaurant
- 3. Type of case:- Renewal
- 4. Details of previous NOC:-No. F6/DFS/MS/EH/2011/1949 dated 12/08/2011.
- 5. Fire safety directives No.- Nil
- 6. Date of inspection:-04/11/14
- 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side:- Mr.D.N. Thakur
- 9. Year of construction: 2006

10. Applicant's letter No:-Nil dated Nil (Building is comprised of basement, ground plus two upper floors.)

			urant is running in Ground floor				
S.No	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	09 m	Provided	MR			
	2) Gate width	N/A	N/A	MR			
	3)Width of internal road	06 m	Provided	MR			
2.	Number, Width Type & Arrangement of Exits: Provided and maintained by Management						
	A. Number of staircases						
	1. Upper floors	N/A	N/A	N/A			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	N/A	N/A	N/A			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	Required	Provided	MR			
	2. Pressurization	Required	Provided	MR			
	D. No. of continuous staircase to terrace	Required	Provided	MR			
	E. Width of corridor	Required	Provided	MR			
	F. Door size	Required	1.41 m & 1.40 m	MR			
3.	Compartmentation Provided and maintained by Building Management						
	1) Fire check door	Required	Provided	MR			
	2) Sealing of electrical shafts	Required	Provided	MR			
	3) Fire rating of shaft door	Required	Provided	MR			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System Provided and maintained by Building Management						
••	1) Basements	30 a/c per hour	Provided	MR			
	2) Upper floors	12 a/c per hour	Provided	MR			
5.	Fire Extinguishers Provided and maintained by Building Management						
	1) Total numbers		05 Nos.	MR			
	2) Types	ISI Marked	ABC, Co2 ,Foam	MR			
	3) ISI marking		Yes	MR			
6.	First-Aid Hose Reel	Provided and maintained by Building Management					
	1) Total number of each floor	do	do	do			
	2) Length of hose reel hose	do	do	do			
	3) Nozzle diameter	do	do	do			

-	Automatic Fire Detection & Alan Management			i de la companya della companya della companya de la companya della companya dell	
	1) Type of detectors	do .	do	do	
	2) Location of main panel	do	do	do	
	3) Location of repeater panel	do	do	do	
	4) Alternate source of power	do	do	do	
_	5) Hooter's Location	do	do	do	
	MOEFA	Provided and maintained by Building Managemen			
).	Public Address System Provided and maintained by Building				
10.	Automatic Sprinkler System	Provided and maintained by Building Management			
	1) Basement	do	do	do	
	2) Upper floors	do	do	do	
	3) Sprinkler above false ceiling	do	do	do	
1.	Internal Hydrants	Provide	d and maintained by B		
	1) Size of riser/down-comer	do	do		
	2) Number of hydrants per floor	do	do	do	
	3) Hose box	do	do	do	
2.	Yard Hydrants			do	
	1) Total number of hydrants	do	do do		
	2) Hose box	- do	do	do	
3.	Pumping Arrangement			do	
	1) Ground level	do	d and maintained by E		
	a) Discharge of main pump	do	do do	do	
	b) Head of main pump	do		do	
	c) Number of main pump	do	do	do	
	d) Jockey pump out put	do	do do	do	
	e) Jockey pump head	do		do	
	f) Stand by pump output	do	do	do	
	g) Stand by pump head	do	do	do	
	h) Auto starting/Manual stopping	do	do	do	
	2) Terrace level	do	do	do	
	a) Discharge of pump	do	do	do	
	b) Head of pump	do	do	do	
	c) Power supply	do	do	do	
	d) Auto starting of pump	do	do do	do	
			The state of the s	do	
	Captive Water Storage for Fire Fighting: Provided and maintained by Building				
	Under ground tank capacity	do	do	do	
	a) Draw-off connection	do	do	do	
	b) Fire service inlet	do	do	do	
	c) Access to tank	do	do	do	
	d) Over head tank capacity	do	do	do	
5.	Exit Signage.	Provided	uo	MR	
ó.	Provision of Lifts.			1711	
	a) Pressurization of lift shaft	NI/A	7.1/4		
	-	N/A	N/A	N/A	
	b) Pressurization of lift lobby c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
		N/A	N/A	N/A	
	e) Lift signage Stand by Power Supply	N/A	N/A	N/A	
	STORE BY POWER Supply	Provided and maintained by Building Management			

M

10	Defuge	Awaa	Provided and maintained by Building Management		
18.	Refuge Area	do	do	do	
	Total are		do	do	do
2	location		00	and maintained by Buildi	ng Management
19.	Fire Co	ntrol Room	Provided		
	a) I	Detector system panel	do	do	do
		low switch panel	do	do	do
		A system panel	do	do	do
		Battery backup	do	do	do
	e) I	Building floor plan	do	do	do
20.	Special	ial Fire Protection System for Protection of special Risk, if any:			

The fire protection system provided in the building were checked and found functional at the time of inspection. The Satyam Complex Nehru Place has been issued NOC by the department.

Keeping in view deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the NOC issued vide letter no F6/DFS/MS/EH/2011/1949 Dated: 12/08/2011 renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly DFA is put up please.

Signature of the inspecting officer Name: - D.B. Mukherjee.

Designation :- Assistant Divisional Officer(BCP).

Do South Milly Side Side Min

Desc 12-11-14 1090

Afr Mus