## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2014/ \$ 2 / 14 20

Dated: 19/11/14

## FIRE SAFETY CERTIFICATE

Issued -- 1-3/11/19--- at New Delhi by.

(Dr. G.C.Misra) Chief Fire Officer Delhi Fire Service

of Enfances

## Copy to:-

- (1) Dy. Health Officer, South Zone, Green Park, Aurbindo Marg, New Delhi-110016
- (2) Mr. Chanpreet Singh Sahni, The Asia Kitchen, 15,Basant Lok, Vasant Vihar, New Delhi-110057

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of NBC
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## INSPECTION REPORT

- 1. Name & address of the building:-The Asia Kitchen(formerly Near East Restaurant), 15, Basant Lok, Vasant Vihar, New Delhi-110030
- 2. Type of occupancy:- Assembly, Group D, Restaurant
- 3. Type of case:-Renewal
- 4. Details of previous NOC:-F6/DFS/MS/EH/2012/2288 dated 26/06/12
- 5. Fire safety directives No.- Nil
- 6. Date of inspection:-31/10/2014
- 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side:- Mr. Sanjay Chaddha
- 9. Year of construction:- 1990
- 10.Applicant's letter no:- DHO/SZ/2014/D/1113 Dated: 26/08/2014

Building is comprised of ground, Mezzanine + 03 upper floors. Restaurant is running at ground, Mezzanine and 1st floor.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks			
1.	Access to Building MR/NMI						
	1) Road width	4.5m	1.5				
	2) Gate width	N/A	4.5 m Provided	MR			
	3)Width of internal road	N/A N/A	N/A	N/A			
2.	Number, Width Type & Arrangement o	f Evita	N/A	N/A			
	A. Number of staircases						
	1. Upper floors						
	2. Basements	N/A	02 nos.	MR			
- 1	B. Width of staircase	IN/A	N/A	N/A			
	1. Unper floors						
-	2. Basements	Old Case N/A	1.05 & 1.23mtrs.	MR (Old Case			
	C. Protection of exits	IN/A	N/A	N/A			
	1. Fire check door						
	2. Pressurization	Requred	Provided	MR			
	D. No. of continuous staircase to terrace	N/A	N/A	N/A			
	E. Width of corridor	Required	01 Nos	MR			
	F. Door size	N/A	N/A	N/A			
	Compartmentation	1.5 m	1.5 m 2 nos.	MR (Old Case)			
1	1) Fire cheek d						
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System	N/A	N/A	N/A			
	Resements						
	2) Upper floors	30 a/c per hour	N/A	N/A			
	Fire Extinguishers	12 a/c per hour	Exhaust Fan	MR			
	1) Total numbers						
	2) Types	101	9 Nos.	MR			
	3) ISI marking	ISI Marked	ABC, Co2	MR			
	) marking		Yes	MR			

6.	First-Aid Hose Reel					
	1) Total number of each floor	01	D 1 1			
	2) Length of hose reel hose	30 m	Provided	MR		
7	3) Nozzle diameter	-	Provided	MR MR		
7.	Automatic Fire Detection & Alarming System- Not required					
	1) Type of detectors					
	2) Location of main panel	N/A N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of nower	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	N/A	N/A		
9.	Public Address System		Provided	MR		
10.	Automatic Sprinkler System	N/A	N/A	N/A		
	1) Basement					
	2) Upper floors	N/A	N/A	NT/A		
	3) Sprinkler above 6.1	Required	Provided	N/A MD		
11.	3) Sprinkler above false ceiling	N/A	N/A	MR		
	Internal Hydrants		17/11	N/A		
	1) Size of riser/down-comer	100 mm	Provided	100		
	2) Number of hydrants per floor	01	01	MR		
2.	3) Hose box	01	01	MR		
4.	Yard Hydrants		O1	MR		
	1) Total number of hydrants	N/A	N/A	N/A		
3.	2) Hose box	N/A	N/A	N/A		
J.	Pumping Arrangement	***	IVA	N/A		
-	1) Ground level					
+	a) Discharge of main pump	N/A	N/A	27/4		
•	b) Head of main pump	N/A	N/A	N/A		
-	c) Number of main pump	N/A	N/A	N/A		
-	d) Jockey pump out put	N/A	N/A	N/A		
-	e) Jockey pump head	N/A	N/A	N/A		
-	f) Stand by pump output	N/A	N/A	N/A		
-	g) Stand by pump head	N/A	N/A	N/A		
-	h) Auto starting/Manual stopping	N/A	N/A	N/A		
-	2) Terrace level		IVA	N/A		
-	a) Discharge of pump	450Lpm	Provided	MD		
	b) Head of pump	35 m	Provided	MR		
-	c) Power supply d) Auto starting of pump	Required	Provided	MR		
. (		Required	Provided	MR		
	Captive Water Storage for Fire Fighting MR					
	Under ground tank capacity     Draw-off connection	N/A	N/A	NIA		
		N/A	N/A	N/A N/A		
· /	b) Fire service inlet	N/A	N/A			
	c) Access to tank	N/A	N/A	N/A		
F	d) Over head tank capacity	5,000 ltrs.	Provided	N/A		
	xit Signage.	Required .	Provided	MR		
P	rovision of Lifts.	de .	- 10 Fided	MR		
	a) Pressurization of lift shaft	N/A	NI/A			
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
		IN/A	N/A	N/A		

17.	Stand by Power Supply	Required	Provided D.G. Sets	MR		
.8.	Refuge Area					
•	Total area	N/A	N/A	N/A		
-	location	N/A	N/A	N/A		
19.	Fire Control Room					
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risk, if any:					

The fire protection system provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2012/2288 Dated:- 26/06/2012 and renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended. Accordingly DFA is put up for perusal and sign, please.

Signature of the inspecting officer

Name:- D.B. Mukherjee.

Designation :- Assistant Divisional Officer(BCP)

fr / 3/1/1

DO South

15/11/14

Chafeali finn

C pout up for