GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. 66/DFS/015/School/2014/NOZ/1485

Dated: 28/11/1

FIRE SAFETY CERTIFICATE

Certified that the Rajkiya Sarvodaya Kanya Vidyalaya at Pkt.B,Mayur Vihar -11, Delhi-91, owned/occupied by, Rajkiya Sarvodaya Kanya Vidyalaya, comprised of ground floor only was issued Fire Safety Certificate vide letter no. No.F.6/DFS/MS/School/2011/2867 dated 04.11.2011.The school building was re-inspected by the officer concerned of this department on 22.11.2014 in the presence of Smt. Gomti Devi (Vice-Principal) of school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular no.F.16/Estate/CC/FS/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and found that the building is fit for occupancy class B "Educational Building" with effect from A. J. J. J. J. J. J. for a period of three years, subject to conditions printed overleaf.

Issued on28////____ at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Ph.011-23414333

Oceopy W

To,

The Vice-Principal
Rajkiya Sarvodaya Kanya Vidyalaya
Pkt.B,Mayur Vihar -11, Delhi-91
Copy to:-

- 1.The Dy.Director of Education D-Block,Anad Vihar,Delhi.
- 2.The Principal Rajkiya Sarvodaya Bal Vidyalaya Pkt.B,Mayur Vihar -11, Delhi-91

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6 ."The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate,six months prior to its expiry"
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building: RSKV, Pkt.B,Mayur Vihar-11,Delhi-91.

2. Building is comprised of : Ground floor only

3. Type of Occupancy : Educational

4. Type of Case :Renewal

5. Details of Previous FSC :F.6/DFS/MS/School/2011/2867 dated

04.11.11

6. Fire Safety Circular No. : F.16/Estate/CC/FS/2011/3298 to 3398

dated 1.3.11

7. Date of Inspection :22.11.2014

8. Name of the Inspecting officers : DO Virendra Singh

9. Name and designation of

Officer from the building side : Smt. Gomti Devi (Vice-Principal).

10. Year of Construction :1995

11. Applicant's letter No : Dated 08.08.2014

NO.	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remarks		
1	Access to building					
	Road widthGate width	06 Mtrs.	06 Mtrs.	MR		
	Width of internal road	N/A	N/A	N/A		
2		N/A	N/A	N/A		
2	Number, Width, Type and Arrangem	ent of Exits	9			
	a. Number of Staircases					
	Upper Floor	N/A	N/A	N/A		
	Basement P Width of Chairman	N/A	N/A	N/A		
	B. Width of Staircases					
	Upper Floor	N/A	N/A	N/A		
	Basement Brotaction of aviits	N/A	N/A	N/A		
	c. Protection of exits					
	THE CHECK GOOT	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	N/A	N/A	N/A		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	1.0 Mtrs	1.0 Mtrs	MR		
	Compartmentation.			1411		
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A		
5.	Fire Extinguishers					
	 Total numbers 	15 Nos.	17 Nos.	MR		
	 Types 	ABC & Co2		MR		
	 IS marking 	ISI marked	ISI marked	MR		

6	First-aid-Hose Reels.						
	Total numbers of each floor	N/A	N/A	N/A			
****	 Length of hose reel hose 	N/A	NI/A				
	 Nozzle diameter 		N/A	N/A			
		N/A	N/A	N/A			
7	Automatic fire detection and alarming system.						
* *	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public address System.	N/A	N/A	N/A			
0	Automatic Sprinkler System.	N/A	N/A	N/A			
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	 sprinkler above false ceiling 	N/A	N/A	N/A			
11	Internal Hydrants	N/A	N/A	N/A			
	size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
2	Yard Hydrants.	N/A	N/A	N/A			
	 Total number of hydrants 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
3	Pumping Arrangements.	N/A	N/A	N/A			
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual	N/A	N/A	N/A			
	stopping Pump House Access	NI/A	NI/A	11/0			
	Terrace Level	N/A N/A	N/A N/A	N/A			
	Discharge of pump			N/A			
	Head of the Pump	N/A	N/A	N/A			
	Power supply	N/A N/A	N/A N/A	N/A N/A			
-							
	Auto Starting of pump	N/A	N/A	N/A			
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
	 Underground tank capacity 	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	 Overhead Tank capacity 	N/A	N/A	- N/A			
5	Exit Signage.	N/A	N/A	· N/A			

1 ,

N	110
1	'

16	Provision of Lifts.	N/A	N/A	N/A
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	 Firemen's grounding switch 	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	 Total area 	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	 Detector system panel 	N/A	N/A	N/A
	 Flow switch panel 	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F.6/DFS/MS/School/2011/2867 Dated 04.11.11 renewal under the circular no.

F.16/Estate/CC/FS/2011/3298 to 3398 dated 1.3.11 is recommended

Submitted please.

Signature of the Inspecting Officer Name:-Virendra Singh Designation:-DO (ED)

DCFO(NDZ)

Lang