

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/School/2014/52/11597

Dated: 17/12/14

FIRE SAFETY CERTIFICATE

Certified that the **Golden Valley Senior Secondary Public School**, A-161, Todarmal Colony, Najafgarh, New Delhi -110043 has two blocks, each block is comprised of ground floor plus two upper floors was issued NOC by this department vide letter F.6/DFS/MS/2011/799 dated 02.05.2011. The School building was re-inspected by the officer concerned of this department on 27.11.2014 in the presence of Sh. Ram Shakal (Security Guard) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on.....17/12/14..... at New Delhi.


(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

Copy to:-

1. The Manager,
Golden Valley Senior Secondary Public School,
A-161, Todarmal Colony, Najafgarh, New Delhi -110043.
2. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/G

Two Blocks Senior Students Block (SSB) & Junior Students Block (JSB) comprised of Ground Plus Two Upper Floors (Golden Valley Senior Secondary Public School, A-161, Todarmal Colony, Najafgarh, New Delhi 110043)

INSPECTION REPORT

1. Name & address of the building : Golden Valley Senior Secondary Public School, A-161, Todarmal Colony, Najafgarh, New Delhi -110043.
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/2011/799 dated 02.05.2011
5. Fire Safety directives letter No : N/A
6. Date of inspection : 27.11.2014
7. Name of Inspecting Officer : A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Ram Shakal (Security Guard)
9. Year of Construction : 1997-1998
10. Applicant's letter No. : FSC/GVSSPS/2014-215/11 dated 10.11.2014.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	<p>Accessible</p> <p style="text-align: center;">—</p> <p style="text-align: center;">—</p>	<p>4.8 mtrs</p> <p>3.7 & 3.5 mtrs</p> <p style="text-align: center;">—</p>	<p>M/R, Old Case</p> <p style="text-align: center;">—</p> <p style="text-align: center;">—</p>
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02 No. (SSB) & 01 No. (JSB)	02 No. (SSB) & 02 No. (JSB)	M/R
	• Basements	N/A	N/A	No basement
	b. Width of staircases			
	• Upper Floor	1.5mtrs.	1.5 & 1.4 m (SSB) & 1.2 & 0.9 m(JSB)	M/R, Old case
	• Basements	N/A	N/A	No basement
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace			
	e. Width of Corridor	—	02 No.'s (SSB) & 01 No. (JSB)	—
	f. Door Size	—	220 cms (SSB) & 345 cms (JSB)	N/A
		—	100 cms (Single door)	M/R (Students less than 45 in each Class room)
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A

Two Blocks Senior Students Block (SSB) & Junior Students Block (JSB) comprised of Ground Plus Two Upper Floors (Golden Valley Senior Secondary Public School, A-161, Todarmal Colony, Najafgarh, New Delhi 110043)

4.	Smoke Management System			
	• Basements	N/A	N/A	No basement
	• Upper floors	—	Natural ventilation	M/R
5.	Fire Extinguishers			
	• Total numbers	24 No's ABC/CO2 type ISI marked	Provided	M/R
	• Types		Provided	M/R
	• IS marking		ISI marked	M/R
6.	First-Aid Hose Reels			
	• Total numbers on each floor (Each Block)	one 30 mtrs 5 mm	Provided	M/R
	• Length of hose reel hose (Each Block)		Provided	M/R
	• Nozzle diameter (Each Block)		Provided	M/R
7.	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Ground Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A

Two Blocks Senior Students Block (SSB) & Junior Students Block (JSB) comprised of Ground Plus Two Upper Floors (Golden Valley Senior Secondary Public School, A-161, Todarmal Colony, Najafgarh, New Delhi 110043)

	<ul style="list-style-type: none"> ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/Manual Stopping 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	N/A	N/A
		450 LPM (02 No.'s)	Provided	M/R
		30 mtrs	Provided	M/R
		N/A	N/A	N/A
		N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		20000 ltrs	Provided	M/R
15.	Exit Signage.	Required	Provided	M/R
16.	Provision of Lifts.	No Lift		
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

Two Blocks Senior Students Block (SSB) & Junior Students Block (JSB) comprised of Ground Plus Two Upper Floors (Golden Valley Senior Secondary Public School, A-161, Todarmal Colony, Najafgarh, New Delhi 110043)

211

20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
-----	--	-----	-----	-----

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F.6/DFS/MS/2011/799 dated 02.05.2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note:- A letter of undertaking given by principal regarding the number of students in each class are less than 45 is placed at C-14.

Sandeep
03/12/14

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

