

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO.F6/DFS/MS/ 2014/52/1599

Dated: 17 / 12/14

FIRE SAFETY CERTIFICATE

Certified that M/s Carmann Auto Private Limited located at A-33, Mohan Cooperative Industrial Estate, Mathura Road, New Delhi was inspected by the officer concerned of this department on 10.12.2014 in presence of Mr. Sunil Tyagi, Project Manager of the building and found that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class (Industrial) with effect from 17/12/19 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/12/14 at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE Tel:- 011-23414333

Copy to: -

1. The Owner/Occupier, M/s Carmann Auto Private Limited,
A-33, Mohan Co-operative Industrial Estate, Mathura Road, New Delhi.

2. The Executive Engineer (Bldg.), MCD, Building Department, Civic Centre, Minto Road, New Delhi.

Conditions for the validity of fire safety certificate

a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.

b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.

c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.

d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:

M/s Carmann Auto Private Limited, A-33, M.C.I.E., Mathura

Road, New Delhi

2. Type of Occupancy

: Industrial

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No

: F6/DFS/MS/2008/1289 dated 05.05.2008

6. Date of inspection

: 10.12.2014

7. Name of the Inspecting Officers : M.K Chattopadhyay, ADO (M. Road)

8. Name and designation of officers

from the building side

: Mr. Sunil Tyagi, Project Manager

9. Year of Construction

: 2007-08

10. Applicant's letter No.

: nil dated 19-11-2014

S. No.	Franciscon and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	 Road width 	09 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	Width of internal road	Required	Provided	MR
2	Number, Width, Type & Arrangement	of Exits		2
	a. Number of staircases	-		-
	• Upper Floors	03	provided	MR
	Basements	03 + 02 ramps	Provided	MR
	b. Width of staircases	-	_	1711(
	• Upper Floors	1.5 mts each	Provided) (D)
	• Basements	1.5 mts each	Provided	MR
	c. Protection of exits			MR
	 Fire check door 	Required	- D	-
	 Pressurization 	N/A	Provided	MR
	e. No. of continuous staircases to terrace	03	N/A 03	N/A
	g. Width of Corridor			MR
	h. Door Size	1.5 mts	Provided	MR
	Compartmentation.	1.5 mts	Provided	MR

	Fire check door	Required	Provided	MR		
	 Sealing of electrical shafts 	Required	Provided	MR		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	 Fire Dampers 	N/A	N/A	N/A		
	Smoke Management System.					
	Basements	30 a/c per hour	Provided	MR		
	 Upper floors 	12 a/c per hour	N/A	N/A		
)	Fire Extinguishers					
	Total numbers	20	Provided	MR		
	• Types	ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
5	First-Aid Hose Reels.					
	Total numbers on each floor	02	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	 Nozzle diameter 	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	Required	Provided(Smoke)	MR		
	 Location of Main Panel 	Ground floor	Provided	MR		
	Location of Repeater Panel	Required at each floor	Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required at each floor	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Provided	MR		
11	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR		
	Number of hydrants per floor	02	Provided	MR		
	 Hose Box 	02	Provided	MR		

2	Yard Hydrants.		· · · · · · · · · · · · · · · · · · ·	
	 Total number of hydrants 	Required(04)	Provided	MR
	Hose Box	Required(04)	Provided	MR
3	Pumping Arrangements.			
	Ground Level			
	Discharge of main Pump	2280 LPM	Provided	MR
	Head of Main pump	60 mts	Provided	MR
	Number of main pumps	01	Provided	MR
	Jockey Pump out put	180 LPM	Provided	MR
	Jockey pump head	60 mts	Provided	MR
	Standby Pump out put	2280 LPM	Provided	MR
	Standby Pump Head	60 mts	Provided	MR
	Auto Starting/ Manual	Required	Provided	MR
	stopping	Required	Provided	MR
	Pump House AccessTerrace level	-	-	•
	Discharge of pump	900 LPM	Provided	MR
	➤ Head of the pump	60 mts	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	Underground tank capacity	1,00,000 lts	Provided	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20, 000 lts	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
ia -	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	Required	Provided	MR
à	Fireman's Grounding Switch	Required	Provided	MR

		Required	Provided	MR	
	Lift Signage	Required	Provided	MR	
7	Standby power supply				
8	Refuge Area.	N/A	N/A	N/A	
	> Total Area		N/A	N/A	
	> Location	N/A	IV/A		
9	Fire Control Room			- (5)	
	Detector System Panel	Required	Provided	MR	
	Flow Switch Panel	Required	Provided	MR	
		N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	14/11	100		
20	Special Fire Protection Systems for		Provided (02 ABC type fire extinguishers		
	Protection of special Risks, if any	Required	near electric panel)		
	The fire protection systems provided time of inspection. In view the substantial compliance of the system of the	ne minimum stand	ards on fire prevention	and fire safety	
req	In view the substantial compliance of the fire safety certificate under rule 35 of the Delhi Fire quired under the rules, it is recommended to grant fire safety certificate under rule 35 of the Delhi Fire				
Sei	rvice rules 2010.		, Tunas		
	DFA is put up for	or approval & signa	iture please.		
			1. 1. 1. 1.		

Signature of the Inspecting Officer
Name M.K.CHATTOPADHYAY
Designation: - Asstt. Div. Officer (M.Rd)

an Tempeduty