GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001

No. \$6/DF3/ms/school2014/52/1557

Dated:

11/12/14

FIRE SAFETY CERTIFICATE

Issued on at New Delhi by

(Dr.G.C.Misra)

Chief Fire Officer

T.No.011-23414333

To,

The Principal Sarvodaya Co-Ed. Senior Secondary School, Munirka Village, New Delhi-67.

Copy to:-.

The Director of Education Old Secretariat, Civil Lines, Delhi-52.

Conditions for the validity of fire safety certificate are overleaf:-

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate in form J, six month prior to its expiry.

	INSP	ECTION REPORT	,		1		
1. Na			ndary School Munic	dro Villago			
	Name & address of the building : Sarvodaya Co-Ed. Senior Secondary School, Munirka Village, New Delhi-110067.						
	uilding is comprised of : G+2(One Block) and G+1(One Block).						
	rpe of Occupancy : Education						
	rpe of Case : New.						
	etails of Previous NOC : Nil.						
o. FII	re Safety direction letter No : F.16/Est	ate/CC/Fire safety/2011	1/3298 to 3398				
7. Da	Dated- (te of Inspection : 27.11.14						
8. Na	me of the Inspecting Officers: : Vedpal (
9. Na	me and designation of Officer	(IDO)					
fro	om the building side : Sh. B.N	M.Panchal (Principal)					
	ear of Construction : 1989.	(=					
		ed 20.11.14.					
S.N	Minimum Standards on fire	Requirement	Provided at Site	Remarks	3		
)	prevention and fire safety as per		15	MR/NMF	3		
	circular no.3298-3398 Dated01.03.11.						
1	Access to building		I				
	Road width	6 m	6 m	MR			
	Gate width	N.A.	N.A.	N.A.			
	Width of internal road	N.A.	N.A.	N.A.			
2	Number, Width, Type and Arrangement of Exits.						
	a. Number of Staircases						
	Upper Floor	2nos.in each block	02nos.in each bl	block MR			
	Basement	N.A.	N.A.	N.			
	B. Width of Staircases		7.1		14.7.		
	Upper Floor	1.5 m(each)	1.36m,1.40m,1.6m&1.6m		MR		
	Basement	N.A.	N.A.		N.A.		
	c. Protection of exits	N.A.					
	Fire check door	N.A.	N.A.		N.A.		
	Pressurization	CONTRACTOR	N.A.		N.A.		
	e. No. of continuous staircases to	N.A.	N.A.		N.A.		
	terrace	1no.in each block	1no.in each block		MR		
	g. Width of Corridor	4.5	4.5		140		
	h. Door Size	1.5 m	1.5 m		MR		
}	Comportmentation	1 m	1m		MR		
)	Compartmentation	NI A	NI A	N			
	Fire check door	N.A.	N.A. N.A.				
	Sealing of electrical shafts	N.A.	N.A.				
	Fire rating of shaft door	N.A.	N.A. N.A.				
	Water curtain	N.A.	N.A.	N.A.			
				N.A.			
	Fire Dampers	N.A.	N.A.	N.A.			
1			N.A.	N.A.	-		
1	Fire Dampers		N.A.	N.A.			

Sarvodaya Co-Ed. Senior Secondary School, Munirka Village, New Delhi-67. Fire Extinguisher 5. 15 nos. MR Total numbers 14 nos. MR CO2 and ABC Type types CO₂ & ABC IS marking ISI marked MR ISI marked First-aid-Hose Reels. In G+3 Block only. 6 Total numbers of each floor 02nos. 02nos. MR. Length of hose reel hose MR. 30m 30m Nozzle diameter 5cm MR. 5cm 7 Automatic fire detection and alarming system. N.A. N.A. Type of detectors N.A. N.A. N.A. Location of main panel N.A. Location of repeater panel N.A. N.A. N.A. Alternate source of power N.A. N.A. N.A. Hooters N.A. N.A. N.A. N.A. 8 MOEFA N.A. N.A. N.A. 9 Public address System. N.A. N.A. 10 Automatic Sprinkler System. Basement N.A. N.A. N.A. upper floor N.A. N.A. N.A. stage of auditorium N.A. N.A. N.A. 11 Internal Hydrants size of down-comer N.A. 100mm N.A. Number of hydrants per floor in each N.A. 02nos. N.A. block N.A. N.A. 02nos. Hose Box 12 Yard Hydrants. Total number of hydrants N.A. N.A. N.A. Hose Box N.A. N.A. N.A. 13 Pumping Arrangements. Ground Level N.A. N.A. N.A. Discharge of main Pump N.A. N.A. N.A. Head of Main Pump N.A. N.A. N.A. Number of main pumps N.A. N.A. N.A. Jockey pump out put N.A. N.A. N.A. Jockey pump head N.A. N.A. N.A. Standby pump out put N.A. N.A. N.A. Standby pump Head N.A. N.A. N.A. Auto Starting /Manual N.A. N.A. N.A. stopping N.A. N.A. N.A. Pump House Access 01no. 02nos. MR. Terrace Level 450LPM 450LPM(Two) MR Discharge of pump 40m 40m(Each) MR Head of the Pump Required Provided MR Power supply Required Provided MR Auto Starting of pump

N

Sarvodaya Co-Ed. Senior Secondary School, Munirka Village, New Delhi-67.

14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	N.A.	NI A			
	Draw-off connection		N.A.	N.A.		
	Fire service inlet	N.A.	N.A.	N.A.		
	Access to tank	N.A.	N.A.	N.A.		
	Overhead Tank capacity	N.A.	N.A.	N.A.		
15	Exit Signage.	10000 liters	15000Ltrs.	MR		
16	Provision of Lifts.	Required	Provided	MR		
	Pressurization of Lift Shaft					
	Pressurization of Lift lobby	N.A.	N.A.	N.A.		
	Communication in lift car	N.A.	N.A.	N.A.		
	Firemen's grounding switch	N.A.	N.A.	N.A.		
	Lift Signage	N.A.	N.A.	N.A.		
17		N.A.	N.A.			
18	Standby power supply	N.A.	N.A.	N.A.		
18	Refuge Area.		IV.A.	N.A.		
	Total area Location	N.A.	N.A.	NI A		
		N.A.		N.A.		
19	Fire Control Room	14.74.	N.A.	N.A.		
	Detector system panel	N.A.	NI A			
	Flow switch panel	N.A.	N.A.	N.A.		
	PA system panel		N.A.	N.A.		
	Batter backup	N.A.	N.A.	N.A.		
	Building Floor Plans	N.A.	N.A.	N.A.		
20	Special Fire Protection systems for	N.A.	N.A.	N.A.		
	protection of special Risks, if any:	N.A.	N.A.	N.A.		

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules

2010.

sou t

Signature of the Inspecting Officer

Name: Vedpal Designation: ADO