GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, Tel: 011-23414333

No.F6/MS/DFS/GH/2014/52/1638

Dated: 23/12/14

FIRE SAFETY CERTIFICATE

Issued - 13/12-/14--at New Delhi by

(Dr. G.C. Misra)
Chief Fire Officer

Copy to:-

1. The Addl. Commissioner of Police (Lic.), First Floor, Police Station Defense Colony, New Delhi- 110049.

2. Mr. K.K.Sehrawat(propriter) A-217,KH NO-416, Road No-6 Mahipalpur Extension,New Delhi- 110037

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of NBC

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1.Name & address of the building:- Hotel Ambrosia, A- 217,KH No. 416,Road No-6,VPO-Mahipalpur New Delhi - 110037
- 2. Type of occupancy:- Residential, Group-A, Lodging or Rooming (Guest House)
- 4. Details of previous NOC:- Nil
- 5. Fire safety directives No.- No
- 6. Date of inspection:- 16/12/2014
- 7. Name of the inspecting officer:- D.B.Mukherjee A.D.O.(BCP)
- 8. Name & designation of officer From the building side: Mr. K.K. Sehrawat (Owner) 9. Year of construction:- 1997/18
- 10. Applicant's letter No:- Nil Dated: 8/12/2014

oper Floors.
)

No	Minimum Standards on fire Prevention and fire safety U/R 33 Access to Building	BBL/NBC Requirement	Provided at site	Remarks MR/NMR
	1) Road width			
	2) Gate width	9m	Provided	
		Required		MR
2.	3)Width of internal road	1	Approachable	MR
2.	Number, Width Type & Arrangement A. Number of staircases	of Evite	N/A	N/A
-		OI EXILS		- 11.2
1	1. Upper floors	0.1		
-	2. Basements	01	01no.	MR
-	B. Width of staircase	02	01 ramp,01no	MR
	1. Upper floors		1)	IVIK
	2. Basements	1.25 m	1.35mtrs	MD
		1.25 m	1.41m & 3.60m	MR
	C. Protection of exits		(ramp)	MR
	1. Fire check door			
2	2. Pressurization	Required	Provided	MD
I	D. No. of continuous staircase to terrace	N/A	N/A	MR
E	E. Width of corridor	Required	01	N/A
F	F. Door size	N/A	N/A	MR
	Compartmentation	N/A	N/A N/A	N/A
1) Fine al. 1.1		IN/A	N/A
2) Fire check door	N/A		
2)) Sealing of electrical shafts	N/A	N/A	N/A
3)	Fire rating of shaft door	N/A	N/A	N/A
4)	Water curtain	N/A	N/A	N/A
(3)	Fire Dampers	N/A	N/A	N/A
Sn	noke Management System	INA	N/A	N/A
1)	Basements	30 0/0 == 1		
(2)	Upper floors	30 a/c per hour	Exhaust Fans	MR
Fi	re Extinguishers	12 a/c per hour	Natural	MR
1)	Total numbers			1411/
2)	Types	ICLA	Provided 20 nos.	MR
3) I	ISI marking	ISI Marked	ABC, Co2	
			Yes	MR

6.	- mot that Host Neel					
	1) Total number of each floor	Required 01 no.	Provided			
	2) Length of hose reel hose	30 m		MR		
	3) Nozzle diameter	5 mm	Provided	MR		
7.	Automatic Fire Detection & Alanmin	S IIIII	Provided	MR		
× .	Automatic Fire Detection & Alarming System 1) Type of detectors N/A N/A N/A					
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Not Required	Provided			
10.	Automotic Services	N/A	N/A	N/A		
10.	Automatic Sprinkler System 1) Basement			11/11		
		Required	Provided	MR		
	2) Upper floors	N/A	N/A	N/A		
11	3) Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants -			IV/A		
	1) Size of riser/down-comer	100 mm.	N/A	NI/A		
	2) Number of hydrants per floor	01	N/A	N/A		
10	3) Hose box	01	N/A	N/A		
12.	Yard Hydrants		1 1/11	N/A		
	1) Total number of hydrants	N/A	N/A			
	2) Hose box	N/A	N/A N/A	N/A		
3.	Pumping Arrangement		IN/A	N/A		
-	1) Ground level	N/A	N/A	N/A		
-	a) Discharge of main pump	N/A	N/A	N/A N/A		
-	b) Head of main pump	N/A	N/A	N/A N/A		
-	c) Number of main pump	N/A	N/A	N/A N/A		
-	d) Jockey pump out put	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A		
_	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A N/A	N/A		
	h) Auto starting/Manual stopping	N/A	N/A N/A	N/A		
	2)Terrace level	1 1/1 1	IN/A	N/A		
	a) Discharge of pump	900 LPM	Dans.' 1 1			
	b) Head of pump	40m	Provided	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
.Car	ptive Water Storage for Fire Fighting	Required	Provided	MR		
	Under ground tank capacity	NI/A				
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	N/A	N/A	N/A		
E	Exit Signage.	10,000 Ltrs.	Provided.	MR		
	Provision of Lifts.	Required	Provided	MR		
1						
		N/A	N/A	N/A		
-	b) Pressurization of lift lobby	N/A	N/A	N/A		
-	c) Communication in lift car	N/A	N/A	N/A		
-	d) Fireman's switch	N/A	N/A	N/A		
-	e) Lift signage	Required	provided	MR		
St	tand by Power Supply	Required	Provided DG Set			
R	efuge Area	N/A	N/A	MR		
To	otal area location	N/A	N/A N/A	N/A		
		- 1/ A A	IN/A	N/A		

19.	Fire Control Room	N/A	N/A	
	a) Detector system panel	N/A		N/A
	b) Flow switch panel		N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for P	N/A	N/A	N/A
	Special Fire Protection System for Protection of special Risk, if any:		N/A	

The fire protection system provided in the building were checked and found non functional at the time of inspection. The shortcomings issued vide letter no.F6/DFS/MS/GH/2014/2327 dt. 01/10/2014 have been rectified. In view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules 35 of the Delhi Fire Service Rules 2010 issuance of FSC is recommended and accordingly DFA is put up for perusal and signature pl.

Signature of the inspecting officer Name: - D.B.Mukherjee. Designation:- Assistant Divisional Officer (BCP)

4