GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE; CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/GH/2014/SZ/ 1626

Dated: 23 /12 /14

FIRE SAFETY CERTIFICATE

Certified that the R.K. Residency located at BE-404, Hari Nagar, New Delhi110064 is comprised of stilt plus four upper floors, having parking & in house kitchen at the Stilt Floor, 06 Guest Rooms on First Floor, 06 Guest Rooms on Second Floor & 03 Guest Rooms at Third Floor and Half Portion of Third Floor & Fourth Floor are used by owner as residence. The guest house building owned/occupied by the M/S R.K. Residency was inspected by the officers concerned of this department on 10.10.2014. in the presence of Sh. Anshu Bharti (Proprietor) and found that management have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Residential Guest House" (15 guest rooms only at First, Second and Partial Third Floor) w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 as printed overleaf.

Issued on 2.3 1.2 14 at New Delhi.

(Dr. G.C.Misra)
Chief Fire Officer
Delhi Fire Service

Copy to:-

- Sh. Anshu Bharti (Proprietor)
 R.K. Residency, BE-404, Hari Nagar, New Delhi110064
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, Defence Colony Police Station, New Delhi. (16463-467/Addl.C.P./Lic.(H) dated 11.04.2014)

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of Stilt plus Four upper floors but Guest House is at First, Second and half (R.K. Residency, BE-404, Hari Nagar, New Delhi110064)

INSPECTION REPORT

1. Name & address of the building:

R.K. Residency, BE-404, Hari Nagar, New Delhi110064

2. Type of Occupancy

Residential

3. Type of Case

New

4. Details of Previous NOC

Nil

5. Fire Safety directives letter No

Nil

6. Date of inspection

10.10.2014.

7. Name of Inspecting Officer

D.O. S.K. Tomar and A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side

Sh. Anshu Bharti (Proprietor)

9. Year of Construction

2006.

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | NBC/ BBL | Provided at | Remarks | |
|--------|---|------------------------|--------------------|----------------|--|
| 1. | Access to building | Requirement | site | MR/NMR | |
| | Road width Gate width Width of internal road | 06 mtrs. N/A N/A | 06 mtrs N/A | M/R N/A | |
| 2. | Number, Width, Type & Arrangement of Exits | IN/A | N/A | N/A | |
| | Number of staircases | | | | |
| | Upper Floors Basements | 01 No's. | 01 No's | M/R | |
| | Width of staircases | N/A | N/A | No Basement | |
| | Upper Floor | | | | |
| | Brotaction of a transfer of a | 90 cms | 92 cms | M/R | |
| | Protection of exits Fire check door | N/A | N/A | No Basement | |
| | Pressurization | | | | |
| | | N/A | N/A | No Basement | |
| | d. No. of continuous staircases to | N/A | N/A | No Basement | |
| | terrace | _ | · * | | |
| | e. Width of Corridor | One | One | M/R | |
| | f. Door Size | 1.5 mtrs | 3 mtrs | M/R | |
| | Composition | | 87cms x 200 cms | M/R, Old Bldg. | |
| | Compartmentation | | | | |
| 1 | Fire check door Sealing of electrical shafts | N/A | N/A | N/A | |
| | Fire Rating of shaft door | N/A | N/A | N/A | |
| 1 | Water Curtain | N/A | N/A | N/A | |
| , 1 | Fire Dampers | N/A | N/A | N/A | |
| 9 | Smoke Management System | N/A | N/A | N/A | |
| | | | | | |
| | Basements | N/A | N/A | No Basement | |

4/2

Building is comprised of Stilt plus Four upper floors but Guest House is at First, Second and half Third Floor (R.K. Residency, BE-404, Hari Nagar, New Delhi110064)

| | Third Floor (R.K. Residency, BE | N/A | Natural | M/R | | | | |
|----------|--|-----------------------|-------------|--------|--|--|--|--|
| | Upper floors | IN/A | Ventilation | 101710 | | | | |
| | | | Ventuation | | | | | |
| 5. | Fire Extinguishers | Fight no/o | Provided | M/R | | | | |
| | Total numbers | Eight no's ABC/CO2 | Provided | M/R | | | | |
| | Types | ABC/CO2 | | | | | | |
| | IS marking | ISI marked | ISI marked | M/R | | | | |
| 6. | First-Aid Hose Reels | | | | | | | |
| | Total numbers on each floor | One | Provided | M/R | | | | |
| | Length of hose reel hose | 30 mtrs | Provided | M/R | | | | |
| | Nozzle diameter | 5 mm | Provided | M/R | | | | |
| 7. | Automatic fire detection and alarming system | | | | | | | |
| - | Type of detectors | N/A | N/A | N/A | | | | |
| | Location of Main Panel | N/A | N/A | N/A | | | | |
| | Location of Repeater Panel | N/A | N/A | N/A | | | | |
| | Alternate source of power | N/A | N/A | N/A | | | | |
| | Hooters' Location | N/A | N/A | N/A | | | | |
| 3. | MOEFA | N/A | N/A | N/A | | | | |
|).). | Public Address System | N/A | N/A | N/A | | | | |
| | Automatic Sprinkler System | | | | | | | |
| 10. | Automatic Sprinkier System | | | | | | | |
| | Basement | N/A | N/A | N/A | | | | |
| | Ground Floor | N/A | N/A | N/A | | | | |
| | Sprinkler above false ceiling | N/A | N/A | N/A | | | | |
| 11. | Internal Hydrants | | | | | | | |
| | Size of riser/down-comer | N/A | N/A | N/A | | | | |
| | Number of hydrants per floor | N/A | N/A | N/A | | | | |
| | Hose Box | N/A | N/A | N/A | | | | |
| 12. | Vard Hydrants | | | | | | | |
| 12. | Total number of hydrants | N/A | N/A | N/A | | | | |
| | Hose Box | N/A | N/A | N/A | | | | |
| 13. | Pumping Arrangements | | | | | | | |
| | Ground Level | 21/0 | NI/A | N/A | | | | |
| | Discharge of main Pump | N/A | N/A | | | | | |
| | Head of Main pump | N/A | N/A | N/A | | | | |
| | Number of main pumps | N/A | N/A | N/A | | | | |
| | Jockey Pump out put | N/A | N/A | N/A | | | | |
| | Jockey pump head | N/A | N/A | N/A | | | | |
| | Standby Pump out put | N/A | N/A | N/A | | | | |
| | Standby Pump Head | N/A | N/A | N/A | | | | |
| | Auto Starting/Manual Stopping | N/A | N/A | N/A | | | | |

Building is comprised of Stilt plus Four upper floors but Guest House is at First, Second and half Third Floor (R.K. Residency, BE-404, Hari Nagar, New Delhi110064)

N/A

N/A

N/A

| 149 | (-with restricting, BL-4 | | New Deinil 10064) | | | |
|---------|--|-----------|--|------|--|--|
| | Pump House Access | N/A | N/A | N/A | | |
| | Terrace level | | | | | |
| | Discharge of pump | 450 LPM | Provided | M/R | | |
| | Head of the pump | 40 mtrs | Provided | M/R | | |
| | Power Supply | Required | Provided | M/R | | |
| | Auto Starting of pump | Required | Provided | M/R | | |
| 14. | Captive Water Storage for fire fighting | | | | | |
| | Underground tank capacity | N/A | N/A | NI/A | | |
| | Draw-off connection | N/A | | N/A | | |
| | Fire service inlet | | N/A | N/A | | |
| | Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | N/A | N/A | N/A | | |
| | | 5000 ltrs | Provided | M/R | | |
| 15. | Exit Signage. | Required | Provided | M/R | | |
| 16. | Provision of Lifts. | | | | | |
| | Pressurization of Lift Shaft | N/A | N/A | BI/A | | |
| | Pressurization of Lift lobby | | | N/A | | |
| | Communication In lift Car | N/A | N/A | N/A | | |
| | Fireman's Grounding Switch | N/A | N/A | N/A | | |
| | Lift Signage | Required | Provided | M/R | | |
| | | Required | Provided | M/R | | |
| 17. 🐧 | Standby power supply | Required | Provided | M/R | | |
| 10 | | | | | | |
| 18. | Refuge Area. | * | | | | |
| | Total Area | N/A | N/A | N/A | | |
| 1 40-11 | Cation | N/A | 4 1 | | | |
| | | IN/ A | N/A | N/A | | |
| 19. | Fire Control Room | | | | | |
| | Detector System Panel | N/A | N/A | N/A | | |
| | Flow Switch Panel PA System Panel | N/A | N/A | N/A | | |
| | L System Famer | N/A | N/A | N/A | | |
| | Battery backup | N/A | N/A | N/A | | |
| | | N/A | | | | |
| | Building Floor Plans | IV/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| | Special Fire Protection System for Protection of | | the state of the s | | | |

215

Building is comprised of Stilt plus Four upper floors but Guest House is at First, Second and half Third Floor (R.K. Residency, BE-404, Hari Nagar, New Delhi110064)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note: - The undertaking is placed on C-12 given by the Proprietor, regarding use of two & a half storey as guest house and the remaining portion as residence and year of guest house building construction is 2006.

Signature of Inspecting Officer

Name: - S.K. Tomar

Designation:- Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer