GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, Tel: 011-23414333

No.F6/MS/DFS/2014/ 52/1638

Dated: 23/12/14

FIRE SAFETY CERTIFICATE

Certified that the Staff Quarter of Lok Sabha Secretariat located at Sector-2, R.K.Puram, New Delhi, building complex comprises of 07 nos. of high rise blocks and a separate basement. Type-II and III blocks are comprised of stilt, ground and eight upper floors, Type-IV blocks are comprised of ground and 8 upper floors and Type-V blocks are comprised of stilt/ground and 8 upper floors. The premises was re-inspected by the officer concerned of this department on 17/12/2014 in the presence of Mr.H.S.Meena (Executive Engineer Civil) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential (Apartment) with effect from .. 2.3. 1.12. 1.4. a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -23 /12-/14-at New Delhi by.

(Dr. G.C. Misra) **Chief Fire Officer**

97c 6/23/12/14 ADO (BID)

Copy to:-

Mr. Munish Kumar Rewari Deputy Secretary Lok Sabha Secretariat, Parliament House Annexe New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of BBL/NBC.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Staff Quarters for Lok Sabha Secretariat, Sec.-II, R.K.Puram,

New Delhi

2. Type of Occupancy : Residential (Apartment)

3. Type of Case : New4. Details of previous NOC : N/A

5. Fire safety directives letter No: F6/MS/DFS/BP/2010/2154 dated 20-07-2010

6. Date of inspection : 17.12.2014

7. Name of the Inspecting Officers: M.K.Chattopadhyay A.D.O(M.Rd.) & D.B.Mukherjee, A.D.O(BCP)

8. Name and designation of officers

from the building side : Mr. Chaman Lal, Executive Engg, (Elct.), Mr.H.S. Meena, Executive

Engg.(Civil) C.P.W.D and Technical Officials.

9. Year of Construction : 2014

10. Applicant's letter No. : Letter no.12/1/2009-GW dated: 13/11/2014

Residential Building complex comprises of 07 nos. of high rise blocks and a separate basement. Type-II and III blocks are comprised of stilt, ground and eight upper floors, Type-IV blocks are comprised of ground and 8 upper floors and Type-V blocks are comprised of stilt/ground and 8 upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/	NBC Requirement	Provided at site	Remarks MR/NMR				
1	Access to building							
	 Road width 	9 Meters	Provided	MR				
	Gate width	5 Meters	Provided	MR				
	 Width of internal road 	6 Meters	Provided	MR				
2	Number, width, type & arrangement of exits							
	a. Number of staircases							
	 Upper Floors 	02 in each block	Provided	MR				
	Basements	03 staircase and 01 ramp	Provided	MR				
	b. Width of staircases		* :					
	 Upper Floors Basements c. Protection of exits Fire check door Pressurization d. No. of continuous staircases 	1.50 mtrs. 1.50 Meter each Required N/A 02 nos. at each block	Type- II 1.36m & 1.37m Type -III 1.50m & 1.50m Type -IV A 1.50m & 1.50m Type -IV B 1.50m & 1.48m Type -V A 1.40m & 1.36m Type-V B 1.40m & 1.40m Type- V C 1.39m & 1.40m 1.53m each & 1 ramp 6m Provided N/A Provided	MR & treated as fate accomplish MR MR MR N/A MR				
	to terrace	Required	Provided	MR				
	e. Width of Corridor f. Door Size	Required	Provided	MR				
3	Compartmentation	MI						
	 Fire check door Sealing of electrical sha Fire Rating of shaft doo 	r Required 2 hrs.	Provided Provided Provided	MR MR MR				
	Water CurtainFire Dampers	N/A N/A	N/A N/A	N/A N/A				

NIZ

		MIZ				
4	Smoke Management System					
	Basements	30 a/c per hour	Provided	MR		
	Upper floors	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	20 nos. in each block	Provided	MR		
	• Types	CO ₂ , ABC	Provided	MR		
	IS marking	ISI marked				
6	First-Aid Hose Reels					
	Total numbers at each floor	02 nos.at each block	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	20 mm	Provided	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	Smoke	Provided at basement	MR		
	 Location of Main Panel 	Pump House	Provided	MR		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	Entire basement area	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System	Required	Provided	MR		
10	Automatic Sprinkler System					
	Basement	Required	Provided	MR		
	Upper Floor	N/A	N/A	N/A		
	 Sprinkler above false 	N/A	N/A	N/A		
1.1	ceiling					
11	Internal Hydrants Size of riser/down-comer	100 mm	Provided	MR		
	• Size of riser/down-corner	02 Nos. at each block.	Provided	MR		
	Number of hydrants	02 No.	Provided	MR		
	Number of hydrantsHose Box	0.2140.	Tiovided	IVIIC		
12	Yard Hydrants					
12	Total number of hydrants	15 nos.	Provided	MR		
		15 nos.	Provided	MR		
13	Hose Box Pumping Arrangements	15 1105.	110,1000			
1 3	Ground Level					
	Ground LevelDischarge of main pump	2850 LPM	Provided	MR		
	> Head of main pump	70 mts	Provided	MR		
	Number of main pumps	01No.	Provided	MR		
	> Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	2850 LPM	Provided	MR		
	Standby pump Head	70 mts	Provided	MR		
	Auto starting/ manual stopping	Required	Provided	MR		
	Pump house access	Required	Provided	MR		
	Terrace level			1		
	Discharge of pump	900 LPM	Provided	MR		
	> Head of the pump	Required	Provided	MR		
	Power SupplyAuto Starting of Pump	Required Required	Provided Provided	MR MR		
				A A D		

14	Captive Water Storage for firefighting					
	 Underground tank capacity 	2, 00, 000 lts	Provided	MR		
	Draw-off connection	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	25, 000 lts. in every	Provided	MR		
15	Exit Signage	block Required	Provided	MR		
16	Provision of Lifts					
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	Required	Provided	MR		
	• Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
7	Standby power supply	Required	Provided	MR		
8	Refuge Area					
	> Total Area	Required	Type-II 14.23 sqm Type-III 11.52sqm Type-IV A 15.58 sqm Type-IV B 15.58 sqm Type V A 12.96 sqm Type V B 12.96 sqm Type V C 12.96 sqm	MR		
	Location	Required	6 th & 8 th floor	MR		
9	Fire Control Room					
	Detector System Panel	Required	Provided	MR		
	Flow Switch Panel	Required	Provided	MR		
	PA System Panel	Required	Provided	MR		
	Battery backup	Required	Provided	MR		
	Building Floor Plans	N/A	N/A	N/A		
0.0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The shortcoming given by the department vide letter no F6/DFS/MS/2014/2797 dated 10/12/14 have been rectified.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010 Accordingly DFA is put up for perusal and signature pl.

Signature of the Inspecting Officer

Name: M.K.Chattopadhyay

Designation:-Asstt. Div. Officer (M. Rd.)

Freder

Signature of the Inspecting Officer Name:D.B.Mukherjee

Designation :- Asstt. Div. Officer (BCP