GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE; NEW DELHI-110001

No. F6/OFS/OS/ EH/2019/W2/1624

Dated: 23 /12 /2014

FIRE SAFETY CERTIFICATE

Certified that the M/s Masabaa Thre Treasury (a unit of VSR Foods India) at premises No. 37, 2nd & 3rd floor, Club Road Punjabi Bagh, New Delhi, comprised of B+G+3 upper floors owned/occupied by M/s Masabaa Thre Treasury have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 28.09.2014 in the presence of Mr. Manoj and that the building/premises is fit for occupancy Assembly with effect from 23/12/19... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Following fire safety directives must be adhered to:-

1) All the means of escape shall be kept free of all type of obstruction all the time.

2) All the employees shall be acquainted with the use and maintenance of a fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

All the fire fighting equipment shall be maintained in perfect working condition all the time and lapse rendering non-functional of fire safety measures, management shall be responsible.

Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.

Basement shall be used only as per NBC part-IV.

This NOC may not be treated in any case for regularizations of unauthorized construction, if any.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs. Delhigovt. Nic.in

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

Issued on 23 /12/14 at New Delhi by

(A.K. Sharma) Director

olc

Delhi Fire Service

Copy to:

1. M/s Masabaa Thre Treasury (a unit of VSR Foods India) · Premises No. 37, 2nd & 3rd floor, Club Road Punjabi Bagh, New Delhi

2. Dy. Health Officer West Zone, Vishal Enclave, New Delhi.

INSPECTION REPORT

: M/s Masabaa Thre Treasury (a unit of VSR 1. Name & address of the building

Nil

Foods India) at premises No. 37, 2nd & 3rd floor, Club Road Punjabi Bagh, New Delhi

2. Type of Occupancy Assembly

3. Type of Case New

4. Details of previous NOC Nil

Fire Safety directives letter No. Date of inspection 6. 28-09-2014

Name of the Inspecting Officers 7. Sunil Chawdhary DO (M.N.)

8. Name and designation of officers

5.

From the building side Mr. Manoj Sharma

9. Year of Construction old construction (2008-2009) As per property tax receipt

S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
Martinida Pinar Andrews	Road width	06 m	Provided	M/R		
	Gate width	required	Provided	M/R		
	Width of internal road	N.R.	N.R.	N.R.		
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	2	2	M.R.		
	Basement	2	2	M.R.		
	b. Width of staircases					
	Upper Floors	1.5 m & 1 m	Provided	M/R		
	Basement	2 m	Provided	M/R		
	c. Protection of exits					
	Fire check door	N.R.	N.R.	N.R.		
	Pressurization	N.R.	N.R.	N.R.		
	d. No. of continuous staircases to terrace					
	e. Width of Corridor	required	Halls only	M.R.		
	f. Door size	2 mtr	Provided	M.R.		
3.	Compartmentation.					
	Fire check door	N.R.	N.R.	N.R.		
	• Sealing of electrical shafts	Required	N.A.	N.A.		
	Fire Rating of shaft door	Required	N.A.	N.A.		
	• Water Curtain	N.A.	N.A.	N.A.		
	• Fire Dampers	N.A.	N.A.	N.A.		
4.	Smoke Management System.					
	Basements	Required	Provided	M.R.		
	• Upper floors	Required	Provided	M.R.		
5.	Fire Extinguishers					
	Total numbers	08	12 Provided	M.R		
	Types	ABC, CO ₂ type	Provided	M.R		
	IS marking	ISI marked	Provided	M.R		

N.R.
N.R.
N.R.
N.R.
NA D
M.R
N.R.
N.A.
N.A.
N.R.
N.R.
N.R.
N.R.
N.R.
N.R.
N.A.
M.R.
M.R.
M.R.
IVI.K.
N.R.
N.R.
N.R.
The same of the sa

		3/2/		
15	Exit Signage.	required	Provided	M.R.
16.	Provision of Lifts			
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch 	N.A.	N.A. N.A. N.A.	N A. N.A. N.A.
	Lift Signage	N.A.	N.A.	N.A.
17. 18.	Standby power supply	Required	Provided	M.R
10.	Refuge Area			
	➤ Total Area	N,A	N.A.	N.A
	➤ Location	N,A	N.A	N.A
19.	Fire Control Room			
	 Detector System Panel 	N.A.	N.A.	N.A.
	Flow Switch Panel	N.A.	N.A.	N.A.
	PA system Panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor plans	N.A.	N.A.	N.A.
20.	Special Fire Protection Systems for Protection of	N.A	N.A	N.A

The fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/.

Signature of the Inspection Officer

Signature of the Inspection Officer

Name Sunil Chawdhary

special Risks, if any:

Name

Designation DO (W)

Designation