GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

Fax:-011-23412593 No. F6/DFS/MS/GH/2015/ NOZ / 71 E-mail ID: cfohq.dlfire@nic.in
Dated

FIRE SAFETY CERTIFICATE

Certified that the M/S Good Luck Inn located at 3997 & 4001 Gali School Wali, Kaseruwalan, PaharGanj, New Delhi comprises of Ground + 3 floors, Ground floor has (one guest room) and 1st floor to 3rd floor has (03 guest rooms at each floor) was granted NOC by this department vide letter No.F6/DFS/MS/GH/2011/1504 dated 08-07-2011. The premises was re-inspected by the officer concerned of this department on 04-01-2015 in the presence of Sh. Arvind Rastogi (Owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub-Division A-1 lodging or rooming houses for 10 guest rooms with effect from 15 / 21 / 2014 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G.C.Misra) Chief Fire Officer Ph – 011-23414333

demen

Copy to:-

1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi – 110049 w.r.t. letter No 39604-607/Joint. C.P./Lic. (H) dated New Delhi 17-10-2014.

2. Sh. Arvind Rastogi (Owner) M/S Good Luck Inn located at 3997 & 4001 Gali School Wali, Kaseruwalan, PaharGanj, New Delhi.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry"

INSPECTION REPORT

1. Name & address of the building : M/S Good Luck Inn located at 3997 & 4001 Gali School Wali,

Kaseruwalan, PaharGanj, New Delhi.

2. Type of Occupancy : Residential Building Gr. + 3 upper floors (total 10guest room)

3. Type of Case : Renewal

4. Details of previous NOC : F6/MS/DFS/GH/2011/1504 dated 08/07/2011

5. Fire Safety directives Letter No. : NA

6. Date of inspection : 04/01/2015

7 Name of the Inspecting Officer : Sh. M. K. Sharma (ADO/CC)

8 Name and designation of Officer

from the building side : Sh. Arvind Rastogi (Owner)

9 Year of Construction : 2010

10. Applicant's letter No. : 39604-607/Joint. C.P./Lic.(H) dated, New Delhi the 17/10/2014.

			0	ld Case	
S No	Minimum standards on fire prevention	Existing	Provided at site	Remarks	
	and fire safety U/R 33	Requirements	(PSS Area)	MR/NMR	
				(PSS Area)	
1.	Access of building				
	Road width	NA	06 Mtr.	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	• Upper floors	1 Nos.	1 Nos.	MR	
	Basements	NA	NA	NA	
	b.Width of staircases		,		
	• Upper floors	0.80 Mtr.	1.25 Mtr. Old case	MR	
	Basements	NA	NA	NA	
	c. Protection of exits		Ē 5		
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No of continuous staircase to terrace	1 No.	1 No.	MR	

e. Width Of Corridor NA f. Door Size NA NA 01 Mtr. 3. Compartmentation 01 Mtr. MR Fire check door NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA Smoke managements System 4 NA NA Basements NA Upper floors NA NA 12 ACPH NATURAL 5 Fire Extinguishers MR Total numbers 08 Nos. 10 Nos. Types MR ABC,CO₂, Wco₂, ABC,CO₂, Wco₂ IS marking MR Required 6 First - Aid Hose Reels Provided MR Total numbers on each floor 01 Length of hose reel hose 01 MR 30 Mtr. 30 Mtr. Nozzle diameter MR 05 MM 7 Automatic fire detection and alarming system 05 MM MR Type of detectors NA NA Location of Main Panel NA NA NA Location of Repeater Panel NA NA NA Alternate source of power NA NA NA Hooters' Location NA NA NA 8 MOEFA NA Required 9 Public Address System Provided MR Required Provided Automatic Sprinkler 10 MR Basements NA* NA Upper Floor NA NA NA Sprinkler above false ceiling NA NA 11 NA Internal Hydrants NA Size of riser/down-comer NA NA Number of hydrants per floor NA NA NA NA 4

1.

	Hose Box			
12	Yard Hydrants	NA	NA	NA
		d	'	
	• Total number of hydrants	NA	NA	NA
13	Hose Box	NA	NA	NA
	Pumping Arrangements			
	o Ground Level			
	Discharge of main pump	NA	NA	NIA
	Head of main pump	NA	NA	NA
	 Number of main pumps 	NA	NA	NA
	Jockey pump out put	NA	NA	NA
	 Jockey pump head 	NA		NA
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	auto Staring/Manual stopping	NA	NA	NA
	Pump House Access		NA	NA
	Terrace level	NA	NA	NA
			*	
	Discharge of pump	450 LPM	450 LPM	MR
	Head of the pump	30 Mtr.	30 Mtr.	MR
	 Power supply 	Required	Provided	MR
	 Auto starting of pump 	Required	Provided	MR
	Captive water Storage for fire fighting			TVIIC
	and ground tank capacity	NA	NA	NA
	of connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	 Access to tank 	NA	NA .	NA
	Overhead Tank capacity	25.00.7		INA
F	Exit Signage	25,00 Ltr.	> 2,500 Ltr.	MR
		Required	Old case Provided	MR
	Provision of Lifts			1/11/
	Pressurization of Lift Shaft Pressurization of Lift Shaft	NA	NA	NTA
	Pressurization of lift lobby Communication in 150.00	NA	NA	NA
	- Communication in lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA		NA
	Lift Signage	NA	NA	NA
		1111	NA	NA

17	Standby power supply	NA	NA	NA	
18	Refuge Area				
	Total area	NA	NA	NA	
	• Location	NA	NA	NA	
19	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection Systems for	Required	ABC, Co ₂	MR	
	Protection of special Risks, if any;				

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/MS/DFS/GH/2011/1504 dated 08/07/2011 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

> Previous FSC was issued on 2500 liter overhead water tank for fire.

Note: Earlier this guest house was running in the name of God Gift Inn now it has been changed from God gift Inn to Good Luck Inn as per record from Joint C.P (Lic.) No. 39604-607/Joint C.P./Lic.(H) dated New Delhi, the 17/10/2014.

Signature of the Inspecting Officer

Name: - M.K. Sharma

Designation :- A. D.O. (CC)

00(60)

July 811/15