

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/ans/FH/2015/52/17

Dated: 06/01/15

FIRE SAFETY CERTIFICATE

Issued on...a.6./61./15.... at New Delhi by.

(Dr.G.C.Misra) Chief Fire Officer T.No.011-23414333

90 1

Copy to:-

- 1.Executive Engineer, Building Department, Najafgarh Zone, South Delhi Municipal Corporation, Main Zonal Building, Room No.121-122, 1st floor, Dhansa Stand, Najafgarh, New Delhi-43.
- 3. Sh. Ashok Kumar Dusad,

M/S The Krishna Green Farm House No.H-1, Pushpanjali, Dawarka Link Road, New Delhi-37.

Conditions for the validity of fire safety certificate are overleaf:-

		INSPECTION RE	EPORT				
1	Name & address of the building				naniali		
1	Name & address of the building	M/s The Krishna Green Farm House No.H-1, Pushpanjali, Dawarka Link Road, New Delhi.					
2	Type of Occupancy						
3	Type of occupancy Type of case	Assembly building "D" Farm House.					
4	Details of previous NOC	Renewal					
	Fire safety directives letter No	No.F6/DFS/MS/H/09/794, dated 20.03.2009.					
5		Nil					
6 7	Date of inspection Name of the inspecting Officers	29.12.2014.					
8		ADO Vedpal					
0		Mr. Ashok Kumar Dusad (Properitor)					
0	from the building side Year of construction	0000	-	T			
9	NO. A PROPERTY OF THE PROPERTY	2002	15 10 00	Output different and	v only and anon		
40	Applicant's letter No.		No.EE(B)NGZ/14/D- 15.12.20 Ground floor o		niy and open		
10			14.	farm house.	To .		
S.	Minimum Standards on fire	Old NOC Requireme	ent	Provided at site	Remarks		
NO.	prevention and fire safety U/R				MR / NMR		
	33						
1	Access to building		β β- 2-2- 1	05.14:	IMP		
	1) Road width	Required		25 Mtr	MR *		
	2) Gate width	5 Mtr		Provided	MR		
2.0	3) Width of internal road	N/A		N/A	N/A		
2	Number, width Type & arranger	ment of exits		Table 1			
	a. Number of staircases						
	1. Upper floors	N.A.		N.A.	N.A.		
	2. basements	N.A.		N.A.	N.A.		
	b. Width of staircase				n H .		
	1. Upper floors	N.A.		N.A.	N.A.		
	2. basements	N.A.		N.A.	N.A.		
	c. Protection of exits	¥.4.	Real March				
	1. Fire check door	N/A	- =	N/A	N/A		
	2. Pressurization	N/A		N/A	N/A		
	d. No. of continuous staircase		77 No. 3	One Provided	MR		
	to terrace			The second secon			
	e. Width of corridor	N/A		N/A	N/A		
	f. Door size	N/A		N/A	N/A		
3	Compartmentation.	IN/A		14/74			
3	1. Fire check door	N/A		N/A	N/A		
	2. Sealing of electrical shafts	N/A		N/A	N/A		
	3. Fire Rating of shaft door	N/A		N/A	N/A		
	4. water curtain	N/A		N/A	N/A		
				N/A	N/A		
A	5. Fire dampers	N/A		IN/A	LIN/M		
4	Smoke Management system.	00 -/	10 1		7		
	Lea Labora	30 a/c per hour	12	N/A	N/A		
	basement	a/c per hour		*			
5	upper floors			N/A	N/A		
	Fire Extinguishers			10 N - 5 - 11 - 1	TME		
	total numbers	08Nos. ABC,CO2 ISI		12 Nos. Provided	MR		
	Types			ABC and CO2	MR		
	ISI marking	**		ISI Mark	MR		
6	First-Aid Hose Reels.				-		
	total numbers on all around	04nos.		07nos.	MR		
	Length of Hose reel hose	30 Mtr		30mtr.	MR		
	Nozzle Diameter	5mm	· L	5mm	MR		
	Putor tis bas one or we breid		, ::				
_	Type of defectors	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		Mya Tank	155		

The Krishna green form Howe Ho H-I Pastanjali Rawaska hink hoad New De

7	Automatic fire detection and	alarming evetem		
	Type of detectors	N/A	INI/A	
	location of Main Panel	N/A	N/A	N/A
	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	hooter's location	N/A	N/A	N/A
8	MOEFA	Required	N/A	N/A
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.	Trequired	Provided	MR
	basement	N/A		
	upper floors	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	14//1	N/A	N/A
	Size of riser/down-corner	N/A	INV	
	Number of Hydrants per floor	N/A	N/A	N/A
	hose Box	N/A	N/A	N/A
	Yard Hydrants.	IN/A	N/A	N/A
	total number of hydrants	Required		la sulla di la
	house box		07nos.	MR
	Pumping arrangements	Required	07nos.	MR
1	1. Ground level	-		1 V
	a. Discharge of main Pump	900lpm		1 B
I	b.Head of main pump	40m	900lpm	MR
	c.Number of main pumps		40m	MR
0	d.jockey pump out put	01no.	01no.	MR
E	e.jockey pump head	N/A	180lpm	N/A
f	. Standby Pump output		40m	N/A
	g.Stanby Pump head	N/A	N/A	N/A
ľh	n.Auto Starting/Manual stopping	N/A	N/A	N/A
p	oump house access	Required	Provided	MR
2	Terrace level	Required	Provided	MR
	. Discharge of pump	N/A	N/A	N/A
b	head of the pump	N/A	N/A	N/A
C	. Power supply	N/A	N/A	N/A
d	. Auto starting of pump	N/A	N/A	N/A
C	captive water storage for fire	N/A	N/A	N/A
l fi	ghting	15,		
	. Underground tank capacity	50000Liv		Tark III
la.	Draw-off connection	50000Liters	50000Liters	MR
	fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
		Required	Provided	MR
1	ver head tank Capacity	10,000 Ltr	Provided	MR
F-	vit Clause	W 4		
E	kit Signage.	Required	Provided	MR
			į. roriuou	IVIC
Pr	ovision of lifts.		No Lift Provided	
a.		N/A	N/A	N/A
b.	pressurization of lift lobby	N/A	N/A	
C.	communication in lift car	N/A **	N/A	N/A
d.	Fireman's grounding switch	V/A	N/A	N/A
e.	1 : (4	V/A	N/A	N/A
	2 - 2	· · · · · · · · · · · · · · · · · · ·	IV/A	N/A
Sta	andby power supply	Required	Provided	MD
	fuge Area.		Not Required	MR
1	alaroo		required	4
100000000000000000000000000000000000000	al area		Not required	

The Kirshana Green farm House NO -H-I Puspanjahi Dawarta Link Road

19 Fire control room a. detector system Panel		
c. Plow switch Panel c. PA system Panel d. Batter backup e. Building floor re	N/A N/A N/A N/A N/A Required Provided N/A N/A N/A N/A N/A N/A N/A N/A N/A	
The fire protection systems provided in the inspection.	S for protection IN/A	

The fire protection systems provided in the building were checked and found functional at the time of In view of the deemed compliance of the minimum standards on fire prevention and fire safety required

under the rules the NOC issued vide letter No.F.6/DFS/MS/H/09/794, dated 20.03.2009 renewal under rule Accordingly DFA is put up for your approval and signature please.

Signature of the Inspecting Officer

Name Vedpal

Design: ADO (SJ)