GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/GH/2015/SZ/

DATED: 12/01/15

FIRE SAFETY CERTIFICATE

(Dr. G.C. Misra) Chief Fire Officer

Copy to,

1. The Authorized Signatory, RTS Hotel (Guest House) at Plot No. A-69, Mahipalpur, NH-8, Near IGI Airport, New Delhi-110037

2. The Dy. Health Officer, Health Department SDMC, Najafgarh Zone, New Delhi-110043.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The basement shall be used strictly as per the provisions of Building Bye laws.
- e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in
- f. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1			INSPE	CTION REPUR	Mahinala	ur, NH-8, Near IGI Ai	rport, New	Delhi-	
-	Name & address	s of the building	RTS Hotel (Guest House), A-69	, iviai iipaip				
1	Name & address	1	10037						
	Type of Occupancy R		Residential & Lodging "A" (Guest House)						
2	2		New						
3	Type of case		No						
4	Details of previous NOC		No						
5	Fire safety directives letter No		22.12.2014						
6	Date of inspection Name of the inspecting Officers :		D.O. (South) D.P. Bhardwaj, ADO Vedpal (SJ)						
7			Sh. Amit Kumar (Owner)						
Name and designation of		ignation of officers	1			Wan Hall 1st floor-			
	from the building side		Basement- Parking, Ground floor- Reception, Hall, 1st floor 4 guest room, 3rd floor -2 guest 4 guest rooms, 2nd floor -4 guest rooms at				est		
			2000	4 guest rooms	2nd floor	& two temporary s	taff rooms	at	
	Year of constr	uction		rooms + owner	residence	looms)	1 15-00	upper	
9			Nil dated 21.11.2014 & SDMC letter NILONIC 7/2014/644 dated NILONIC 7/2014/644 dated REPORT FOR THE PROPERTY OF THE PROPERTY STATES AND THE PROPERT					ff	
7	Applicant's let	tter No.	No. DHO	NGZ/2014/644 date	ed	rooms at terrace			
40			20.06.20	Requirement		ovided at site	Remarks MR / NMF	,	
10 S. NO.	Minimum Sta	andards on fire prevention	NBC	Requirement		· · · · · · · · · · · · · · · · · · ·	WIR / NIVII		
0,,,,	and fire safe	ty U/R 33							
	Access to b	uilding			15 Mtr Pro	ovided	MR		
1	1) Road widt	h	Required	1	Directly a	associable to main	MR		
	2) Gate width		Require	d	road		1 4 - 4		
			N/A		N/A	411	N/A		
=	3) Width of i	nternal road		v			2		
2	Number, wi	idth Type & arrangement o) CAILO			vided	MR	S =	
	a. Number	of staircases	One				MD		
	1. Upper flo	1015	2 Nos		1 No. St	air + 1 Ramp	MR		
	2. basemen	nts	2 1400		-				
	b. Width of	f staircase	14	· ·	1.10 Mt	Provided	MR		
	1. Upper flo		0.90 M 0.90 M		1.10 Mt	r + Ramp Provided	MR	*	
	2. baseme		0.90 1	LI .			21/0		
		ion of exits	N/A		N/A		N/A		
	1. Fire che		N/A		N/A		N/A MR		
	2. Pressur	rization			Provide		IVIT		
		of continuous staircase			Provid	od.	MR		
	terrace e. Width o	of corridor	1.25	Vitr	Provid		MR		
	f. Door size		1 Mtr		FIOVIG	04			
		mentation.			N/A		N/A		
	1. Fire ch		N/A		Provid	led	MR		
	2. Sealin	g of electrical shafts	Requ	ııred	N/A		N/A		
	3. Fire R	ating of shaft door	N/A		N/A		N/A		
	4. water		N/A	~	N/A		N/A		
	5. Fire da	ire dampers		N/A **		138 34			
	4 Smoke	Smoke Management system.		30 a/c per hour		Exhust fans provided			
	baseme	nt	12 8	a/c per hour		356 See 14 12	L		
	Dasoino				Natu	ral Ventilation	MR		
	upper fl	oors			1. 10.20				
		tinguishers			10 N	los	MR		
	total nu	mbers			ABC	C, Water Co2,	MR		
	Types	W. Carlotte	ISI		Yes		MR		
	ISI mai	rking	[101		. 1				

6			1181 978 Beet 108 He	Post Lazar Co.		
0	First-Aid Hose Reels.					
	total numbers on each floor	N/A	One Provided			
	Length of Hose reel hose	N/A	30 Mtr. Provided	MR		
7	Nozzle Diameter	N/A	5 MM Provided	MR /		
	Automatic fire detection and alarmin	ng system		MR		
	Type of detectors	N/A	N/A	NI/A		
	location of Main Panel	N/A	N/A	N/A		
	location of Repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
0	hooter's location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.		14//	N/A		
	basement	Required	Provided	145		
	upper floors	N/A	NI/A	MR		
3 -	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants		(D) 1 1 1 4 -	N/A		
	Size of riser/down-corner	N/A	N/A			
	Number of Hydrants per floor	N/A	N/A	N/A		
	hose Box	N/A	NI/A	N/A		
12	Yard Hydrants.			N/A		
	total number of hydrants	N/A	N/A	A Radio Company		
	hose box	N/A	N/A	N/A		
13	Pumping arrangements		[IV//\]	N/A		
	1. Ground level		Harris (gr.e., cq.sa.)			
	a. Discharge of main Pump	N/A	N/A	2 2 2 2 3		
	b.Head of main pump	N/A	N/A	N/A		
	c.Number of main pumps	N/A	el Spire in gasting particular and a second	N/A		
	d.jockey pump out put	N/A	N/A	N/A		
	e.jockey pump head	N/A	N/A	N/A		
	f. Standby Pump output	N/A	N/A	N/A		
	g.Stanby Pump head	N/A	N/A	N/A		
	h.Auto Starting/Manual stopping	N/A	IN/A	N/A		
	pump house access	N/A	N/A	N/A		
	2.Terrace level	. 4/1 \	N/A	N/A		
	a. Discharge of pump	N/A	450 L DM D			
	b. head of the pump	N/A	450 LPM Provided	MR		
	c. Power supply	N/A	35 Mtr Provided	MR		
	d. Auto starting of pump	N/A	Provided	MR		
14		. 1// 1	Provided	MR		
	Captive water storage for fire fighting		1 8 . 98	x *		
	Underground tank capacity	N/A	N/A	N/A		
1	a. Draw-off connection	N/A	N/A	N/A		
	b. fire service inlet	N/A	N/A	N/A		
	c.Access to tank	N/A	N/A	N/A		
	Over head tank Capacity	N/A	5,000 ltrs. Provided	MR		
	Exit Signage.	Required	Provided	MR		
17	Provision of lifts.		A Paragraphy of the state of th			
	a. Pressurization of lift shaft	N/A	N/A	N/A		
	o. pressurization of lift lobby	N/A	N/A	N/A		
	c. communication in lift car	Required	Provided	MR		
	d. Fireman's grounding switch	Required	Provided	MR.		
(e. Lift signage	N/A	N/A	N/A		
	Standby power supply					

		Not Required				
	Refuge Area.		Not required			
	total area			1		
	location					
19	Fire control room		NI/A	N/A		
	a. detector system Panel	N/A	N/A	N/A		
	b. Flow switch Panel	N/A	N/A	N/A		
	c. PA system Panel	N/A	N/A	N/A		
	d. Batter backup	N/A	N/A			
	a Building floor plans	N/A	N/A	N/A		
00	Special Fire Protection systems	for protection of specia	I risks, if any: N/A			
20	The state of the s					
he Shorto	oming vide letter no. F6/DFS/MS/GH,	/2014/1886 dated 26.08.2	014 has been rectified.			
- five pro	staction systems provided in the build	ing were checked and fol	ind fullclional at the time of mepoda	1.		
ne me pre	Steelier dysterns pro-	ii atandarde on	fire prevention and fire safety required	d under the rules it is		
(eeping in	view the substantial compliance of tr ded to grant Fire Safety, Certificate ur	dor rules 35 of the Delhi	fire prevention and fire safety required			
ecommen	ded to grant Fire Safety Certificate un	idel fales 55 of the Barri	royal and signature please.			
	/Accordingly D	FA is put up for your app	roval and signature please.			
	4					

Signature of the inspecting officer

Name

D. P. Bhardwaj

Designation : Divisional Officer (South)

Signature of the inspecting officer

Name:- Vedpal

Designation: ADO (SJ)