GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2015/ S2 / 214

Dated:

16/02/15

FIRE SAFETY CERTIFICATE

Certified that the **Hotel De- Continental** located at 8A/44, WEA, Karol Bagh, New Delhi-110005 is comprised of Ground floor plus three upper floors, using ground floor as reception, office & 03 guest rooms, first, second & third floor each having 05 guest rooms respectively (Total 18 guest rooms) and a pantry for staff on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2012/84 dated 10.01.2012 owned/ occupied by Sh. Suresh Kumar. The guest house building was re- inspected by the officers concerned of this department on 02.02.2015 in the presence of Sh. Madan Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

- 1. The Joint Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.719/Joint C.P./Lic.(H), Dated 08.01.2015)
- 2. Sh. Suresh Kumar (Owner) Hotel De- Continental, 8A/44, WEA, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

. Parada in the State of the

- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground floor plus three upper floors.

1/13	INSPECTIC	IN REPORT		1.00 H- 10 A		
	INSPECTION REPORT 1. Name & address of the building: Hotel De-Continental, 8A/44, WEA, Kax 2. Type of Occupancy : Residential (Guest House) 3. Type of Case : New Case/Renewal 4. Details of Previous NOC : Letter No. F.6/DFS MS GH 2012 84 Date 10 00 5. Fire Safety directives letter No : O2. 02. 2015 7. Name of Inspection : Date of inspecting Officer : No. S.K. Tomax & A.D.O P.S. Dahiya 8. Name and designation of officers From the building side : Sh. Madan Singh (Manager)					
	6.6.	Sh. Madan Singh (Manager) Before 2001				
	10. Applicant's letter No. : 7	19 Joint C.P.	LIC. (H) dated	08.01.7017		
1	Minimum Standards on fire	NBC/BBL	Provided at	Remarks		
	prevention and fire safety U/R 33	Requirement	site	MR/NMR		
	Access to building		09mtr	MR		
	Road width	Accessible				
	 Gate width 	-	1.54 cms	MR		
	 Width of internal road 					
2.	Number, Width, Type & Arrangement	of Exits		The same of the sa		
	a. Number of staircases			Nap		
	• Upper Floors	One	One	MR Na Bases and		
-	 Basements 			No Basement		
	b. Width of staircases	100	100	MR		
	Upper Floor	125 cms	125 cms	No Basement		
	Basements			, No Made Curen		
	c. Protection of exits • Fire check door					
	• pressurization		Constitution of the Consti			
	d. Not of continuous staircases to					
	terrace		One			
	e. Width of Corridor	-	10Scms, 220cm	4 -		
	f. Door Size		78 cms x20Scm			
			TO CHIO KOUS CIT			
3.	Compartmentation					
	Fire check door	-				
	 Sealing of electrical shafts 		Sealed			
	 Fire Rating of shaft door 					
	Water Curtain	•		-		
	 Fire Dampers 					
4.	Smoke Management System					
	* Basements	30 a/c per	_	No Baseme		
	Upper floors	hour	Natural Venti	labon MR		
			Malaral VENTI	la thou		

	1914.		ij.	
	17/120	12 a/c per	7 12 27 de	
		hour	-	-
5.	Fire Extinguishers			1
	 Total numbers 	Two at each floor	Provided	MR
	Types	Co2, WCo2	-do-	MR
	IS marking	ISI marked	151 Marked	MR
6.	First-Aid Hose Reels			
	 Total numbers on each floor 	One	Provided	MR
	 Length of hose reel hose 	30 m	-do-	MR
	Nozzle diameter	5 mm	-do:-	MR
7.	Automatic fire detection and alarming	system		
	 Type of detectors 	-	•	4
1	 Location of Main Panel 	_		: +
	 Location of Repeater Panel 			+
	 Alternate source of power 	_	D.G. Set of 25 KVA	
	 Hooters' Location 		Near Staircase	
8.	MOEFA	Required	Provided	MR
9.	Public Address System	- do -	-do-	MR
10.	Automätic Sprinkler System			
	• Basement .			No Basement
	 Upper Floor 			
1	 Sprinkler above false ceiling 			-
11.	Internal Hydrants			
	 Size of riser/down-comer 			
	 Number of hydrants per floor 	•		+
	 Hose Box 	-		
12.	AT A S A S A S A S A S A S A S A S A S A		J.	
1	 Total number of hydrants 			
	 Hose Box 			
13				
1	Ground Level			
	Discharge of main Pump	,		
ļ	> Head of Main pump			
	Number of main pumpsJockey Pump out put			
	Jockey Pump out putJockey pump head			
1	> Standby Pump out put			
	> Standby Pump Head		addresses	
	Auto Starting/Manual			
1			-	
1	stopping			

U

7114

8A/44, WEA, Karol Beigh, New Delhi - 110005.

	Pump House Access	•	9				
	Terrace level			- 8			
	> Discharge of pump	450 LPM	450 LPM	MR			
	> Head of the pump	30 M Reguired	30 M Provided	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump		• 1				
14.	Captive Water Storage for fire fighting			ì			
	 Underground tank capacity 		•				
	Draw-off connection		No.				
	Fire service inlet		Symmetry	Lambara.			
	Access to tank			-			
	 Overhead Tank capacity 	-	asoo Ur	MR, Old Case			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.		,	is a			
	Pressurization of Lift Shaft			,			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 						
			0				
			Provided	MR			
				Old Wift			
		Required	Provided	MR .			
17.	Standby power supply	Required	Provided	MR ;			
4.0				Š.			
18.	Refuge Area.						
	> Total Area		V-manage.				
	> Location		-				
19.	Fire Control Room						
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 						
			· Company	1			
			The second secon	:			
			0				
			Provided				
	1						
20.	Special Fire Protection System for			_			
china de la companya	Protection of special Risks, if any:						

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/NFS/MS/GH/2018/84 dated 10.01.2012 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.



Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Milary galig.

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Asst. Divisional Officer