

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

NO. F6/DFS/MS/Auditorium/2015/M02/277 DATED: 27/02/15

FIRE SAFETY CERTIFICATE

Certified that the Auditorium at Swaminarayan Akshardham Temple, N.H.24, Opp.Nizammuddin Bridge, New Delhi 92, owned/occupied by BAPS Swaminarayan Sanstha, comprising of ground floor only was granted fire safety certificate vide letter no. No.F.6/DFS/MS/Auditorium/2012/635 dated 24.02.12. The auditorium building was inspected by the officer concerned of this department on 21.02.15 in the presence of Swami Dhyeynishtha Das and found that the auditorium building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 and that the auditorium building is fit for occupancy Group D "Assembly Building" with effect from 27/02/15 for a period of three years, subject to conditions printed overleaf.

Issued on 27/02/15 at New Delhi by



(Dr.G.C.Misra)
Chief Fire Officer
Ph.011-23414333

To,

Sh.Jayesh Gadhia
BAPS Swaminarayan Sanstha
Swaminarayan Akshardham Temple, N.H.24,
Opp.Nizammuddin Bridge, New Delhi 92

Copy to:-

The Addl. Commissioner of Police (Lic.),
First Floor, Police Station,
Defence Colony, New Delhi.

In refrence letter no.1659-63/ Joint.CP/Lic
(Amst.) Dated 23.01.15

copy K

1. Name & address of the building : Auditorium at Swaminarayan Akshardham Temple,
N.H.24, Off. Nizammuddin Bridge, Delhi- 92
2. Building Comprised of : Ground floor only
2. Type of Occupancy : Assembly
3. Type of Case : **Renewal**
4. Details of Previous FSC : F.6/DFS/MS/Auditorium/2015/635 Dated 24/02/12
5. Fire Safety directives No : NBC Part IV
6. Date of Inspection : 21.02.2014
7. Name of the Inspecting Officer : DO Virendra Singh
8. Name of the designation of Officer
From the building side : Sh. Jayesh Gadhia (Manager)
9. Year of Construction : 2005
10. Applicant's letter No : 1659-63 /Joint C.P./Lic.(Amst.)Dated 23/01/2015

Sl.no.	Minimum Standards on fire prevention and fire safety U/R33	NBC Part IV Requirement	Provided at Site	Remarks
1	Access to building			MR/NMR
	<ul style="list-style-type: none"> Road width 	06 Mtrs	20 Mtrs.	MR
	<ul style="list-style-type: none"> Gate width 	4.5 Mtrs	06 Mtrs.	MR
	<ul style="list-style-type: none"> Width of internal road 	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	<ul style="list-style-type: none"> Upper Floor 	02 Nos	02 Nos.	MR
	<ul style="list-style-type: none"> Basement 	N/A	N/A	N/A
	B. Width of Staircases			
	<ul style="list-style-type: none"> Upper Floor 	2 M	2 M	MR
	<ul style="list-style-type: none"> Basement 	N/A	N/A	N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization 	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	2 M	2 M	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Sealing of electrical shafts 	Required	Sealed	MR
	<ul style="list-style-type: none"> Fire rating of shaft door 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Water curtain 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Fire Dampers 	N/A	N/A	N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> Basement 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Upper floor 	Required	Provided	MR

5.	Fire Extinguisher			
	• Total numbers	10 nos.	10 Nos.	MR
	• types	ABC & Co2	ABC & Co2	MR
	• IS marking	ISI marked	ISI marked	MR
6.	First-aid-Hose Reels.			
	• Total numbers of each floor	2 nos.	2 nos.	MR
	• Length of hose reel hose	30 m	30 m	MR
	• Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	Smoke	smoke	MR
	• Location of main panel	Control Room	Provided	MR
	• Location of repeater panel	Security Room	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters's location	Hall	Hall	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	N/A	Provided	MR
10	Automatic Sprinkler System.	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	• upper floors	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	100 MM	100 MM	MR
	• Number of hydrants r	1 No.	1 No.	MR
	• Hose Box	1 No.	1 No.	MR
12	Yard Hydrants.			
	• Total number of hydrants	2 Nos.	2 Nos.	MR
	• Hose Box	2 Nos.	2 Nos.	MR
13	Pumping Arrangements.			
	• Ground Level	Required	Provided	MR
	➤ Discharge of main Pump	2850 LPM	2850 LPM	MR
	➤ Head of Main Pump	70 M	70 M	MR
	➤ Number of main pumps	1 No.	1 No.	MR
	➤ Jockey pump out put	225 LPM	225 LPM	MR
	➤ Jockey pump head	70 M	70 M	MR
	➤ Standby pump out put	70 M	70 M	MR
	➤ Standby pump Head	Required	Provided	MR
	➤ Auto Starting /Manual stopping	Required	Auto	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace Level	N/A	N/A	N/A
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the Pump	N/A	N/A	N/A
	➤ Power supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	2,00,000 Ltrs.	4,00,000 Ltrs.	MR
	➤ Draw-off connection	N/A	Provided	MR
	➤ Fire service inlet	N/A	Provided	MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.	N/A	N/A	N/A
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	Required	Provided	MR
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	Provided	MR
	• Battery backup	Required	Provided	MR
	• Building Floor Plans	N/A	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

Fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measure as required under the rules. The fire safety certificate issued vide letter no. F.6/DFS/MS Auditorium/2012/635 dated 24.02.12 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Submitted please.

Virendra Singh
 Signature of the Inspecting Officer
 Name:-Virendra Singh
 Designation :- DO (ED)