

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

Fax:-011-23412593

E-mail ID: cfhq.dfire@nic.in

No. F6/DFS/MS/Club/NDZ/2015/283

Dated 27/02/15

**FIRE SAFETY CERTIFICATE**

Certified that the **National Sports Club of India** located at **Mathura Road, New Delhi** comprises of **Ground + One floor** was granted NOC by this department vide letter No.F6/DFS/MS/2011/542 dated 25-03-2011 and letter No. F6/DFS/MS/Club/NDZ/2014 dated 17/09/2014 is for **Marwah Loung & Dining hall**. The premises was re-inspected by the officer concerned of this department on 12-02-2015 in the presence of Mr. Lamba (Member) for inclusion of **Maikhana Bar** and found that the building at Ground floor (**Marwah Loung, Dining hall & Maikhana Bar**) have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the **Marwah Loung, Dining hall & Maikhana Bar** is fit for occupancy class **Group D Assembly Building, Sub-Division D-3** with effect from ~~27/02/~~2015 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on...27/02/15..... at New Delhi by.

  
(Dr.G.C.Misra)  
Chief Fire Officer  
Ph – 011-23414333

Copy to:-

1. The Asstt. Commissioner (Excise),  
Office of Commissioner (Excise)GHCT,  
L&N Block, Vikas Bhawan, New Delhi.
2. Hony. Regional Secretary,  
National Sports Club of India,  
Mathura Road, New Delhi.
3. The Medical Health Officer, NDMC, New Delhi.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry"
7. The FSC is only for Marwah Lounge and Dining Hall & Maikhana Bar.

## INSPECTION REPORT

1. Name & address of the building : **National Sports Club of India, Mathura Road, New Delhi.**
2. Type of Occupancy : **Building (Ground+ One floor) at Present Ground floor  
(Marwah Lounge, Dining hall & Maikhana Bar)**
3. Type of Case : **Renewal**
4. Details of previous NOC : **F6/DFS/MS/2011/542 dated 25/03/2011  
F6/DFS/MS/Club/2014/NDZ/1209 dated 17/09/2014  
(Marwah Lounge & Dining hall)**
5. Fire Safety directives Letter No. : **NA**
6. Date of inspection : **12/02/15**
7. Name of the Inspecting Officer : **Sh.G.S. Chauhan (DO/CD) & Sh. M.K. Sharma (A.D.O. CC)**
8. Name and designation of Officer  
from the building side : **Mr. Lamba (Member)**
9. Year of Construction : **Old**
10. Applicant's letter No. : **F.1(CLUB)/MISC/2007-08/256/5965 dated 29/01/2015.**

Old Case

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR
1.	<b>Access of building</b>			
	• Road width	12 Mtr.	16 Mtr.	MR
	• Gate width	06 Mtr.	06 Mtr.	MR
	• Width of internal road	NA	NA	NA
2.	<b>Number, width, Type &amp; Arrangements of exits</b>			
	a. Number of staircases			
	• Upper floors	01	01	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper floors	1mt.	1.10mt.	MR
	• Basements	NA	NA	NA
	c..Protection of exits			
	• Fire check door	NA	NA	NA
	Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	1 mt	1.25mt	MR
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	1mt.	1.5 mt.	MR
3.	<b>Compartmentation</b>			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
		NA	NA	NA

Smoke managements System				
4	• Basements	NA	NA	NA
	• Upper floors	NA	NA	NA
5	<b>Fire Extinguishers</b>			
	• Total numbers	20	24	MR
	• Types	ABC, Co2, Wco2	ABC, Co2, Wco2	MR
	• IS marking	Required	Provided	MR
6	<b>First – Aid Hose Reels</b>			
	• Total numbers on each floor	02	02	MR
	• Length of hose reel hose	30 mt	30 mt	MR
	• Nozzle diameter	05 mm	05 mm	MR
7	<b>Automatic fire detection and alarming system</b>			
	• Type of detectors	Required	Provided	MR
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	<b>Automatic Sprinkler</b>			
	• Basements	NA	NA	NA
	• Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	<b>Internal Hydrants</b>			
	• Size of riser/down- comer	100 mm	100 mm	MR
	• Number of hydrants per floor	02	02	MR
	• Hose Box	02	02	MR
12	<b>Yard Hydrants</b>			
	• Total number of hydrants	05	05	MR
	• Hose Box	05	05	MR
13	<b>Pumping Arrangements</b>			
	○ Ground Level			
	• Discharge of main pump	900 LPM	900 LPM	MR
	• Head of main pump	40 mm	40 mm	MR
	• Number of main pumps	01	01	MR
	• Jockey pump out put	280 LPM	280 LPM	MR
	• Jockey pump head	40 mm	40 mm	MR
	• Standby Pump out put	NA	NA	NA
	• Standby Pump Head	40 mm	40 mm	MR
	• auto Staring/Manual stopping	Required	Provided	MR
	• Pump House Access	Required	Provided	MR
		NA	NA	NA

	• Head of the pump	NA	NA	NA
	• Power supply	NA	NA	NA
	• Auto starting of pump	NA	NA	NA
14	Captive water Storage for fire fighting			
	• Under ground tank capacity Draw of connection	50,000 ltrs Required	50,000 ltrs Provided	MR MR
	• Fire service inlet	Required	Provided	MR
	• Access to tank	Required	Provided	MR
	• Overhead Tank capacity	10,000 ltrs	10,000 ltrs	MR
15	Exit Signage	Required	Provided	MR
16	Provision of Lifts			
	• Pressurization of Lift Shaft	Required	Provided	MR
	• Pressurization of lift lobby	NA	NA	NA
	• Communication in lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
	• Total area	NA	NA	NA
	• Location	NA	NA	NA
19	Fire control room			
	• Detector system panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	Required	Provided	MR
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any;	YES	ABC, Co <sub>2</sub>	MR

**Note:-** Renovation is carried out in Maikhana Bar at Ground floor.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2011/542 dated 25/03/2011 and F6/DFS/MS/Club/2014/NDZ/1209 dated 17/09/2014 (Marwah Lounge & Dining hall) renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name :- G.S Chauhan  
Designation :- DO (CD)

Signature of the Inspecting Officer

Name :- M.K. Sharma  
Designation :- ADO (CC)



By CFO (NDZ) / name

