GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/GH/2015/ \$2 293

Dated:

03/03/15

FIRE SAFETY CERTIFICATE

Certified that the M/S S & S Pioneer Corp., A-30, Mayapuri Industrial Area, Phase-I, New Delhi 110064, is comprised of Ground floor only having two halls. The banquet hall is owned/occupied by the unit of M/S S & S Pioneer Corp. The banquet hall building was inspected by the officers concerned of this department on \$\mathbb{Q}\$.01.2015 in the presence of Sh. Sameer Arora (Owner) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on o3 o3 lo3 at New Delhi.

(Dr. G. C. Misra) Chief Fire Officer Ph-011-23414333

ofc

Copy to:-

 The Deputy Health Officer, West Zone (SDMC), Public Health Department, Vishal Enclave, New Delhi. (Letter No. D-3210/HO/WZ dated 29.01.2015)

The General Manager, M/S S & S Pioneer Corp., A-30 Mayapuri Industrial Area, Phase I, New Delhi 110064.

INSPECTION REPORT

1. Name & address of the building: M/S S & S Pioneer Corp., A-30, Mayapuri Industrial Area, Phase-I, N. Delhi 64.

2. Type of Occupancy

: Group 'D' Assembly Building.

3. Type of Case

4. Details of Previous NOC

: N/A

5. Fire Safety directives letter No : N/A

6. Date of inspection

: 29.01.2015

7. Name of Inspecting Officer

: D.O. S.K. Tomar and A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side

: Sh. Sameer Arora (Owner)

9. Year of Construction

: 2014.

10. Applicant's letter No.

: Letter No. D-3210/HO/W7 dated 29.01.2015 & Form 'I 'dated Nil.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	n Dir. Of Edu. Circular dt. 01.03.2011	Provided at	Remarks MR/NMR			
1.	Access to building						
	Road widthGate width	Accessible 06 mtrs.	12 mtrs Open	M/R M/R			
	Width of internal road	-					
2.	Number, Width, Type & Arrangemena. Number of staircasesUpper Floors	t of Exits N/A	N/A	(Ground Floor Only)			
	Basements b. Width of staircases	N/A	N/A	(No Basement)			
	Upper FloorBasements	N/A N/A	N/A N/A	(Ground Floor Only) (No Basement)			
	c. Protection of exitsFire check doorPressurization	N/A N/A	N/A N/A	(Ground Floor Only) (Ground Floor Only)			
	d. No. of continuous staircases to terracee. Width of Corridorf. Door Size	N/A	N/A	(Ground Floor Only) M/R			
		200 cms	400 cms. 04 doors each in Hall- & Hall-II having width 275 cms	I M/R			
3.	Compartmentation						
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	(No Basement)			
	Upper floors	N/A	N/A	(Ground Floor Only)			
5.	Fire Extinguishers						

Banquet Hall- 2 No's at Ground Floor only (S & S Pioneer Corp., A-30, Mayapuri Industrial Area, Phase- I, N. Delhi)

	Total numbers	15 No's	Provided	M/R			
	• Types	W/Co2/ CO2type	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			
	First-Aid Hose Reels						
6.	Total numbers on each floor	Three	Provided	M/R			
	 Length of hose reel hose 	30 mtrs.	Provided	M/R			
	Nozzle diameter	5 mm	Provided	M/R			
		system					
7.	 Automatic fire detection and alarming Type of detectors 	N/A	N/A	N/A			
	Type of detectors		N/A	N/A			
	 Location of Main Panel 	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A N/A	N/A	N/A			
	Hooters' Location			14/0			
3.	MOEFA	Required	Provided	M/R			
) <u>.</u>	Public Address System	N/A	Provided	N/A			
10.	Automatic Sprinkler System						
		N/A	N/A od	N/A			
	Basement	N/A	Provided	N/A			
	 Ground Floor Sprinkler above false ceiling	N/A	Provided	N/A			
11.	Internal Hydrants						
11.	Titter max 12 y d. a.a.s.		100	N/A			
	Size of riser/down-comer	N/A	100 mm	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	14/71			
12.	Yard Hydrants						
	Table weeker of hydrants	N/A	02 No's	N/A			
	Total number of hydrants	N/A	02 No's	N/A			
13.	Hose Box Pumping Arrangements						
13.							
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump		N/A	N/A			
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A		N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A				
	> Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/Manual	N/A	N/A	N/A			
	Stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace level						
	> Discharge of pump	900 LPM	900 LPM & 180	M/R			
	> Head of the pump	22	LPM 30 Mtrs (Each)	M/R			
	> Power Supply	30 Mtrs.	Provided	M/R			
	,	Required	TTOVIded	TTALAC			



12/3

Banquet Hall- 2 No's at Ground Floor only (S & S Pioneer Corp., A-30, Mayapuri Industrial Area, Phase- I, N. Delhi)

	Auto Starting of pump	Required	Provided	M/R			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	Required	Provided	M/R			
	Access to tankOverhead Tank capacity	N/A	N/A	N/A			
		15000 Ltrs.	15,000 Ltrs.	M/R			
15.	Exit Signage.	Required	Provided	M/R			
16.	Provision of Lifts.			(No Lift)			
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A			
		N/A	N/A	N/A			
 17.	Standby power supply	Required	Provided (380 KVA *2 No's)	M/R			
17.	Standay power supply						
18.	Refuge Area.						
	Total AreaLocation	N/A	N/A	N/A			
-		N/A	N/A	N/A			
19.	Fire Control Room						
······································	Detector System Panel	N/A	N/A	N/A			
	Flow Switch PanelPA System Panel	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Building Floor Plans		1 1 1 1				
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note: The authorized signatory's letter regarding the height of the banquet hall building is less than 10 mtrs. is placed at C-6.

Signature of Inspecting Officer

Name: - S.K. Tomar

Designation:- Divisional Officer

Signature of Inspecting Office

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer