FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DECHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI - 110001

No. F6/DFS/MS/2015/W2/333

Dated: 13/03/15

## FIRE SAFETY CERTIFICATE

Certified that Crystal Crop Protection Pvt. Ltd. located at B-95, WazirPur Industrial Area, New Delhi. in a building comprised of 2 Basement +Ground+ 2Upper Floors) owned/ occupied by The Crystal Crop Protection Pvt. Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officer concerned of this department on 13-01-2015 in the presence of Sh. Pravin Antal(DGM Admin) and found that the said building that the premises is fit for occupancy "Class -G-2 Moderate Hazards Industry with effect from 13/03/15 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 13 /03 /15 ... at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to:

1. Crystal Crop Protection Pvt. Ltd ,B-95. WazirPur Industrial Area New Delhi

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning

5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. Basement shall be used strictly as per Building Bye Laws.

The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

## INSPECTION REPORT

1. Name & address of the building: Crystal Crop Protection Pvt. Ltd. B-95, WazirPur Industrial Area, New Delhi.

: Class -G-2 Moderate Hazards Industry( 2 2. Type of Occupancy Basement +Ground+ 2Upper Floors)

3. Type of Case

4. Details of previous NOC

Fire Safety directives Letter No.: F6/DFS/MS/BP/2012/2053 dated 06/06/2012

Plot area=1923m<sup>2</sup>

:13-01-2015 Date of inspection

Covered area=3832 m<sup>2</sup> (B1st & 2nd- 960 m<sup>2</sup> Name of the Inspecting Officer: DO/W&ADO (WP) each, FF - 960 m<sup>2</sup>, SF- 952

Name and designation of Officer

: Sh. Pravin Antal(DGM Admin) from the building side

: 2014 9. Year of Construction

:Nil dated 09/12/2014 10. Applicant's letter No.

Minimum standards on fire prevention and fire safety U/R 33	Directive Requirements	THE THE CHARLES THE	Remarks MR/NMR
. Access of building			MR
• Road width	60 mtrs	Provided	
• Gate width	5 mtrs	Provided	MR
• Width of internal road	NA	NA	NA
. Number, width, Type & Arrang	gements of exits		The second secon
a. Number of staircases		THE PROPERTY OF THE PARTY OF TH	MD
• Upper floors	2	Provided	MR
Basements	2	provided	MR
b. Width of staircases			
	2X1.5 M	Provided	MR
<ul><li>Upper floors</li><li>Basements</li></ul>	2X1.5M(2car	Provided	MR
	lift&2 Passenger Lift)		
c. Protection of exits	The state of the s		
• Fire check door	Required	Provided	MR
d. Pressurization	Required	Provided	MR
e. No of continuous	Required	Provided	MR
staircase to terrace	1	Provided	MR
f. Width Of Corridor	NA		
g. Door Size	1m	Provided(including door frame)	MR
111.13		Haille)	
3. Compartmentation			

	Fire check door	Required	Provided	MR
	Sealing of electrical	Required	Provided	MR
	shafts			
	<ul> <li>Fire Rating of shaft</li> </ul>	Required	Provided	MR
	door			
	Water Curtain	NA	NA	NA
	<ul> <li>Fire Dampers</li> </ul>	NA	NA	NA
4.	Smoke managements System			
	Basements	Required	Provided	MR
	• Upper floors	NA	NA	NA
5.	Fire Extinguishers			
<i>J</i> ,	• Total numbers	18 nos.	Provided	MR
	<ul><li>Total numbers</li><li>Types</li></ul>	CO <sub>2</sub> &ABC	Provided	MR
		ISI marked	Provided	MR
6	IS marking     First – Aid Hose Reels	151 marred	Flovided	IVIIX
6.	First – Ald Hose Reels			
terms was made and the second	Total www.haus.an.aaah	1	Provided	MR
	Total numbers on each	I	Flovided	IVIIX
	floor	30 m	Provided	MR
	<ul> <li>Length of hose reel</li> </ul>	30 111	Provided	IVIIX
	hose	5 mm	Provided	MR
	Nozzle diameter		Provided	IVIX
7.	Automatic fire detection and ala			100
	<ul> <li>Type of detectors</li> </ul>	Smoke Heat	Provided	MR
	<ul> <li>Location of Main Panel</li> </ul>	Ground Floor	Provided	MR
	<ul> <li>Location of Repeater</li> </ul>	NA	NA	NA
	Panel		1 11 11 11 11 11 11 11	
	• Alternate source of .	Required	Provided	MR
	power		1 2 2 1 1 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1	
	<ul> <li>Hooters' Location</li> </ul>	NA	NA	NA
8.	MOEFA	Required	Provided	MR
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System			
	<ul> <li>Basements</li> </ul>	Required	Provided	MR
	<ul> <li>Upper Floor</li> </ul>	Required	Provided	MR
	<ul> <li>Sprinkler above false</li> </ul>	Required	Provided	MR
	ceiling			
11.	Internal Hydrants	1.7 .u.s		
				11.1
	Size of riser/down-	150 mm	Provided	MR
	comer			
	<ul> <li>Number of hydrants per</li> </ul>	1	Provided	MR
	floor	16 61	45 96 0	
	Hose Box	1	Provided	MR
12.	Yard Hydrants	1.644.0		
12.	raid frydrains			
	Total number of	Required	Provided	MR
		required	Hovided	IVII
	hydrants Hose Pov	Required	Provided	MR
	• Hose Box	required	Filovided	1711
				I be delle fi

13.	Pumping Arrangements			
	Ground Level			BELLINE :
	<ul> <li>Discharge of main</li> </ul>	1X2280LPM	Provided	MR
	pump			7100
	Head of main pump	50m	Provided	MR
	Number of main pumps	1 1001 51 (	Provided	MR
	Jockey pump out put	180LPM	Provided	MR
	> Jockey pump head	50m	Provided	MR
	Standby Pump out put	1X2280LPM	Provided	MR
	Standby Pump Head	50m	Provided	MR
	Auto Staring/Manual stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	<ul> <li>Terrace level</li> </ul>			1 1
	Discharge of pump	900 lpm	Provided	MR
	Head of the pump	40 m	Provided	MR
	Power supply	Required	Provided	MR
	Auto starting of pump	Required	provided	MR
14.	Captive water Storage for fire fig	ghting		
	<ul> <li>Under ground tank capacity</li> </ul>	1,00,000 litres	Provided	MR
	> Draw of connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank     capacity	20, 000 litres	Provided	MR
15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	Mary In.		
10,	> Pressurization of Lift	Required	Provided	MR
	Shaft			1 1 1
	Pressurization of lift	Required	Provided	MR
	lobby			
	Communication in lift	Required	Provided	MR
	Fireman's Grounding	Required	Provided	MR
	Switch	Required	Trovided	
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area	N. Baille		
	> Total area	NA	NA	NA
	> Location	NA	NA	NA
19.	Fire control room			
	Detector system panel	NA	NA Property of the second of t	NA
	Flow Switch Panel	NA	NA	NA
	> PA System Panel	NA	NA	NA .
	Battery backup	NA	NA	NA
	Building Floor Plans	Required	Provided	MR

20.	Special Fire Protection	NA	NA	NA	
	Systems for Protection of	*			
	special Risks, if any;	4			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Udas Vir Singh

Name Sh Sumil chawdhary

Designation ADO/WP

Designation Del 6