GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- $\underline{\text{cfohq.dlfire@nic.in}}$ No. F.6/DFS/MS/EH/2015/ \mathbb{S} \mathbb{Z} \mathbb{Z} \mathbb{Z} Fax:- 011-23412593

Dated: 20/03/15

FIRE SAFETY CERTIFICATE

Certified that the **Dilli Darbar**, F-20, Upper Ground Floor, District Centre Janak Puri, Janak Palace, New Delhi 110058, is running at upper ground floor only. The above restaurant was issued FSC vide Letter No. F6/DFS/MS/EH/2011/2862 dated 03.11.2011 owned/ occupied by a unit of Super Engineering Works. The Restaurant building was reinspected by the officers concerned of this department on 13.03.2011 in the presence of Sh. Vijay Pal Singh Bisht (Owner) and found that the M/S Super Engineering Works have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. Sh. Vijay Pal Singh Bisht (Owner),
Dilli Darbar, F-20, UGF, Janak Palace, District Centre Janak Puri,
New Delhi 110058.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- Basement shall be used as per the building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	(A)	q				
	Restaurant at Upper Ground Floor (Dilli Darbar, F-20, UG	F, Janak Palace, Distric	t Centre Janak Puri, New	Delhi 110058)		
V	INSPECTIO	N REPORT				
	_		Palace, District Cent	tre Janak Puri,		
i,	New Delhi					
	2. Type of Occupancy : Group D (Assembly)				
	3. Type of Case : Renewal	1 " 1				
*		S/EH/2011/2862 d	ated 03.11.2011.	5)		
	5. Fire Safety directives letter No : Nil.					
	6. Date of inspection : 13.03.201					
	7. Name of Inspecting Officer : D.O. S.K. Tomar and A.D.Q. Sandeep Duggal					
	8. Name and designation of officers					
	From the building side : Sh. Vijay Pal Singh Bisht (Owner)					
	9. Year of Construction : Before 2007					
~		22.01.2015				
S.	Minimum Standards on fire prevention and	NBC/ BBL	Provided at site	Remarks		
No. 1.	fire safety U/R 33 Access to building	Requirement		MR/NMR		
1.	Access to building					
	Road width	Accessible	09 mtrs	M/R		
	Gate width		145 cms	M/R, Being Old		
ě	Width of internal road	2 1		Case		
	Width of Meerican out		06 mtrs	M/R		
2.	Number, Width, Type & Arrangement of Exits			A STATE OF THE STA		
			T	T		
	a. Number of staircases) (/D		
	Upper Floors	Two	Two	M/R		
	 Basements 	Two	Two	M/R		
	b. Width of staircases	2				
			136 & 125 cms	M/R, Being Old		
	Upper FloorBasements		136 & 140 cms	M/R, Being Old		
	Basementsc. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	Fressurization			. ,,		
	d. No. of continuous staircases to		One			
ě.	terrace	2 1 CS 11		ena, ampara		
	e. Width of Corridor		245 cms	***************************************		
	f. Door Size		92 cms	M/R, Being Old		
2	Commontantion		92 CIIIS	WITK, Dellig Old		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		

Fire Rating of shaft doorWater Curtain

Sealing of electrical shafts

Fire Dampers

Smoke Management System

4.	Smoke Management System

•	Basements	-	Exhaust Fans	M/R
			Provided	

N/A

N/A

N/A

N/A

Sealed

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Restaurant at Upper Ground Floor (Dilli Darbar , F-20, UGF, Janak Palace, District Centre Janak Puri, New Delhi 110058)

	Restaurant at Upper Ground Floor (Dilli Darbar, F-20, UGF,		Maturar	M/R		
ı	Upper floors	a 8	Ventilation			
	Fire Extinguishers (Restaurant at Ground Floor only)	8				
	THE DANISMENT (Six no's / floor	Provided	M/R		
	Total numbers	ABC/CO2	Provided	M/R		
284	Types	÷	ISI marked	M/R		
	IS marking	ISI marked	151 marked			
•	First-Aid Hose Reels (Restaurant at Upper Ground Floor only)					
		one	Provided	M/R		
	Total numbers on ground floor	30 mtrs	Provided	M/R		
	Length of hose reel hose	5 mm	Provided	M/R		
	Nozzle diameter					
7.	Automatic fire detection and alarming system (R	estaurant at Upper Gr	round Floor only)			
•			Smoke & Heat	M/R		
	Type of detectors	-	G. Floor	M/R		
•	Location of Main Panel		5.1.55			
	Location of Repeater Panel	Required	Provided	M/R		
*	Alternate source of power	· <u></u>	Near exits	M/R		
	Hooters' Location	Required	Provided	M/R		
8.	MOEFA	Required		- 4/2		
	- Cristom	Required	Provided	M/R		
9.	Public Address System					
10.	Automatic Sprinkler System			2.6/10		
	Dant	Required	Provided	M/R		
	Basement Cround Floor	N/A	Provided	M/R		
	Upper Ground FloorSprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants (Restaurant at Upper Ground Flo	oor only)				
11.	Internal Hydranes (ressumment)		100mm	M/R		
	Size of riser/down-comer		Provided	M/R		
	 Number of hydrants 		Provided	M/R		
	Hose Box		• • • • • • • • • • • • • • • • • • • •			
12.	Yard Hydrants					
			Provided			
	Total number of hydrants		Provided			
	Hose Box Pumping Arrangements (common with DDA).	Janak Palace com	olex)			
13.	Ground Level			M/R		
	Discharge of main Pump		2400 LPM			
	Head of Main pump		88 mtrs	M/R		
	Number of main pumps		02	M/R		
12	Jockey Pump out put		240 LPM	M/R		
	Jockey pump head		88 mtrs	M/R		
			2400 LPM	M/R		
	Standby Pump out put		88 mtrs.	M/R		
	in the second se		Required	M/R		
	Standby Pump HeadAuto Starting/Manual Stopping		Required	Supplemental State of		
1	> Auto Starting/Manual Stopping					

Restaurant at Upper Ground Floor (Dilli Darbar, F-20, UGF, Janak Palace, District Centre Janak Puri, New Delhi 110058)

5	Pump House Access		Provided	M/R
	Terrace level			
	Discharge of pump	N/A	N/A	N/A
i	➤ Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
*	Auto Starting of pump	N/A	N/A	N/A
4.	Captive Water Storage for fire fighting (common w	vith DDA Januar P	alace complex)	
••	Underground tank capacity		200000 Ltrs	M/R
	> Draw-off connection		Provided	M/R
	Fire service inlet		Provided	M/R
	Access to tank		Provided	M/R
	Overhead Tank capacity	 N/A	N/A	N/A
		Required.	Provided	M/R
5	Exit Signage.			
		к до 1993 година ¹ 1		
6.	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft			N/A
	Pressurization of Lift lobby	N/A	N/A N/A	N/A N/A
*	Communication In lift Car	N/A		
	Fireman's Grounding Switch	Required	Provided	M/R
	Lift Signage	Required	Provided	M/R
		Required	Provided DG Set 75 KVA	M/R
17.	Standby power supply			
8.	Refuge Area.		* x · c · · · · · · · · · · · · · · · · ·	1/8
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire Control Room Detector System Panel	N/A	Provided	N/A
ě.	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel		* *	N/A
	Battery backup	N/A	Provided	
۳	- Buttery Buckup	N/A	Provided	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	IN/A	18/7	1 1/ / / /

112

Restaurant at Upper Ground Floor (Dilli Darbar, F-20, UGF, Janak Palace, District Centre Janak Puri, New Delhi 110058)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/EH/2011/2862 dated 03.11.2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note: - The restaurant is at upper ground floor of the Janak Palace (DDA), Janak Puri District Centre and have common fire safety installations.

Signature of Inspecting Officer

Name: - S.K. Tomar

Designation:- Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy.C.F.O (South Zone)

Alay 3/15