GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2015/ 52 \467

Dated: 31/03/15

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Surya Palace** located at 12A/16, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, Ground Floor plus four upper floors, using basement as hall/storage, ground floor as reception & 04 guest rooms, first & second floor each having 09 guest rooms respectively, third floor having 04 guest rooms (Total 26 guest rooms) and a pantry for staff with two staff rooms on fourth floor was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2012/1735 dated 14.05.2012 owned/ occupied by Sh. Sachin Suri. The guest house building was reinspected by the officers concerned of this department on 11.03.2015 in the presence of Sh. Rakesh Talwar (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Joint Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Re. No.3674/Joint C.P./Lic.(H), Dated 23.02.2015)
- 2. Sh. Sachin Suri (Owner) Hotel Surya Palace, 12A/16, WEA, Karol Bagh, New Delhi – 110005.

	1 Name 8	TION REPORT					
	1. Name & address of the building: Hotel Surva Palace 13 Alse 1.150 Kg.						
	2. Type of Occupancy	DESTACTION CONTRACT HOUSE					
	3. Type of Case	New Case/Renewal Letter No. F.6/DFS/MS/GH/2012/1735 Date 14.05.2					
	4. Details of Previous NOC						
	5. Fire Safety directives letter No :						
	6. Date of inspection						
	7. Name of Inspecting Officer						
	8. Name and designation of officers						
	From the building side :						
	9. Year of Construction :						
	10. Applicant's letter No.	3674/Joint C.	P/Lic. (H) date	1 90 09 900			
	J Scaridards Off file	NBCIBBL	Provided at	Remarks			
0.	prevention and fire safety U/R 33	Requirement	site				
	Access to building	The state of the s	JICC	MR/NMR			
	 Road width 	Accessible	09mtr	100			
	 Gate width 	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		MR			
	 Width of internal road 		185cms	MR			
	Number, Width, Type & Arrangement		Mar.	_			
	a. Number of staircases	or Exits		•			
	• Upper Floors						
	Basements	One	One	MR			
	b. Width of staircases	-do-	-do-	MR			
	Oppermon	125 cms	125 cms	MR			
	Basements		90 cms	The state of the s			
	c. Protection of exits	desired and the second	10 000	MR, Old C			
	 Fire check door 	Secretary 2		And the second s			
	• pressurization			Appropriate to the control of the co			
	d. No. of continuous staircases to		- Secretary				
	terrace			Annual Control of the			
	e. Width of Corridor		One				
	f. Door Size		330 cms, 180 cms	-			
-		-	80 cms x 200 cms	and the second s			
	Compartmentation			Construence of the second seco			
	Fire check door	,					
	Sealing of electrical shafts		Management				
	Fire Rating of shaft door	-	Sealed	Stellang			
	Water Curtain	-					
	• Fire Dampers		Manager 1				
	The same and the s						
	Smoke Management System						
	* Basements	30 a/c per	Exhaust Fons	The second secon			
	Upper floors	hour	are Provided	MR			
		\ \ \ \	latural Ventilation	MR			

(No

M134. 12A/16, WEA, Karol Bagh, New Delhi-110005.

	Pump House Access			2		
	Terrace level			3		
	Discharge of pump	450 LPM	450 LPM	DO C		
	Head of the pump	THE RESERVE OF THE PARTY OF THE		MR		
	Power Supply	30 M Required	30 M Provided	MR		
	Auto Starting of pump	1	7 30 114 64	1.11		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity					
	> Draw-off connection					
	Fire service inlet			-		
	Access to tank					
	Overhead Tank capacity	5000 Ur	Soooldr	MR		
15.	Exit Signage.	5000 Ltr Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	-		1		
	 Pressurization of Lift lobby 			- ;		
	Communication In lift CarFireman's Grounding Switch		Parish	N10		
		0 . 4	Provided	MR		
	Lift Signage	Kequired	- do -	MR		
		- do -	-do-	MR		
17.	Standby power supply	Required - do - Required	Provided	MR		
×			=	j		
18.	Refuge Area.					
	> Total Area		_	-		
	> Location					
19.	Fire Control Room					
	Detector System Panel		- 12 E			
	• Flow Switch Panel			1		
	PA System Panel					
	Batter backup					
	Building Floor Plans		Provided			
20.	Special Fire Protection System for					
	Protection of special Risks, if any:					

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6 NFS MS BH 2012 1735 dated 14.05.2012 renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

17/3/17

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Abett. Divisional Officer