GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001 Fax: 23412593, Tel:- 011- 23414333

No.F6/MS/DFS/GH/2015/ 52 435

Dated: -- 26 3 15

(Dr. G. C. Misra)

Chief Fire Officer

FIRE SAFETY CERTIFICATE

Issued - 26 (3) -- at New Delhi by.

Copy to:-

- (1) Joint. Commissioner of Police Licencing(H) 1st Floor, PS Defence Colony, New Delhi.
- (2) The Manager Zara Grand, H-2A, Green Park Extension, New Delhi-110016,

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Zara Grand(Formerly Hotel Green Palace), H-2A, Green Park Extn, New Delhi
- 2. Type of occupancy:- Group-A,Residential (Lodging and Rooming House)

3. Type of case: - Change of Name in FSC /Renewal.

- 4. Details of previous NOC: F6/DFS/MS/ GH/ 2012/4495 dated 06/12/2012. issued to Hotel Green Palace
- 5. Fire safety directives No.- Nil

6. Date of inspection: 28/02/2015

7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)

8. Name & designation of officer From the building side: - Mr.Bhupinder Singh

9. Year of construction:- 1989

10. Applicant's letter No:- Nil dated: 29/01/2015.

Building is comprised of Basement, Ground + 03 Upper Floors.Guest house is running in ground and 03 upper floors

SI. No	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
	Access to Building						
	1) Road width	9m	Provided	MR			
	2) Gate width	Required	Approachable	MR			
	3)Width of internal road	N/A	N/A	N/A			
	Number, Width Type & Arrangement of Exits						
	A. Number of staircases						
	1. Upper floors	01	Provided	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	1.25 m	Provided	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	Required	01 nos.	MR			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	N/A	N/A	N/A			
	Compartmentation						
-	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System						
	1) Basements	30 a/c per hour	N/A	N/A			
	2) Upper floors	12 a/c per hour	Natural	MR			
	Fire Extinguishers						
•	1) Total numbers		10 Nos. Provided	MR			
	2) Types	ISI Marked	ABC, Co2	MR			
	3) ISI marking		Yes	MR			
	First-Aid Hose Reel						
0	Total number of each floor	Required 01 no.	Provided	MR			
	2) Length of hose reel hose	30 m	Yes	MR			
	3) Nozzle diameter	5 mm	Yes	MR			



7.	Automatic Fire Detection & Alarming Sy	stem		19		
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
11.	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per floor	N/A	N/A	N/A		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
14.	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
12	,	11//11	14/17	1		
13.	Pumping Arrangement	NI/A	N/A	N/A		
	1) Ground level	N/A	N/A N/A	N/A		
	a) Discharge of main pump	N/A	N/A N/A	N/A		
	b) Head of main pump	N/A	N/A N/A	N/A N/A		
	c) Number of main pump	N/A		N/A		
	d) Jockey pump out put	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual stopping	N/A	N/A	N/A		
	2)Terrace level					
	a) Discharge of pump	450 LPM	Provided	MR		
	b) Head of pump	Required	30m	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.0	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	10,000 Ltrs.	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
10.	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
15		Yes	Provided DG Set	MR		
17.	Stand by Power Supply	N/A	N/A	N/A		
18.	Refuge Area	N/A N/A	N/A	N/A		
	Total area location		N/A N/A	N/A		
19.	Fire Control Room	N/A		N/A N/A		
	a) Detector system panel	N/A	N/A	N/A N/A		
	b) Flow switch panel	N/A	N/A			
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		

20. Special Fire Protection System for Protection of special Risk, if any:

N/A

The fire safety systems provided in the guest house were tested and found functional at the time of inspection. The shortcomings issued vide letter no.F6/DFS/MS/GH/2014/2927 dated: 23/12/2014 has been removed. The owner has submitted an affidavit that the basement floor is not his property.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/ GH/2012/4495 dated 06/12/2012, renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended

Accordingly DFA is put up for perusal and signature pl.

(4)3)15

Signature of the inspecting officer

Name: - D.B.Mukherjee.

Designation: - Assistant Divisional Officer (BCP)

Dollann

9/8/15