

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/MS/DFS/SZ/EH/2015/ 82/503

Dated: 09/04/15

FIRE SAFETY CERTIFICATE

Certified that the Desi Roots Café & Bar (a unit of Lemon Seeds Hospitality Pvt. Ltd.) located at shop no.G-16-17 & G-30-31, Salcon Rasvillas Mall, Plot No.- D-1 Distt. Center, Saket, New Delhi-110017, comprised of basement, ground + five upper floors owned/occupied by a unit of Lemon Seeds Hospitality Pvt Ltd was issued FSC vide letter no.F6/DFS/MS/2011/EH/3667 dated: 22-12-2011. The restaurant is running at ground floor and inspected by the officer concerned of this department on 30/03/15 in the presence of Mr.Nikhil and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group – D, Assembly Building(Restaurant) with effect from ~~22-12-2011~~ 09/04/15 the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued ~~22-12-2011~~ 09/04/15 at New Delhi by.


(Dr. G.C. Misra)
Chief Fire Officer
Tel: 011-23414333



Copy to:-

- (1) Dy. Health Officer, South Zone
Aurbindo Marg, Green Park
New Delhi
- (2) Mr. Rajesh Gupta
M/S Desi Roots Café & Bar
G-16-17 & 30-31, Salcon Rasvillas Mall,
Plot No-D-1 Distt Center, Saket, New Delhi-110017,

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of NBC
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Desi Roots Café & Bar (a unit of Lemon Seeds Hospitality Pvt. Ltd.)
(Formerly Tryst Restaurant) Shop no.G-16-17& 30-31, Salcon
Rasvillas Mall, Plot No D-1 Distt. Center, Saket, New Delhi-110017
 2. Type of occupancy:- Group – D, Assembly Building (Restaurant)
 3. Type of case:-Renewal
 4. Details of previous NOC:- F6/DFS/MS/2011/EH/3667 dated 22/12/2011
 5. Fire safety directives No.- Nil
 6. Date of inspection:-30/03/15
 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
 8. Name & designation of officer From the building side:- Mr. Nikhil
 9. Year of construction:- 2007.
 - 10.Applicant's letter No:-No.D/2018/DHO/SZ dated 24/12/14
- Building is comprised of Basement, Ground + Five Upper Floors. Restaurant is running at ground floor.

Sl.No	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement BBL/NBC	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	9mtrs	Provided	MR
	2) Gate width	Required	Approachable by road	MR
	3)Width of internal road	06	Provided	MR
2.	Number, Width Type & Arrangement of Exits		Provided and maintained by Mall	
	A. Number of staircases			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D.No. of continuous staircase to terrace	Required	Provided by mall	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	02 m/1.5m	1.82m, 2.07m, 1.80m	MR (Old Case)
3.	Compartmentation		Provided and maintained by Mall	
	1) Fire check door	Required	Provided by Mall	MR
	2) Sealing of electrical shafts	Required	Provided by Mall	MR
	3) Fire rating of shaft door	Required	Provided by Mall	MR
	4) Water curtain	Required	Provided by Mall	MR
	5) Fire Dampers	Required	Provided by Mall	MR
4.	Smoke Management System		Provided and maintained by Mall	
	1) Basements	30 a/c per hour	Provided by Mall	MR
	2) Upper floors	12 a/c per hour	Provided by Mall	MR
5.	Fire Extinguishers		Provided and maintained by Mall	
	1) Total numbers	ISI Marked	06 Nos.	MR
	2) Types		ABC, Co2 ,Foam	MR
	3) ISI marking		Yes	MR



6.	First-Aid Hose Reel	Provided and maintained by Mall		
	1) Total number of each floor	Required	01 no. provided near restaurant	MR
	2) Length of hose reel hose	30 m	Provided	MR
	3) Nozzle diameter	5mm	Provided	MR
7.	Automatic Fire Detection & Alarming System:	Provided and maintained by Mall		
	1) Type of detectors	Smoke	Provided by Mall	MR
	2) Location of main panel	Fire control room	Provided by Mall	MR
	3) Location of repeater panel	Every floor	Provided by Mall	MR
	4) Alternate source of power	Required	Provided by Mall	MR
	5) Hooter's Location	Every floor	Provided by Mall	MR
8.	MOEFA	Provided and maintained by Mall		
9.	Public Address System	Provided and maintained by Mall		
10.	Automatic Sprinkler System	Provided and maintained by Mall		
	1) Basement	Required	Provided by Mall	MR
	2) Upper floors	Required	Provided by Mall	MR
	3) Sprinkler above false ceiling	Required	Provided by Mall	MR
11.	Internal Hydrants	Provided and maintained by Mall		
	1) Size of riser/down-comer	150mm	Provided by Mall	MR
	2) Number of hydrants per floor	Required	Provided by Mall	MR
	3) Hose box	Required	Provided by Mall	MR
12.	Yard Hydrants	Provided and maintained by Mall		
	1) Total number of hydrants	Required	Provided by Mall	MR
	2) Hose box	Required	Provided by Mall	MR
13.	Pumping Arrangement	Provided and maintained by Mall		
	1) Ground level			
	a) Discharge of main pump	2280 lpm	Provided	MR
	b) Head of main pump	70m	70m	MR
	c) Number of main pump	02	Provided	MR
	d) Jockey pump out put	180 lpm	Provided	MR
	e) Jockey pump head	70m	70m	MR
	f) Stand by pump output	2280 lpm	Provided Diesel Engine	MR
	g) Stand by pump head	70m	70m	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting	Provided and maintained by Mall		
	1) Under ground tank capacity	1,50,000 ltrs.	Provided.	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	20000 ltrs.	Provided	MR
15.	Exit Signage.	Provided and maintained by Mall		

16.	Provision of Lifts.	Provided and maintained by Mall		
	a) Pressurization of lift shaft	Required	Provided by Mall	MR
	b) Pressurization of lift lobby	Required	Provided by Mall	MR
	c) Communication in lift car	Required	Provided by Mall	MR
	d) Fireman's switch	Required	Provided by Mall	MR
	e) Lift signage	Required	Provided by Mall	MR
17.	Stand by Power Supply	Provided and maintained by Mall		
18.	Refuge Area	Provided and maintained by Mall		
	Total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
19.	Fire Control Room	Provided and maintained by Mall		
	a) Detector system panel	Required	Provided by Mall	MR
	b) Flow switch panel	Required	Provided by Mall	MR
	c) PA system panel	Required	Provided by Mall	MR
	d) Battery backup	Required	Provided by Mall	MR
	e) Building floor plan	Required	Provided by Mall	MR
20.	Special Fire Protection System for Protection of special Risk, if any:	N/A		

The fire protection system provided in the restaurant were checked and found functional at the time of inspection.

The mall has issued FSC vide letter no. F6/DFS/MS/2015/SZ/437 dated 26/03/2015.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rules 3 5 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up for perusal and sign. please.

[Handwritten Signature]
6/4/15

Signature of the inspecting officer
Name :- D.B. Mukherjee.
Designation :- Assistant Divisional Officer.