## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in No.F.6/DFS/MS/School/2015/ \$72 / 57/ 6 Fax:- 011-23412593 Dated: 17/04//5

## FIRE SAFETY CERTIFICATE

Certified that the Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018 comprised of ground floor plus two upper floors, was issued NOC by this department vide letter F6/DFS/MS/2011/850 dated 10.05.2011. The School building was re-inspected by the officer concerned of this department on 30.03.2015 in the presence of Sh. Pardeep (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 17/09/05 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- The Manager, Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground plus two upper floors (Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018)

## **INSPECTION REPORT**

1. Name & address of the building: Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018.

2. Type of Occupancy : Educational3. Type of Case : Renewal

4. Details of Previous NOC : F6/DFS/MS/2011/850 dated 10.05.2011

5. Fire Safety directives letter No : N/A

6. Date of inspection : 30.03.2015

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. Pardeep (Manager)

9. Year of Construction : 1993-94

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ Dt. of edu. Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road width	Accessible	09 mtrs	M/R		
	Gate width		4.0 mtrs	_		
	<ul> <li>Width of internal road</li> </ul>		_			
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Upper Floors	02 No.	02 No's	M/R		
	Basements	N/A	N/A	No basement		
	b. Width of staircases					
	Upper Floor	1.5 mtrs	1.5 & 1.0 mtrs	M/R		
	• Basements	N/A	N/A	No basement		
	c. Protection of exits	14/11	11/11	110 basement		
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	J. No. of continuous stains and to	IN/A	N/A	IN/A		
	d. No. of continuous staircases to terrace	27/1		77/1		
	e. Width of Corridor	N/A	one	N/A		
	c. Width of Confidor	1.5 mtrs.	1.5 mtrs.	M/R		
	f. Door Size			M/R (Students less		
		100 cms	120 cms	than 45 in each class		
3.		100 cms	120 CIIIS			
).	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	Basements	N/A	N/A	No basement		

Ground plus two upper floors (Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018)

	Upper floors		Natural	M/R			
-			ventilation				
5.	Fire Extinguishers						
	<ul> <li>Total numbers</li> </ul>	07 no's	Provided	M/R			
	<ul> <li>Types</li> </ul>	ABC/CO2 type	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			
6.	First-Aid Hose Reels	151 markeu	201 Marked	IVI/IX			
	<ul> <li>Total numbers on each floor</li> </ul>	One	Provided	M/R			
	<ul> <li>Length of hose reel hose</li> </ul>	30 mtrs	Provided	M/R			
	Nozzle diameter	5 mm	Provided	M/R			
			Tiovided	IVI/R			
7.	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A N/A	N/A	N/A N/A			
	a Harry II	IN/A	N/A	N/A			
3.	Hooters' Location     MOEFA	Verille September		11/11			
	MOEFA	N/A	N/A	N/A			
).	Public Address System	N/A	Provided	N/A			
10.	Automatic Sprinkler System		2.0.1404	IV/A			
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	100 mm	N/A			
	Number of hydrants per floor	N/A	one	N/A			
	Hose Box	N/A	one	N/A			
2.	Yard Hydrants	1		11/11			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A N/A			
13.	Pumping Arrangements						
	Ground Level		1				
	Discharge of main Pump	N/A	N/A	NI/A			
	Head of Main pump	N/A		N/A			
	Number of main pumps		N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			

NI

Ground plus two upper floors (Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018)

-1			ock, vikaspuri, Ne	w Deini 1100		
	Pump House Access  Terrace level	N/A	N/A	N/A		
	Discharge of pump					
	Head of the pump	450 LPM	450 &180 LPM	M/R		
	Power Supply	40 mtrs	Provided	M/R		
	Auto Starting of pump	N/A	N/A	N/A		
	and or bump	N/A	Provided	N/A		
14.	Captive Water Storage for fire fighting					
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A			
	Draw-off connection	N/A		N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank		Provided	N/A		
	<ul> <li>Overhead Tank capacity</li> </ul>	N/A	N/A	N/A		
		10000 ltrs	Provided	M/R		
15.	Exit Signage.	Required	Provided	M/R		
16.	Dec. 1 to a via					
10.	Provision of Lifts.	No Lift				
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A		N/A		
	Lift Signage		N/A	N/A		
		N/A	N/A	N/A		
17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	Total Area	N/A	N/A	DT/A		
	Location			N/A		
×		N/A	N/A	N/A		
9.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel     PA Control	N/A	N/A			
	PA System Panel	N/A		N/A		
	Battory backup		N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
).	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

Ground plus two upper floors (Columbia Junior School, F- Block, Vikaspuri, New Delhi 110018)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F.6/DFS/MS/2011/850 dated 10.05.2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note: - As per the letter given by the manager of the school (Placed at C-11), there are less than 45 students in each class room.

Signature of Inspecting Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Name

Designation:- Asstt. Divisional Officer

Designation