GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/2015/52/536

Dated: 15/64/15

FIRE SAFETY CERTIFICATE

Certified that M/s Sneh Designs Pvt. Ltd., located at A-32/B-1 MCIE, Mathura Road, New Delhi comprised of basement, ground plus one & half floor was granted NOC by this department vide letter no. F.6/DFS/MS/BP/92/944 dated 19.05.92. The premises was reinspected by the officers concerned of this department on 24-03-2015 in the presence of Mr. Vikram Khandelwal, director and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class Commercial with effect from _/s/ou//s for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on 15/04/15 at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

 The Director, M/s Sneh Designs Pvt. Ltd., located at A-32/B-1 MCIE, Mathura Road, New Delhi.

2. The Executive Engineer (Bldg.), MCD, Town Hall, New Delhi.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s Sneh Designs Pvt. Ltd., located at A-32/B-1 MCIE,

Mathura Road, New Delhi

2. Type of Occupancy

: Industrial

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/BP/92/944 dated 19.05.92

5. Fire Safety directives letter No : F6/DFS/MS/BP/88/639 dated 12.05.88

6. Date of inspection

: 24.03.2015

7. Name of the Inspecting Officers : M.K Chattopadhyay, ADO (M. Road)

8. Name and designation of officers

from the building side

Mr. Vikram Khandelwal, director

9. Year of Construction

: 1987-88

10. Applicant's letter No.

: nil dated 30-01-2015

	Building is comprised of base	sement, ground plu	is one & half floor	
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	Road width	09 mts	Provided	MR
	Gate width	4.5 mts	Provided	MR
	Width of internal road	Required	Provided	MR
2	Number, Width, Type & Arrangement of	of Exits		
	a. Number of staircases	-	_	-
	Upper Floors	02	provided	MR
	Basements	02	Provided	MR
	b. Width of staircases	-	-	-
	Upper Floors	1.25 mts each	Provided	MR
	Basements	1.25 mts each	Provided	MR
	c. Protection of exits	-	-	-
	Fire check door	Required	Provided	MR
	 Pressurization 	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	02	02	MR
	g. Width of Corridor	1.25 mts	Provided	MR
	h. Door Size	1.25 mts	Provided	MR
3	Compartmentation.			

	P' about door	Required	Provided	MR		
	• Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts By Property of shaft door.	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers		,			
5	Smoke Management System.	30 a/c per hour	Provided	MR		
	• Basements	12 a/c per hour	N/A	N/A		
	• Upper floors	12 dre per mour	N/A	14/21		
	Fire Extinguishers		Duaridad	MR		
	 Total numbers 	12	Provided	MR		
	 Types 	ABC type	Provided	MR		
	IS marking	ISI marked	Provided	IVIIV		
	First-Aid Hose Reels.		Duaridad	MR		
	Total numbers on each floor	01	Provided Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	FIOVIGE			
	Automatic fire detection and alarming system.					
	Type of detectors	N/A	Provided(Smoke)			
	Landian of Main Panel	N/A	Provided at GF			
		N/A	N/A	N/A		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of power	N/A	Provided at			
	Hooters' Location	2 1/2 7	each floor			
	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
	Automatic Sprinkler System.			T		
10	Dt	Required	Provided	MR		
	BasementUpper Floor	Required	Provided	MR		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
1.1	I down al Hydrants					
11	Size of riser/down-comer	N/A	Provided (100 mm)			
	Number of hydrants per floor	N/A	Provided(1)			
	Hose Box	N/A	Provided(1)			

12	Yard Hydrants.				
	 Total number of hydrants 	N/A	Provided(2)		
	Hose Box	N/A	Provided(2)		
13	Pumping Arrangements.				
	Ground Level	N/A	N/A	N/A	
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual	N/A	N/A	N/A	
	stoppingPump House Access	N/A	N/A	N/A	
	Terrace level	_		-	
	Discharge of pump	900 LPM	Provided	MR	
	➤ Head of the pump	60 mts	Provided	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
14	Captive Water Storage for fire fighting	5.			
	 Underground tank capacity 	25,000 lts	Provided	MR	
	Draw-off connection	Required	Provided	MR	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity	5, 000 lts	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	 Pressurization of Lift Shaft 	N/A	N/A	N/A	
	 Pressurization of Lift lobby 	N/A	N/A	N/A	
8	• Communication In lift Car	N/A	N/A	N/A	
	• Fireman's Grounding Switch	N/A	N/A	N/A	

	* 10 G	N/A	N/A	N/A
1.7	Lift Signage	Required	Provided	MR
17	Standby power supply		apakante manta 41.01	
18	Refuge Area.		N/A	N/A
	> Total Area	N/A		
	> Location	N/A	N/A	N/A
19	Fire Control Room	27/4	N/A	N/A
	 Detector System Panel 	N/A	IN/A	* 11 * -
		N/A	N/A	N/A
	Flow Switch Panel		NI/A	N/A
	 PA System Panel 	N/A	N/A	
	Batter backup	N/A	N/A	N/A
		NI/A	N/A	N/A
	Building Floor Plans	N/A	11/71	2. 80 %
20	Special Fire Protection Systems for		Provided (02 ABC type fire extinguishers	MR
	Protection of special Risks, if any	Required	near electric panel)	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The shortcomings issued by this department vide letter No. F.6/DFS//MS/2014/2969 dated 26.12.2014 has been compliance by the building management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/BP/92/944 dated 19.05.92, renewal under Delhi Fire Service Act- 2007 & Rules- 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY

Designation: - Asstt. Div. Officer (M.Rd)