GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2015/ NO2/668

Dated : 01/01/15

FIRE SAFETY CERTIFICATE

Certified that the Sameer Guest House located at 5937-38, Ballimaran, Delhi comprised of Ground + 4 Upper Floors (Ground floor- reception + 01 hall,1st floor- 11 guest room,2nd floor-11 guest room ,3rd floor - 11 guest room & 4th floor - store room & staff room = 33 guest rooms) was granted FSC by this department vide letter No.F6/DFS/MS/GH/2012/1637 dated 04/05/2012. The premise was re-inspected by the officer concerned of this department on 18/04/15 in the presence of Mr. Kayum (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group A-1 (33 guest rooms at 1st to 3rd floor only) with effect from -01/65-/15----- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued en for first at New Delhi by.

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

Ph: - 011-23414333

Copy to: (1) The Joint Commissioner of Police (Lic.), 1st Floor, Police Station, Defence Colony, New Delhi.

> The Manager, Sameer Guest House, 5937-38, Ballimaran, Delhi.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

M-23

INSPECTION REPORT

Sameer Guest House, 5937-38, Ballimaran, 1. Name & address of the building:-

Delhi.

Residential Group A-1 Ground+ 4 Upper 2. Type of occupancy:-

Floors (33 guest rooms) (Ground floorreception + 01 hall,1st floor- 11 guest

room,2nd floor- 11 guest room,3rd floor - 11 guest room & 4th floor - store room & staff

room)

3. Type of case:-Renewal

No. F6/DFS/MS/GH/2012/1637 dated 4. Details of previous FSC:-

04/05/2012.

N/A 5. Fire safety directives No.-

18/04/15 6. Date of inspection:-

7. Name of the inspecting officer:-A.D.O. Mehmood 8. Name & designation of officer

From the building side:-

Mr. Kayum (Manager). 9. Year of construction:-

5207/Joint.C.P./Lic. (H) Dated 30/03/15 10. Applicant's letter No:-

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (PSS Area)	Provided at site PSS	Remarks MR/NMR
1.	Access to Building			
	1) Road width	Required	10 Mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arran	gement of Exits		
	A. Number of staircases			
	1. Upper floors	01 No	01 No.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.06 mtr.	1.06 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01 No.	01 No.	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	91 cms.	91 cms.	MR
3.	Compartmentation			-
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 ACPH	N/A	N/A

	2) Hanna floors	12 ACPH	N/A	N/A
-	2) Upper floors Fire Extinguishers	12 110111		
5.		14 Nos.	14 No.	M
	1) Total numbers 2) Types	ABC & CO2	ABC, CO2 & W.CO2	MR
	1.	ISI	Yes	MR
	3) ISI marking	151	105	
6.	First-Aid Hose Reel	01 No.	01 No.	MR
	1)Total number at each	01140.		
-	floor	30 m	30 m	MR
	2) Length of hose reel hose	5 mm	5 mm.	MR
-	3) Nozzle diameter Automatic Fire Detection & A			
7.		N/A	N/A	N/A
	 Type of detectors Location of main panel 	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
0	5) Hooter's Location MOEFA	N/A	N/A	N/A
8.	Public Address System	Required	Provided	MR
9.	Automatic Sprinkler System	10040110		
10.	1) Basement	N/A	N/A	N/A
		N/A	N/A	N/A
	2) Upper floors3) Sprinkler above false	N/A	N/A	N/A
		1 1/12		
1.1	ceiling Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
12	Pumping Arrangement			
13.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	* N/A	N/A	N/A
	c) Number of main pur	np N/A	N/A	N/A
	d) Jockey pump out pu	1	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump outp		N/A	N/A
	g) Stand by pump head		N/A	N/A
	h) Auto starting/Manus		N/A	N/A
	stopping			
	2) Terrace level	V		1.00
	a) Discharge of pump	Required	450 LPM	MR
	b) Head of pump	Required	35 mtr.	MR
	c) Power supply	Required	Provided	MI
) 101101 5547-7			B
				B

MIL

M-25

2-1-3	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
1374	1) Under ground tank capacity	N/A	N/A	N/A	
11	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	5,000 Ltrs.	5,000 Ltr.	MR	
15.	Exit Signage.	Required	Required	MR	
16.	Provision of Lifts.			IVIIC	
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
1.77	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
Đ	Total area location	N/A	N/A	N/A	
9.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
-	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System any:	for Protection of	special Risk, if	N/A	

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter

No.F6/DFS/MS/GH/2012/1637 dated 04/05/2012, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

Assistant Divisional Officer

D.O. (Central)

24/N/15