FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/ms/2015/W2/659

Dated: 01/05/15

FIRE SAFETY CERTIFICATE

Certified that the GREEN LOUNGE NORTH BANQUET (A Unit of nagpal hospitality Pvt Ltd) located at Ground and 1st Floor at C-93, WazirPur Industrial Area, Delhi - 110052 in a building comprised of Basement + Ground Floor +Mez + one Upper Floor. The premises was inspected by the officers concerned of this department on 08-04-2015 in the presence of Sh. Jadish Nagpal (Owner) and found that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from of for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .0! \. 55/1.\. at New Delhi by.

(Santokh Vingh) Chief Fire Officer Delhi Fire Service Phone -23414250

Copy to:

1. Sh. Jadish Nagpal, C-93, Wazir Pur Industrial Area, Delhi – 110052

2. The Dy Health Officer, Civil Line Zone, Public Health Department, 16' Rajpur Road, Delhi-

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Green Lounge North Banquet (A unit of Nagpal Hospitality) Pvt Ltd, Located at Ground & 1st Floor, C-93, WazirPur industrial Area, Delhi – 110052

2. Type of Occupancy

: Assembly(G. Floor + one upper floor, in a

building comprised of Basement + Ground +Mez. +one upper Floor)

3. Type of Case

: New

4. Details of previous NOC

: Nil

5. Fire Safety directives Letter No. :F.6/DFS/MS/BP/2014/13Dated17/01/14 (For

Industry) The occupancy is change to assembly.

Plot Area=1923 m²

6. Date of inspection

: 08/04/2015

Covered Area:-Basement=317m² (storage)

7. Name of the Inspecting Officer: Udaivir singh ADO (WP)

G.Floor=907M² (Banquet)

8. Name and designation of Officer

Mez. Floor=201M²(Offices) 1st Floor=880M²(Banquet)

from the building side

: Sh. Nagpal

9. Year of Construction

2008

10. Applicant's letter No.

: DHO/CLZ/2014/1866 Dated 21/11/2014

S	Minimum standards on fire	BBL	Provided at site	Remarks			
No	prevention and fire safety U/R 33	Requirements		MR/NMR			
l.	Access of building						
	Road width	12 m	Provided	MR			
	 Gate width 	5 m	Provided, on main Road	MR			
	 Width of internal road 	NA	NA	NA			
2.	Number, width, Type & Arrangements of exits (Basement being used by cinesale as astore)						
	a. Number of staircase	S	/				
	 Upper floors 	2	3 provided	MR			
	 Basements 	NA	Two Provided	NA			
	b. Width of staircases						
	• Upper floors	2X200cm	1X200cm,1X182cm &1X 205 cm	MR			
	 Basements 	NA	1X142cm &1X132cm	NA			
	c. Protection of exits						
	 Fire check door 	Required	Provided	MR			
		NIA	NA	NA			
	 Pressurization 	NA					
	 Pressurization d. No of continuous staircase to terrace e. Width Of Corridor 	2	provided	MR			

N/B

	f. Door Size	2X200cm	GF=2X245cm,1X365cm &1X190cm FF=2X200cm,1X205cm					
3.	Compartmentation							
	Fire check door	Required	Provided	MR				
	 Sealing of electrical shafts 	NA	NA	NA				
	• Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
4.	Smoke managements System		Basement used by Cinesale as a store					
	Basements	30 a/c per hour	Provided	NA				
	Upper floors	12 a/c per hour	Provided	MR				
5.	Fire Extinguishers							
	• Total numbers	15 nos.	Provided	MR				
	TypesIS marking	ABC & CO ₂	Provided	MR				
		ISI marked	Provided	MR				
6.	First – Aid Hose Reels							
	Total numbers on each floor	Required	Provided	MR				
	 Length of hose reel hose 	30 m	Provided	MR				
	Nozzle diameter	5 mm	Provided	MR				
7.	Automatic fire detection and alar	ming system						
	Type of detectorsLocation of Main Panel	Smoke	Provided	MR				
	Location of Repeater Panel	Required	Provided at Ground Floor	MR				
	Alternate source of power	Required	Provided	MR				
	1	Required	Provided	MR				
	Hooters' Location	NA	NA	NA				
8.	MOEFA.	Required	Provided	MR ~				
9.	Public Address System	Required	Provided	MR				
10.	Automatic Sprinkler System							
	Basements	Required	Provided	MR				
	Upper Floor	Required	Provided	NR				
	 Sprinkler above false ceiling 	NA	NA	NA				
11.	Internal Hydrants							
	Size of riser/down- comerNumber of hydrants per	100 mm	Provided	MR				
	floor	2	Provided	MR				

		Hose Box			Mo	1		
	12.	Yard Hydrants			2	Pro	vided	MR
-								
		• Total number	r of hydra	enta (14			
		Hose Box	or myura	ants 04			Provided	MR
-	1 -			T	Page 1			
-	13.	Pumping Arrangeme • Ground Leve	ents (All t	he num	Required		Provided	MR
		 Ground Leve 	re puin	ps are con	mecte	d with DG Se	et)	
	• Discharge of main pump Head of main pump							
				60004		provided	MR	
		Number of ma	in numne	5 01			provided	MR
	Jockey pump out put Jockey pump head			-	&OLP	~	provided	MR
				60	mtrs	Ta		MR
		Standby Pumr	Out put		22801	Om	provided	MR
		Standby Pump	Head		mtrs	1110	provided	MR -v
		Auto Staring/N	I anual		quired	7	provided	MR
		Stopping		100	quired		provided	MR
		Pump House A	ccess	Re	quired		D	
		• Terrace level		100	141100		Provided	MR
		Discharge of pu	ımp	900	lpm		D	
		Head of the pur	np	60 1		1	Provided	MR
		- o rect supply			uired		Provided	MR
14.	C	- Tate Starting Of	pump	D	uired		Provided	MR
14.	The water Storage for fire fi			hting	wii o d		Provided	MR
	Under ground tank			5000014				
	capacity			Required			provided provided	MR
		Draw of connection						
		Fire service inlet		Requ			rovided	MR
		Access to tank		Requ			provided	MR
15	Fvi	 Overhead Tank of the Signage 	apacity		litres (w		rovided	MR
16.	Pro	vision of Lifts		Requ	ired		rovided	MR
	110	Programination					ovided	MR
		Pressurization of Shaft	Lift	NA	711	N.	Α	27.
								NA
		Pressurization of Communication in	iiit lobby	NA		N.	1	NA -
	>	Fireman's Ground	ing Car	NA		NA		NA NA
		Switch	mg	NA		NA		NA NA
	7	Lift Signage		NIA				INZ
7.	Stanc	by power supply		NA	1	NA		NA
3.	Refu	ge Area		Requir	ed	Pro	vided	MR
	7	Total area		NIA	,			
	Location		-	NA.		NA		NA
. F		ontrol room		NA		NA		NA
4								
	Detector system NA							
	panel		NA			NA		
3 1.		Flow Switch Panel NA						
	PA System Panel Battery backup NA NA NA			NA			NA	
			NA			NA		
			NA		NA			NA
			- 14 1		NA			NA

	Plans		2 0 1	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings noted at serial numbers

Signature of the Inspecting Officer Signature of the Inspecting Officer

Name Volay VIV Simph Designation ADO/WP Name

Designation