GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / EH / 2015/86

FIRE SAFETY CERTIFICATE

Certified that the Taco Bell (Restaurant) (A unit of Burman Hospitality Private Limited) located Space-8(T-316),3rd Floor, Ambience Mall, Vasant Kunj, New Delhi-110070, comprised of 03 basements, Ground + Three upper Floors. The restaurant is running at 3RD Floor. The premises inspected by the officer concerned of this department on 21.05.2015 in the presence of Mr Virender and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule33 of the Delhi Fire Service Rules-2010and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant) with effect from 29.15.115

-- for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, as mentioned below.

Issued on 28/5/2015 at New Delhi

(Dr. G.C. Misra) Chief Fire Officer

DATED: 28/5/15

Copy to:-

1. The DHO (South Zone), SD MC, South Zone, Aurobindo Marg, Green Park, New Delhi.

Taco Bell Restaurant,
 (A unit of Burman Hospitality Private Limited)
 Space-8, T – 316, 3RD Floor, Ambience Mall,
 Vasant Kunj, New Delhi.

The following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. The staff should be trained and available round the clock.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non functional of fire safety measures shall be at the risk and responsibility of the management.
- 4. Any deviation w.r.t construction etc shall be verified the concerned building sanctioning agency.
- 5. Basement shall be used as per BBL.
- 6. This certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in Form K provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Sertificate to the Director in Form-J{sub rule 37} along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1.Name & address of the building:- Taco Bell (Restaurant) (A unit of Burman Hospitality Private Limited, Space-8 (T-316), 3rd floor, Ambience Mall, Vasant Kunj, New Delhi-110070,
- 2. Type of occupancy:- Assembly, Group D, Restaurant
- 3. Type of case:-New
- 4. Details of previous NOC:-Nil
- 5. Fire safety directives No.- Nil
- 6. Date of inspection:-21/05/2015
- 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side:- Mr.Virender
- 9. Year of construction: 2010.
- 10.Applicant's letter no:- D-298/DHO/SZ Dated 28/04/2015

Building is comprised of 03 Basements, Ground + Three Upper Floors. The restaurant is running at third

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33 Access to Building	Requirement NBC	Provided at site	Remarks MR/NMR			
	1) Road width						
	2) Gate width	09 m	Provided	MR			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number W. M. W.	06 m	Provided	MR			
2.	A Number, Width Type & Arrangement of Exits						
	A. Number of staircases Provided and maintained by Mall 20 pos						
	1. Opper Hoors	20 nos.	17 nos.	MR			
	2. Basements	25		(DDA has approved 16 starcases. These staircases, meet the required travel distance)			
	B. Width of staircase	25 nos.	Provided	MR			
	1 Upper floor						
	2. Basements	1.5 m	1.38m - 1.5m	MR			
	C. Protection of exits	1.5 m	1.38m - 1.5m	MR			
	1 Fire shoot de a						
	2. Pressurization	Required	Provided by mall	MR			
	D. No. of continuous staircase to terrace	Required	Provided by mall	MR			
I	E. Width of corridor	10	Provided	MR			
	F. Door size	Required	Provided by mall	MR			
	Compartmentation	2mtrs.	Open from all side	MR			
) Fire check door						
3) Sealing of electrical shafts	Required	Provided by Mall	MR			
) Fire rating of shaft door	Required	Provided by Mall	MR			
) Water curtain	Required	Provided by mall	MR			
5) Fire Dampers	Required	Provided by mall	MR			
		Required	Provided by mall	MR			
1	Dogward Hangement System						
	Upper floors	30 a/c per hour	Provided by Mall	MR			
E E	Circ Extinguish	12 a/c per hour	Provided by Mall	MR			
	Provided and maintained by M. H.						
2)	Total numbers Types		05Nos.	MR			
		ICINA 1 1	ABC, Co2	MR			
	ISI marking	<u></u>	Yes	MR			



11/2

6.	First-Aid Hose Reel 1) Total number of each floor	Provided and maintained by Mall				
	2) Length of hose reel hose	Required	Provided	MR		
	3) Nozzle diameter	30 m	Provided	MR		
7.	Automatic Fire D. 4. 41	5 mm	Provided			
	Automatic Fire Detection & Alarming System Provided and MR					
	1) Type of detectors					
	2) Location of main panel	do	do	do		
	3) Location of repeater panel	do	do	do		
	4) Alternate source of power	do	do	do		
8.	5) Hooter's Location	do	do	do		
	MOEFA	Provided and	d maintained by Mall	do		
9.	Public Address System	Provided and	MR			
10.	Automatic Sprinkler System	2 10 vided and maintained by M		MR		
	1) Basement	Provided and	maintained by Mall			
	2) Upper floors	do	do	do		
	3) Sprinkler above false ceiling	do	do	do		
11.	Internal Hydrants	do	do	do		
	1) Size of riser/down-comer do do do do do do do do do d					
	2) Number of hydrants per floor	do	do	do		
	3) Hose box	do	do	do		
12.	Yard Hydrants	do	do	do		
	1) Total number of hydrants			uo		
	2) Hose box	do	do	do		
3.	Pumping Arrangement	do	do	do		
	1) Ground level	Provided and maintained by Mall				
	a) Disabaras s C		J I I I I I			
	a) Discharge of main pump	4500 lpm	Provided	MR		
	b) Head of main pump c) Number of main pump	70m	Provided	MR		
		02nos.	Provided			
	panip out put	180 lpm	Provided	MR		
	pamp nead	70 m	Provided	MR		
ŀ	- J Parip Output	4500 m	Provided	MR MR		
t		70 m	Provided	MR		
+	h) Auto starting/Manual stopping2) Terrace level	Required	Provided	MR		
-				IVIK		
	a) Discharge of pumpb) Head of pump	N/A	N/A	N/A		
	c) Power supply	N/A	N/A	N/A N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
	Captive Water Storage for The	N/A	N/A	N/A		
	1) Under grown by Provided and maintained by					
	a) Draw-off connection	JOOKL	Provided	MR		
	b) Fire service inlet	Required	Provided	MR		
	c) Access to tank	Required	Provided	MR		
	d) Over head tank capacity	Required	Provided	MR		
I	Exit Signage.	30kl	20k1	MR		
		Provided and ma	intained by Mall	1111		
ŀ	Provision of Lifts.	Provided and maintained by Mall				
	a) Pressurization of lift shaft	do				
	b) Pressurization of lift lobby	do	do	do		
	c) Communication in lift car	do	do	do		
	d) Fireman's switch	do	do	do		
	e) Lift signage	l uo	do	do		

17.	Stand by Power Supply	Provided and maintained by Mall			
18.	Refuge Area				
	Total area	N/A	N/A	N/A	
	location	N/A	N/A	N/A	
19.	Fire Control Room	Provided and	Provided and maintained by Mall		
	a) Detector system panel	do	do	do	
	b) Flow switch panel	do	do	do	
	c) PA system panel	do	do	do	
	d) Battery backup	do	do	do	
	e) Building floor plan	do	do	do	
20.	Special Fire Protection System for Protection of special Risk, if any:				

The fire protection system provided in the building were checked and found functional at the time of inspection.

And increase the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer

Name: - D.B. Mukherjee.

Designation: - Assistant Divisional Officer.

22/5/2015