

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/EH/2015/ MOZ/1274

Dated: 16/07/15

FIRE SAFETY CERTIFICATE

Certified that the Barbeque Nation Restaurant at G-2 & G-3 Ginger Hotel, Plot No.C, DDA Community Centre, Vivek Vihar, Delhi, owned/occupied by M/s A unit of Barbeque Nation Hospitality Ltd., was granted FSC vide letter no.F6/DFS/MS/EH/2012/3530 dated 25.09.12. The restaurant was inspected by the officers concerned of this department on 09.07.15 in the presence of Sh.Harpreet Singh (Manager) and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group D Assembly Building "Restaurant" with effect from 16.10.15 for a period of three years in accordance with Rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010, subject to conditions printed overleaf.

Issued on 16.10.15 at New Delhi by


1577
(Dr. G. C. Misra)
Chief Fire Officer
Ph. 011-23414333

OK
h

To,
Barbeque Nation Restaurant
M/s A unit of Barbeque Nation Hospitality Ltd.
G-2 & G-3 Ginger Hotel, Plot No.C,
DDA Community Centre, Vivek Vihar, Delhi

Copy to:-
The Dy. Health Officer,
East Delhi Municipal Corporation, Health Department,
Shahdara (South) Zone, Karkardooma, Shahdara, Delhi

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

4/5

1. Name & address of the building : Barbeque Nation at G-2 & G -3 Ginger Hotel, Plot No.C,DDA Community Centre,Vivek Vihar,Delhi.
2. Type of Occupancy : Assembly at ground floor.(Restaurant)
3. Type of Case : Renewal
4. Details of Previous FSC : F.6/DFS/MS/EH/2012/3530 dated 25.08.12.
5. Fire Safety directives No : NBC
6. Date of Inspection : 09.07.15
7. Name of the Inspecting Officer : ADO Suresh Singh & DO Virendra Singh
8. Name of the designation of Officer
From the building side : Sh. Harpreet Singh (Manager)
9. Year of Construction : 2009
- 10.Applicant's letter No : Nil *dd 07/7/15*

	Minimum Standards on fire prevention and fire safety U/R33	NBC Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	12 Mtrs 4.5 Mtrs. N/A	30 Mtrs. 6 Mtrs. N/A	MR MR N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Upper Floor • Basement 	N/A N/A	N/A N/A	N/A N/A
	B. Width of Staircases	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Upper Floor • Basement 	N/A N/A	N/A N/A	N/A N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required N/A	Provided N/A	MR N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	2.0 Mtrs.	3 nos. 2.0 Mtrs. each	MR
3	Compartmentation.	Required	Provided for entire building	
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire rating of shaft door • Water curtain • Fire Dampers 	N/A N/A N/A N/A N/A	Provided Sealed N/A N/A N/A	MR MR N/A N/A N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basement • Upper floor 	N/A N/A	N/A N/A	N/A N/A
5.	Fire Extinguisher			
	<ul style="list-style-type: none"> • Total numbers • Types 	4 Nos. ABC & Co2	06 Nos. ABC & Co2	MR MR
	<ul style="list-style-type: none"> • IS marking 	ISI marked	ISI marked	MR
6	First-aid-Hose Reels.			
	<ul style="list-style-type: none"> • Total numbers of each floor • Length of hose reel hose • Nozzle diameter 	1 no. 30 m 5 mm	Provided Provided Provided	MR MR MR

7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors 	Heat & smoke	Provided	MR
	<ul style="list-style-type: none"> Location of main panel 	N/A	At ground floor	MR
	<ul style="list-style-type: none"> Location of repeater panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Alternate source of power 	Battery & DG Set	Provided	MR
	<ul style="list-style-type: none"> Hooters's location 	Different Location	Different Location	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	Required	Provided	MR
10	Automatic Sprinkler System.	N/A	Provided	MR
	<ul style="list-style-type: none"> Basement 	N/A	N/A	N/A
	<ul style="list-style-type: none"> upper floor 	N/A	N/A	N/A
	<ul style="list-style-type: none"> sprinkler above false ceiling 	N/A	N/A	N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> size of riser/down-comer 	150 mm	150 mm	MR
	<ul style="list-style-type: none"> Number of hydrants per floor 	1no.	1 no.	MR
	<ul style="list-style-type: none"> Hose Box 	1 no.	1 no.	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants 	Not Required	1no.	MR
	<ul style="list-style-type: none"> Hose Box 	Not Required	1 no.	MR
13	Pumping Arrangements.	For main	Building	
	<ul style="list-style-type: none"> Ground Level 	N/A	Provided	MR
	<ul style="list-style-type: none"> ➤ Discharge of main Pump 	N/A	2280 LPM	MR
	<ul style="list-style-type: none"> ➤ Head of Main Pump 	N/A	88 mtrs	MR
	<ul style="list-style-type: none"> ➤ Number of main pumps 	N/A	2 nos.	MR
	<ul style="list-style-type: none"> ➤ Jockey pump out put 	N/A	450 LPM	MR
	<ul style="list-style-type: none"> ➤ Jockey pump head 	N/A	88 mtrs.	MR
	<ul style="list-style-type: none"> ➤ Standby pump out put 	N/A	2280 LPM	MR
	<ul style="list-style-type: none"> ➤ Standby pump Head 	N/A	88 Mtrs.	MR
	<ul style="list-style-type: none"> ➤ Auto Starting /Manual stopping 	N/A	Provided	MR
	<ul style="list-style-type: none"> ➤ Pump House Access 	N/A	Provided	MR
	<ul style="list-style-type: none"> Terrace Level 			
	<ul style="list-style-type: none"> ➤ Discharge of pump 	450 LPM	Provided	MR
	<ul style="list-style-type: none"> ➤ Head of the Pump 	88 mtrs.	Provided	MR
	<ul style="list-style-type: none"> ➤ Power supply 	Required	Provided	MR
	<ul style="list-style-type: none"> ➤ Auto Starting of pump 	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.	For main	Building	
	<ul style="list-style-type: none"> Underground tank capacity 	N/A	2,00,000 Ltrs.	MR
	<ul style="list-style-type: none"> ➤ Draw-off connection 	N/A	Provided	MR
	<ul style="list-style-type: none"> ➤ Fire service inlet 	N/A	Provided	MR
	<ul style="list-style-type: none"> ➤ Access to tank 	N/A	Provided	MR
	<ul style="list-style-type: none"> Overhead Tank capacity 	20000 Ltrs.	20000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization of Lift lobby 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Communication in lift car 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Firemen's grounding switch 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Lift Signage 	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR

2017

18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room		For main Building	
	• Detector system panel	Required	Provided	MR
	• Flow switch panel	N/A	Provided	MR
	• PA system panel	N/A	Provided	MR
	• Batter backup	N/A	Provided	MR
	• Building Floor Plans	N/A	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules the FSC issued vide letter no. F.6/DFS/MS/EH/2012/3530 dated 25.08.12.renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

Submitted please.

S Singh
10.7.15

Signature of the Inspecting Officer
Name :-Suresh Singh
Designation :-ADO(Shah.)

V Singh
10/7/15

Signature of the Inspecting Officer
Name:Virendra Singh
Designation :-DO(ED)