GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/EH/2015/ NO2/1308

Dated :---21/07/15

FIRE SAFETY CERTIFICATE

Certified that the M/s Garam Dharam Dhaba (A Unit of Veeru Foods Pvt. Ltd.) located at M-16, Ground & Mezzanine Floor, Outer Circle, Connaught Place, New Delhi-110001... building is comprised of Ground, Mezzanine + 2 upper floors have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 19/07/15 in the presence of Mr. Pandey that the premises is fit for occupancy of class Assembly Building Group-D at ground & mezzanine floor with effect from -21/-5 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Ph:- 011-23414333

0/6

- Copy to:- (1) Medical Officer of Health.

 New Delhi Municipal Council,

 Palika Kendra, New Delhi.
 - (2) M/s Garam Dharam Dhaba (A Unit of Veeru Foods Pvt. Ltd.), M-16, Ground & Mezzanine Floor, Outer Circle, Connaught Place, New Delhi-110001.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigoyt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

M/s Garam Dharam Dhaba (A Unit of 1. Name & address of the building:-

Veeru Foods Pvt. Ltd.), M-16, Ground & Mezzanine Floor, Outer Circle, Connaught

Place, New Delhi-110001.

Group – D Assembly Building (comprised of 2. Type of occupancy:-

New

ground, mezzanine + 2 upper floor restaurant at ground & mezzanine)

3. Type of case:-

4. Details of previous FSC:-N/A 5. Fire safety directives No.-N/A

6. Date of inspection:-19.07.2015

7. Name of the inspecting officer:-D.O. Gurmukh Singh & A.D.O. Manoj

Kumar Sharma

8. Name & designation of officer From the building side:-

Mr. Pandey Heritage Bldg. (old) 9. Year of construction:-

10. Applicant's letter No:-MOH/D/602/Lic./SI-I dated 13/07/15

S.No.	Minimum Standards on fire	Requirement	Provided at site	Remarks	
	Prevention and fire safety U/R 33			MR/NMR	
1.	Access to Building				
	1) Road width	9 mtr.	13 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrangement of Exits				
	A. Number of staircases				
	1. Upper floors	02 Nos.	02 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors (Mez.)	02 Nos	1.50 mtr. (Iron) 90 cm to 115cm	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits	:**			
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	2 mtr.	2 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 a/c per	N/A	N/A	

		hour				
	2) Upper floors	12 a/c per	Exhaust fan			
		hour	provided			
5.	Fire Extinguishers					
	1) Total numbers	06 Nos.	06 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	ISI	Yes	MR		
6.	First-Aid Hose Reel					
25 "	1) Total number of eachfloor	01 No.	01 No.	MR		
-	2) Length of hose reel hose	30 m	30 m	MR		
_	3) Nozzle diameter	5 mm	5 mm	MR		
7.	S J Stelli					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
*	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	Provided	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling					
11.	Internal Hydrants					
	1) Size of riser/down-comer	100 mm.	100 mm.	MR		
	2) Number of hydrants per	01 no.	01 no.	MR		
	floor					
	3) Hose box	01 no.	01 no.	MR		
12.	Yard Hydrants	,				
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump					
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump		N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping					
	stopping 2) Terrace level					
	2) Terrace levela) Discharge of pump	450 LPM	450 LPM	MR		
	2) Terrace level	450 LPM 30 mtr.	450 LPM 30 mtr.	MR MR		

14	d) Auto starting of p Captive Water Stave	ump Require	ed Provided	MD
	Captive Water Storage: 1) Under ground tank	for Fire Fighti	ng	MR
	capacity	N/A	N/A	N/A
	a) Draw-off connectib) Fire service inlet		N/A	NI/A
	c) Access to tank	Required	Provided	N/A
	d) Over head tank	N/A	N/A	MR
	capacity	10,000 Lt	rs. 10,000 Ltrs	N/A
15.	Exit Signage.		- sooo Eus	MR
16.	Provision of Lifts.	Required	Provided	MR
	a) Pressurization of lif			1411/
	shaft		N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in	N/A		IV/A
	lift car		N/A	N/A
	d) Fireman's switch e) Lift signage	N/A	N/A	DIA
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	Required	Provided	N/A
		N/A	N/A	MR
	Total area location	N/A		N/A
9.	Fire Control Room		N/A	N/A
		N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	
	b) Flow switch panel	227		N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A N/A
		N/A	N/A	N/A N/A
	e) Building floor plan	N/A		IN/A
	Special Fire Protection S.	· C D	N/A	N/A
	Risk, if any:	N/A		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate, under rule 35 of the Delhi Fire Service Rules 2010, is recommended please.

Gurmukh Singho Divisional Officer

Manoj Kumar Sharma Assistant Divisional Officer