GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F6/OFS/as/ School/2015/1102/1346 Dated: 24/07/15

FIRE SAFETY CERTIFICATE

Certified that the EDMC Primary School at North Ghonda (Urdu), B-5, Yamuna Vihar, Delhi-110053, comprised of ground floor only, owned/occupied by EDMC Primary School was issued FSC vide letter No-F6/DFS/MS/School/2012/1833 dated-21/05/2012. The school building was re-inspected by the officer concerned of this department on 13/07/2015 in the presence of Mrs. Aneesha Begum, Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter No-F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11 issued by Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' for ground floor with effect from 2-4/-07-//3. for a period of three years, subject to conditions, printed overleaf.

Issued on 24/07/15 at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer Ph.011-23414333 OIC

To,

The Principal, EDMC Primary School, (Ist Shift), North Ghonda (Urdu), B-5, Yamuna Vihar, Delhi-110053

Copy:-

- The Director of Education, EDMC, Udyog Sadan, Plot No. 419, FIE, Patpargani Industrial Area, Delhi-110092
- The Principal, 2. EDMC Primary School, (IInd Shift) North Ghonda (Urdu), B-5, Yamuna Vihar, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

Name & address of the building

: EDMC Primary School,

North Ghonda (Urdu), B-5, Yamuna Vihar, Delhi-110053

2. Building is comprised of : Ground floor only

3. Type of Occupancy : Educational

4. Type of Case : Renewal

Details of Previous FSC letter

: F6/DFS/MS/School/2012/1833 dated-21/05/2012

Fire Safety direction letter No 6.

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 13/07/2015

Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of officer

: Mrs. Aneesha Begum (Principal)

from the building side

: 1992

10. Year of Construction 11. Applicant's letter No

: Letter No.-Nil, Dated- 13/07/2015

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Circular Requirement	Provided at Site	Remarks			
01	Access to Building						
	Road width	06 mtr.	06 mtr.	MR			
	 Gate width 	4.50 mtr.	05 mtr.	MR			
	 Width of internal road 	N/A	N/A	N/A			
02	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	 Upper floor 	N/A	N/A	N/A			
	 Basement 	N/A	N/A	N/A			
	b. Width of Staircases						
	 Upper floor 	N/A	N/A	N/A			
	 Basement 	N/A	N/A	N/A			
	c. Protection of exits						
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	· N/A			
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A			
	e. Width of corridor	N/A	- N/A	N/A			
	f. Door Size	01 mtr.	01 mtr.	MR			
03	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	 Water curtain 	N/A	N/A	N/A			
	 Fire dampers 	N/A	N/A	N/A			
)4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	02 nos.	02 nos.	MR			
	• types	ABC /CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			

06	First-Aid-Hose Reels.	a reas considerante distanciado los servirantes de madeira con considerada (in construir dos considerados con				
	Total numbers on each floor	N/A	N/A	N/A		
	Length of hose reel hose	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
07	Automatic fire detection and alarming syste	em.				
	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	Location of repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	 Hooter's location 	N/A	N/A	N/A		
08	MOEFA	N/A	N/A	N/A		
09	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose box	N/A	N/A	N/A		
12	Yard Hydrants.		J	apparent and the second		
	Total number of hydrants	N/A	N/A	N/A		
	Hose box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	➢ Ground Level					
	Discharge of main pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
М. 1	Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	N/A	N/A	N/A		
	Standby pump head	N/A	N/A	N/A		
	 Auto starting /manual stopping 	N/A	N/A	N/A		
	Pump house access	N/A	N/A	N/A		
	> Terrace Level					
	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	N/A		
	Power supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	NA		
	Fire service inlet	N/A	N/A	N/A ·		
	Access to tank	N/A	N/A	N/A		
	Overhead tank capacity	N/A	N/A	N/A		
15	Exit Signage.	N/A	N/A	N/A		

16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	 Pressurization of lift lobby 	N/A	N/A	N/A			
	 Communication in lift car 	N/A	N/A	N/A			
	 Firemen's grounding switch 	N/A	N/A	N/A			
	Lift signage	N/A	N/A	N/A			
17	Standby Power Supply	N/A	N/A	N/A			
18	Refuge Area.						
***************************************	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	 Flow switch panel 	N/A	N/A	N/A			
	 PA system panel 	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked at the time of inspection. The school building was issued FSC vide letter No-:F6/DFS/MS/School/2012/1833 dated-21/05/2012.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the circular no- F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name- Vijay Bahadur Designation- A.D.O

DO(ED)