## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No: F.6/DFS/MS/School/2015/52/1439

Dated: 07/08/15

## FIRE SAFETY CERTIFICATE

Certified that the building of S.L. Suri D.A.V. Public Sr. Sec. School located at Chander Nagar, 'A' Block, Janak Puri, New Delhi-110058 is comprised of ground floor plus two upper floors owned/occupied by the DAV College Managing Committee was re-inspected by the officer concerned of this department on 30.07.2015 in the presence of Ms. Annu Arora (Principal) and found that the DAV College Managing Committee have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph. 011-23414333

## Copy to: -

- The Principal,
   S.L. Suri D.A.V. Public Sr. Sec. School,
   Chander Nagar, 'A' Block, Janak Puri, N.D-58
   (Ref. No. SL SURI DAV JP/2015/8485 dated 17.07.2015)
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. The certificate may not be treated in any case for regularization of

unauthorized construction, if any.

6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this

Certificate, six months prior to its expiry.

	1 Name 8 11 INSPEC	CTION REPORT			•			
	1. Name & address of the building	S. L. Suri D. A.	V. Public Sr. Sec.	School Char	do h			
		S. L. Suri D. A. V. Public Sr. Sec. School, Chander New Pasa/Renowed						
	3. Type of Case	: New Case/Rene	wal	I WILL JOHN	RATU			
	Second OLLLENIONS MADE	: Letter No.		Date				
	3. Fire Safety directives letter No				-			
	- soce of mapertion	30.07.2015						
	rathe of hispecting Officer . A. A. O. C. A. Li							
	8. Name and designation of officer							
	From the building side	: _ Smt. Ann	4 Arora (Prin	(ihi)				
	9. Year of Construction	1990		. s				
 S.	10. Applicant's letter No.	: SL Suzi DAY.	JP/2015/8485	Late 17.07	2011			
	The standards of title	NBC/BBL	Provided at	Remarks	2010			
No.	prevention and fire safety U/R 33	Requirement		MR/NMR	-			
1.	Access to building			IAILA IAIAIK				
	<ul> <li>Road width</li> </ul>	Accessible	09mts	MR				
	<ul> <li>Gate width</li> </ul>							
	• Width of internal road		395cms	MR				
2.	Number, Width, Type & Arrangement	t of E. U.						
	a. Number of staircases	TOLEXIES						
	• Upper Floors		and the same of th					
	Basements	Two	Two	MR				
	b. Width of staircases	•	*	No Boseme	nt			
				l social	116			
	• Upper Floor	~~	117cms, 132cms.	MR				
	Basements		_	No Basem	:1,			
	c. Protection of exits	The state of the s		Lusem	ent			
	Fire check door			Andrew Commenced in a decomposition address is a second discuss, and the				
	• pressurization							
	d. No. of continuous staircases to			AND A STATE OF THE				
	terrace		<u> </u>	Committee being the change on the control of the co				
	e. Width of Corridor		One					
	f. Door Size	***************************************	doocms, 180cms					
~			106 cms x 200 cms					
3.	Compartmentation		119 Cms x 210 Cms					
	Fire check door							
	<ul> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> </ul>		-	English and the state of the st				
			Sealed					
		_	Annual francisco de la constantina del constantina de la constantina del constantina de la constantina		7			
			Comments of the Comments of th					
	<ul> <li>Fire Dampers</li> </ul>	STATE AND ADDRESS OF THE PARTY						
1.	Smoke Management System							
	Basements	20 -/						
	Upper floors	30 a/c per	<del>-</del>	No Baseme	nt			
		hour	Vateral Ventilable					

1 0	NIY	The state of the s		* ,
		12 a/c per hour		
5.	Fire Extinguishers			
	<ul> <li>Total numbers</li> </ul>	10 Nos		,
	<ul><li>Types</li></ul>	ABC, Co.	Provided	MR
	<ul><li>IS marking</li></ul>	ISI marked	-do,-	MR
6.	First-Aid Hose Reels	131 Marked	1SI marked	MR
	<ul> <li>Total numbers on each floor</li> </ul>	760	0	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	- do -	MR
7.	Automatic fire detection and alarming	system	- do!-	I MR
	<ul> <li>Type of detectors</li> </ul>	- I		7
į	<ul> <li>Location of Main Panel</li> </ul>			
	<ul> <li>Location of Repeater Panel</li> </ul>			+
	<ul> <li>Alternate source of power</li> </ul>		-	
	<ul> <li>Hooters' Location</li> </ul>			4
8.	MOEFA			
9,	Public Address System	0	0	
10.	Automatic Sprinkler System	Required	Provided	MR
	<ul> <li>Basement</li> </ul>			
	<ul> <li>Upper Floor</li> </ul>			No Basement
	<ul> <li>Sprinkler above false ceiling</li> </ul>			
1.	Internal Hydrants			+
	<ul> <li>Size of riser/down-comer</li> </ul>			
	<ul> <li>Number of hydrants per floor</li> </ul>			+
	* Hose Box		•	
2.	Yard Hydrants			L
	<ul> <li>Total number of hydrants</li> </ul>		1.	!
	* Hose Box			
3.	Pumping Arrangements			
	<ul> <li>Ground Level</li> </ul>			
	Discharge of main Pump			
	Head of Main pump			
	Number of main pumps	-		
	Jockey Pump out put		Section 1	
	Jockey pump head		Comments of the Comments of th	-
	Standby Pump out put			Same.
	Standby Pump Head	- 10 10 10 10 10 10 10 10 10 10 10 10 10	+	· Contraction of the Contraction
	Auto Starting/Manual			-
The state of the s	stopping			Element .
		-	Control	<u> </u>
				M

## Ms - Chander Nagar, A' Block, Janak Pun', New Delli-110058.

	Pump House Access	-		635m-				
	Terrace level							
	Discharge of pump	450 LPM	450 LPM	MR				
	Head of the pump	I .	30 M	MR				
	Power Supply	Required	Provided	MR				
	Auto Starting of pump	/		-				
14.	Captive Water Storage for fire fighting							
	<ul> <li>Underground tank capacity</li> </ul>	-	_	~				
	Draw-off connection	Marie Para and a second para a		-				
	Fire service inlet	-						
	Access to tank							
	<ul> <li>Overhead Tank capacity</li> </ul>	10000 (1	1000011	0				
The same and the s		Required	10000 ltr	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.			9				
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	_	_					
	<ul> <li>Pressurization of Lift lobby</li> </ul>	•	-	-				
	<ul> <li>Communication In lift Car</li> </ul>		Parell	Na O				
	<ul><li>Fireman's Grounding Switch</li></ul>	0	Poovided	MR				
	Lift Signage	Required	- de -	MR				
		- do -	-do-	MR				
17.	Standby power supply	Required Required	D.C. Set of 62.5 KVA	MR				
18.	Refuge Area.							
	> Total Area							
	> Location							
		-	_	-				
19.	Fire Control Room							
	Detector System Panel	-	_	<u> </u>				
	Flow Switch Panel	- Comment						
	PA System Panel			2				
	1 A System I dilei		-	Comme				
	Batter backup			· ·				
		-	-					
	Batter backup	-	-					
20.	Batter backup		- 1					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers

Note: - The school building is comprised of Ground Floor plus two upper Floors. The upper Floors are served by two staircases having width 117 cms \$132 cms respectively.

The school management has rectified all the short comings which is raised vide letter No. F.6 | DFS | MS | School | 2015 | 85 dated 09.01.2015. FSC is recommended please.

Signature of Inspecting Officer

Name P.S. Dahiya
Designation ABBH. Divisional Officer

Name

Designation

Signature of Inspecting Offices