GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/MS/DFS/EH/SZ/2015/ 5/3

Dated: 19/68/15

FIRE SAFETY CERTIFICATE

Issued 19-1-8-11-at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer Tel: 011-23414333

of C type (BUP)

Copy to:

 Dy. Health Officer(South Zone) Green Park, Aurbindo Marg, New Delhi.

2. Authorized Signatory

Carls Jr (Unit of Cybiz Brightstar Restaurants Pvt. Ltd.), Shop No.-1& 2, Plot no.-D-2, Southern Park, District Centre Saket, Saket, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:-CarlsJr (A Unit of CybizBrightstar Restaurants Pvt. Ltd.)
 Shop No.1& 2 at Ground Floor & kitchen at 1st floor, Plot no.D2,District Centre, Southern, Park, Saket, New Delhi.
- 2. Composition of the Building: 2 tier basement, ground and 05 upper floors
- 3. Type of occupancy:- Assembly, Group D, Restaurant
- 4. Type of case:-New
- 5. Details of previous NOC:- Nil
- 6. Fire safety directives No.- Nil
- 7. Date of inspection:-4/8/2015
- 8. Name of the inspecting officer:-D.B.Mukherjee, A.D.O.(BCP)
- 9. Name & designation of officerFrom the building side:- Mr. Deepak
- 10. Year of construction: 2006

Applicant's letter no:-DHO/SZ/2012/D-560, dated:02/06/2015& applicant letter no nil dated nil. Restaurant is running at ground floor and kitchen at first floor.

Sl.No	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks		
1.	Access to Building Requirement MR/NMR					
	1) Road width	9mtr	Provided	MR		
	2) Gate width	Required	At GF Approachable	MR		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement o	f Exits	11//11	IN/A		
	A. Number of staircases					
	1. Upper floors	02 Provided	Provided	MR		
	2. Basements	N/A	N/A	The second second		
	B. Width of staircase	14/11	IV/A	N/A		
	1. Upper floors	1.25m	1.45m &0.90m There are 04 nos. of staircases having width 1.45,1.40,1.35, & 1.23 m from ground to upper floors is provided by mall	MR		
	2. Basements	N/A	N/A	N/A		
-	C. Protection of exits		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	IN/A		
-	1. Fire check door	Required	Provided by Mall	MR		
	2. Pressurization	Required	Provided by Mall	MR		
	D. No. of continuous staircase to terrace	Required	Provided by Mall	MR		
-	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1.5m	2.20m, 1.37m& 1m	MR		
	Compartmentation 2.20m, 1.37m& 1m WR					
	1) Fire check door	Required	Provided by Mall	MR		
	2) Sealing of electrical shafts	Required	Provided by Mall	MR		
	3) Fire rating of shaft door	Required		MR		
4	4) Water curtain	N/A		N/A		
	5) Fire Dampers	Required		MR		
	Smoke Management System					
) Basements	30 a/c per hour	N/A	N/A		
2	2) Upper floors	12 a/c per hour	Mechanical Ventilation.	MR		
I	Fire Extinguishers	we per from	, chiliation.	IVIK		

-	1) Total numbers		10 nos.	MR MR		
	2) Types	ISI Marked	ABC, Co2			
	3) ISI marking	8	Yes	MR		
	First-Aid Hose Reel	Provided and maintained by mall				
5.	1) Total number of each floor	03	Provided	MR		
	2) Length of hose reel hose	30 m	Provided	MR		
	2) Neggle diameter	5 mm	Provided	MR		
	3) Nozzle diameter 5 mm Provided Automatic Fire Detection & Alarming System Provided and maintained by					
•		Required	Provided Smoke	MR		
	1) Type of detectors	Required	1 st basement	MR		
	2) Location of main panel	Required	Basement	MR		
	3) Location of repeater panel	Required	DG Set	MR		
	4) Alternate source of power	Every Floor	Provided	MR		
	5) Hooter's Location	Required	Provided	MR		
	MOEFA	Required and				
	Public Address System	Provided and maintained by mall Provided and maintained by mall				
0.	Automatic Sprinkler System		N/A	N/A		
	1) Basement	N/A	Provided	MR		
	2) Upper floors	Required	N/A	N/A		
	3) Sprinkler above false ceiling	N/A		11/12		
11.	Internal Hydrants Provided and maintained by man					
	1) Size of riser/down-comer	100 mm.	Provided	MR		
	2) Number of hydrants per floor	03	Provided			
	3) Hose box	03	Provided	MR		
12.	Yard Hydrants	Provided and	d maintained by mall	MD		
14.	1) Total number of hydrants	07	Provided	MR		
	2) Hose box	07	Provided	MR		
13.	Pumping Arrangement Provided and maintained by mall					
13.	1) Ground level			1.65		
	a) Discharge of main pump	2850 lpm	Provided 02 nos.			
	b) Head of main pump	70m	70m	MR		
	c) Number of main pump	02	Provided 02 nos	MR		
	d) Jockey pump out put	180 lpm	Provided 02 nos			
	e) Jockey pump head	70m	70m	MR		
		2850 lpm	Provided Diesel	MR		
	f) Stand by pump output		Engine			
	g) Stand by pump head	70m	70m	MR		
		Required	Provided	MR		
		1				
		900 lpm	Provided	MR		
	a) Discharge of pump	39 m	Provided	MR		
	b) Head of pump	Required	Provided	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump		and maintained by mall			
14.	Captive Water Storage for Fire Fightin	300KL	2.75 KLProvide	ed. MR		
	1) Underground tank capacity	Required	Provided	MR		
	a) Draw-off connection	Required	Provided	MR		
	b) Fire service inlet	Required	Provided	MR		
	c) Access to tank	30000 ltrs.	50000 ltrs.	MR		
	d) Over head tank capacity		Provided	MR		
15.	Exit Signage.	Required	Tiovided			
16.	Provision of Lifts.	27/4	N/A	N/A		
	a) Pressurization of lift shaft	N/A		N/A		
	b) Pressurization of lift lobby	N/A	N/A	IV/II		

	110	N/A	N/A	N/A
*	c) Communication in lift car		N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	Provided D.G. Sets	MR
17.	Standby Power Supply	Required	Provided D.G. Sets	TVIIC
18.	Refuge Area	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	location	Provided and maintained by Mall		
19.	Fire Control Room	Required	Provided	MR
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	Required	Provided	MR
	c) PA system panel	Required	Provided	MR
	d) Battery backup	Required	Provided	MR
9	e) Building floor plan	retaction of special Risl		N/A
20.	Special Fire Protection System for Pr	rotection of special resi	d and found functional a	t the time o

The fire protection system provided in the restaurant were checked and found functional at the time of inspection.

The mall has been issued FSC vide letter no. F6/MS/DFS/SZ /Mercantile/2015/ 1415, dated: 04/08/2015.

In view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rulesissuance of Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010 is recommended. Accordingly DFA is put up please.

Signature of the inspecting officer

Name: D.B. Mukherjee.

Designation: - Assistant Divisional Officer(BCP)