GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/MS/DFS/GH/2015/ S2 1590

Dated: 03. 09. 2015

FIRE SAFETY CERTIFICATE

Certified that the Hotel Daya Continental, located at A-6, Road No-1, N.H.-8, Mahipalpur Extn., New Delhi110037 comprised of Basement, Ground and 03 Upper floors (Basement: others property, ground floor:
office & reception, first to third floor 8 rooms at each floor, total -24 guest rooms) owned/occupied by Daya
Continental was inspected by the officer concerned of this department on 27/08/2015 in the presence of Mr.
Vinay Kumar Choudhary and observed that the said premises have complied with the fire prevention and
fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the
premises is fit for occupancy class **Group A- Residential (Lodging or Rooming House)** with effect
from (23:21:22). a period of three years in accordance with rule 36 unless renewed under rule 37 or
sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire
Service Rules 2010.

Issued <u>03. 09. 2015</u> at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer Tel: 011-23414333

ore process

Copy to:-

- DHO(NG Zone)
 South Delhi Municipal Corporation
 Public Heath Department, Najafgarh Zone
 New Delhi
- 2) Hotel Daya Continental, A-6, Road No-1,N.H.-8,Mahipalpur Extn,New Delhi-110037

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Hotel Daya Continental, A-6, RoadNo-1,N.H-8,Mahipalpur Extn., New Delhi-110037
- 2. Type of occupancy:- Group-A, Residential, Rooming or Lodging House (Guest House)
- 3. Type of case: -New
- 4. Details of previous NOC: -Nil
- 5. Fire safety directives No.- Nil
- 6. Date of inspection: 27/08/2015
- 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side: Mr. Vinay Kumar Choudhary
- 9. Year of construction:-
- 10.Applicant's letter No:- DHO/NZ/2015/4089 dated 16/07/2015
- 11. Composition of the building :Basement, Ground & 03 Upper Floors . Guest house is running at ground & 03 upper floors.

SI. No	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	6mtr	Provided	MR			
	2) Gate width	Required	Directly accessible from road	MR			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits						
	A. Number of staircases						
	1. Upper floors	01	Provided	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	1.25m	1.30m	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	Required	01 nos.	MR			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	1 mtr	Provided	MR			
i.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System						
	1) Basements	30 a/c per hour	N/A	N/A			
	2) Upper floors	12 a/c per hour	Natural Ventilation	MR			
	Fire Extinguishers						
	1) Total numbers		10 nos.	MR			
	2) Types	ISI Marked	ABC, Co2	MR			
	3) ISI marking		Yes .	MR			
6.	First-Aid Hose Reel						
	1) Total number of each floor	1Nos.	Provided	MR			
	2) Length of hose reel hose	30mtr	Provided	MR			
	3) Nozzle diameter	5mm	Provided	MR			



7.	Automatic Fire Detection & Alarming S	ystem		
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		11/12	14/11
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants		1 1/1 1	14/21
-	1) Size of riser/down-comer	100mm	Provided	MR
	2) Number of hydrants per floor	1NOs.	Provided	MR
	3) Hose box	1Nos.	Provided	MR
12.	Yard Hydrants	11,00	Tiovided	IVIIX
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement	1 37.4 4	IV/A	IN/A
	1) Ground level	N/A	N/A	NI/A
	a) Discharge of main pump	N/A	N/A N/A	N/A
	b) Head of main pump	N/A N/A	N/A N/A	N/A
	c) Number of main pump	N/A	N/A N/A	N/A
	d) Jockey pump out put	N/A N/A	N/A N/A	N/A
	e) Jockey pump head	N/A N/A		N/A
	f) Stand by pump output	N/A N/A	N/A N/A	N/A
	g) Stand by pump head	N/A N/A		N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2)Terrace level	IN/A	N/A	N/A
	a) Discharge of pump	1501 nm	4501	100
	b) Head of pump	450Lpm 35mtr	450Lpm	MR
	c) Power supply		35mtr each	MR
	d) Auto starting of pump	Required	Provided	MR
14.0	Captive Water Storage for Fire Fighting	Required	Provided	MR
14.0		NI/A	27/1	[27]
	Under ground tank capacity Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
15.		N/A	N/A	N/A
	d) Over head tank capacity Exit Signage.	5,000ltr	5,000ltr	MR
	0 0	Required	Provided	MR
16.	Provision of Lifts. a) Pressurization of lift shaft	NI/A	27/1	7711
		N/A	N/A	N/A
	,	N/A	N/A	N/A
		N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area			
	Total area location	N/A	N/A	N/A

19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the building were tested and found functional at the time of inspection. In view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under rule 35 of the Delhi Fire Service Rules 2010, issuance of fire safety certificate is recommended. Accordingly DFA is prepared and put up for perusal, approval and signature pl.

318/15

Signature of the inspecting officer

Name: - D.B.Mukherjee.

Designation:- Assistant Divisional Officer (BCP)